

Compound, 1 Pascual, Parañaque, 1700 Metro Manila Contact no. 09978900746 | Email address: stanghero21@gmail.com

SCOPE OF WORK

CUSTOMER DETAILS

Jane Smith
Ford Mustang EcoBoost
XYZ456
09876543211
jane@example.com

EMPLOYEE DETAILS

Ysay Balandra Branch Manager 92121930903 rbbalandra14@gmail.com

SERVICE DETAILS

Replaced engine oil and oil filter Check and clean

- Brake system
- Front brake pads
- Rear brake pads 70%

Cleaning and greasing were done front and rear

Clean maf sensor and Throttle body

All Filters

Air and cabin filter were cleaned

- Check fluid condition (all fluids are in good and right level)
- Transmission cooler line correction

Retighten suspension/under chassis

- Stabilizer link was replaced
- Tie rod and rack end need replacement

Tires and Battery

Tires: falken azenic fk510 Thread: 80% front and rear

Production date:

Battery: Varta DIN60 - good condition

REMARKS

Steering rack and pinion (need 2nd opinion) Transmission jerk 1st Gear