SYNTHETIC TRAINING LOG - ENGINEERING WATCH
0800 Watch assumed
0830 Pump B abnormal vibration observed
0845 Supervisor notified
0915 Pump B vibration cleared and returned to service