Specialty McCafé 1-Step Espresso Equipment Resources



FRANKE SB1200



FRANKE FM850

NO QR CODE



BUNN Sure-Tamp



Melitta CT8

SB1200

Franke Coffee Systems Americas

- 1-866-374-2544
- cs.servicecenter.us@franke.com
- Marcello Togneri – marcello.togneri@franke.com
- Franke SB1200 (QR Code Link)

SB1200 Details:

- 2 hoppers & dedicated grinders
- CleanMaster with clean-in-place cartridge
- IQFlow Technology – consistent in-cup quality
- Franke SB1200 unit is obsolete as of 2026.
- Parts will be supported through 2029.

FM850

Franke Coffee Systems Americas

- 1-866-374-2544
- cs.servicecenter.us@franke.com
- Marcello Togneri – marcello.togneri@franke.com
- No QR Code

FM850 Details:

- 2 hoppers & dedicated grinders
- 10.4" touch screen user interface
- FoamMaster Technology – barista-quality hot & cold milk foam
- Franke FM850 unit is obsolete as of 2019.
- Parts will be supported through 2029.

Sure Tamp

Bunn

- For service on BUNN Espresso Equipment (only), all work orders are initiated through BUNN: 1-800-209-2866
- https://www.bunn.com/
- BUNN Sure-Tamp (QR code link)

Sure-Tamp Details:

- Bunn Sure Tamp unit is obsolete as of 2/1/2023.
- Parts will be supported through 2/1/2028.

CT8

Melitta Professional Coffee Solutions

- 1-847-717-8900
- McDonald's USA Support – mcdusasupport.mpcs@melitta.com
- Service Hot Line: 866-910-9105
- Melitta CT8 (QR code link)

CT8 Details:

- Clean-in-place system, no parts to remove.
- ACS —Automatic Coffee-quality System. The CT8 monitors and maintains extraction times and automatically optimizes the grind and dose.
- CF Milk System consistently produces high-quality milk foam.
- Melitta CT8 unit is obsolete as of 2024.
- Parts will be supported through 2029.