BIC & BIM Equipment Resources

Multiplex Troubleshooting



Multiplex BIC PLUS (Manual Fill)



Multiplex BIC (Manual Fill)



Taylor C029

Blend In Cup PLUS MA-8-2

Multiplex

- 1-844-724-2273
- Email for service: bevservice@welbilt.com
- Email for parts: bevorders@multiplexbev.com
- Escalation: thomas.scotti@welbilt.com

MA-8-2 PLUS Details:

- Primary approved unit for US market.
- Includes all features and functions of legacy BIC unit.
- Improved blender assembly.
- All stainless interior refrigerator.
- R290 refrigerant for improved efficiency.
- 7” high-definition UI with local network connection.

Blend In Cup MA-8-2 [Legacy]

Multiplex

- 1-844-724-2273
- Email for service: bevservice@welbilt.com
- Email for parts: bevorders@multiplexbev.com
- Escalation: thomas.scotti@welbilt.com

MA-8-2 Legacy Details:

- Legacy Blend-In-Cup machine equipped with open hopper and ice-shaver to allow for half-dice ice to be manually filled in top of unit.
- Programmable menu controls beverage dispense.
- Two chambers to blend two beverages at once.
- Obsoleted for U.S. market in 2023.
- Service parts available through 2033.

Taylor C029

Taylor

- Taylor Direct Service: 1-800-228-8309
- Scott Nicholas scott.Nicholas@taylor-company.com

C029 Details:

- The unit was obsoleted in the U.S. in 2015, and is not available for purchase.
- Service parts are available through 2026.