TOASTERS—PRINCE CASTLE® CBT AND IRT

DAILY

SUPPLIES:



KAY® Rapid Multi Surface Disinfectant Cleaner Solution



KAY® QSR Heat-Activated Equipment Cleaner (HAEC)



Heat-Resistant Gloves




Clean Sanitizer-Soaked Grill Cloths




Clean Sanitizer-Soaked Towels

CORE BUN TOASTER (CBT)




- Turn OFF toaster
- Put on heat-resistant gloves

CBT




- Spray clean sanitizer-soaked towel with Rapid MSDC Solution
- Wipe crumbs from crumb collection area
- Rinse with separate clean sanitizer-soaked towel; discard towel in soiled towel bucket after use

CBT




- Remove in-feed rack, landing zone, clips and release sheets

CBT



- Wash, rinse and sanitize in-feed rack, landing zone tray and clips at 3-compartment sink or in Warewash machine
- Sanitize with Sanitizer Solution for 1 minute; allow to air dry

CBT




- Wipe both sides of release sheet with a clean, sanitizer-soaked towel; discard towel into soiled towel bucket after use

NOTE: DO NOT clean release sheet at 3-compartment sink

NOTE: If heavy buildup on release sheets, spray with Equipment Cleaner and then wipe and rinse

CBT




- While toaster is still **hot**, pull out conveyor belt from toaster while wearing heat-resistant gloves

CBT



- Spray a clean sanitizer-soaked grill cloth with Equipment Cleaner

CBT



- Apply Cleaner onto conveyor belt until it is completely coated
- Scrub conveyor belt with grill cloth
- Discard grill cloth into soiled towel bucket after use

NOTE: If belt has heavy buildup, allow Cleaner to sit for 5-8 minutes and then wipe


ECOLAB®
Kay Chemical Company
8300 Capital Drive
Greensboro, NC 27409-9790, USA

CUSTOMER SERVICE 800.529.5458


59694J02 MCD US 59694/8002/1025 ©2025 Ecolab USA Inc. All rights reserved.

TOASTERS—PRINCE CASTLE® CBT AND IRT (CONTINUED)


DAILY




- Rinse conveyor belt with a separate clean sanitizer-soaked towel; discard towel into soiled towel bucket after use




- Rotate conveyor belt to clean and rinse other side




- Reassemble clean release sheets, clips, in-feed rack and landing zone tray




- Spray a clean sanitizer-soaked towel with Rapid MSDC Solution; wipe exterior of toaster
- Rinse with a separate clean sanitizer-soaked towel; discard towel in soiled towel bucket after use
- Turn ON toaster



- Turn OFF toaster
- Put on heat-resistant gloves



- Remove crumb tray and in and out-feed rack




- Wash, rinse and sanitize crumb tray and in and out-feed rack in 3-compartment sink or Warewash machine
- Sanitize in Sanitizer Solution for 1 minute; allow to air dry



- Spray a clean sanitizer-soaked towel with Equipment Cleaner
- Apply Cleaner onto conveyor belt until belt is completely coated

NOTE: If belt has heavy buildup, allow Cleaner to sit for 5-8 minutes and then wipe



- Wipe wire belt with towel until clean
- Rinse wire belt with separate clean sanitizer-soaked towel; discard towel into soiled towel bucket after use


ECOLAB®
Kay Chemical Company
8300 Capital Drive
Greensboro, NC 27409-9790, USA

CUSTOMER SERVICE 800.529.5458


59694/02 MKD US 59694/8002/1025 ©2025 Ecolab USA Inc. All rights reserved.

TOASTERS—PRINCE CASTLE® CBT AND IRT (CONTINUED)

DAILY



- Spray a clean sanitizer-soaked towel with Rapid MSDC Solution and wipe exterior of toaster
- Rinse exterior with a separate clean sanitizer-soaked towel
- Discard towel into soiled towel bucket after use



- Reinstall clean crumb tray, out and in-feed racks
- Turn toaster ON
- Wash, rinse and sanitize all utensils, tools, and PPE used to clean toaster at 3-compartment sink

59694/02 MCD US 59694/8002/1025 ©2025 Ecolab USA Inc. All rights reserved.