## System Efficiency between L258-2 (26137) and TYSONS (26165) for period 2019-07-16 00:00 to 2019-08-17 00:00

System Efficiency (%): 1.2

Diverted (ML):	634.0 52.2
Delivered (ML):	6.9
Evaporative loss (ML):	0.9
Rainfall (ML):	0.4
Seepage loss (ML):	not yet implemented
Unaccounted loss (ML):	574.4

## Outlets

Telemetered:	1
Manually read:	2
Unmetered sites:	0
Total:	3

2 manually read meters are missing up to date readings.

outlet	object_id	RTU_totaliser (ML)	flow_integral (ML)	manual_reading (ML)	diff	FG_calc
M2367A/1	64120					
L258-3	26585	6.702	6.848		-2.127	6.901
M2367A/3	67663					
	Total	0.0	0.0	0.0		6.9

time of data collection: 2020-04-23 15:04

meters not read: 67663 64120