

Customer : ETD

Rev. Date: Jan 01, 2016

Manual : TSM Type: A380 Selected applicability: ALL

> 36-22-11-991-02400-00-A / SHEET 2/2 - Engine 2 Pylon, Loop 'B' - Fault Location Zone and Access Table (Short Circuit/Overheat)

	FAULT LOCATION ZONE									
LOC	START OF ZONE m ft ITEM			MID POSITION m ft ITEM			END OF ZONE m ft ITEM			ACCESS PANEL(S)
053	0.36		111HF2	0.38		111HF2	0.39		111HF2	463BL
054	0.41		111HF2	0.42		111HF2	0.44	1.44		463BL
055				0.75		119HF2				463BL
056				3.52	11.55	119HF2				463BL
057				0.15	0.49	938				
058				1.60	5.25	938				
059				3.06	10.04	938				
060				4.51	14.80	938				
061				0.51	1.67	4083				
062				1.96	6.43	4083				
063				3.42	11.22	4083				
064 065				4.87 6.33	15.98 20.77	4083 4083	+			
066				7.78	25.52	4083				
067				9.24	30.31	4083	-			
068				10.70	35.10	4083	-			
069				12.15	39.86	4083				
070				13.61	44.65	4083				
071				15.06	49.41	4083				
072				16.52	54.20	4083				
073				17.97	58.96	4083				
074				19.43	63.75	4083				
075				20.88	68.50	4083				
076				22.34	73.29	4083				
077				23.79	78.05	4083				
078				25.25	82.84	4083				
079				26.70	87.60	4083				
080				28.16	92.39	4083				
081 082				29.61	97.15 2.07	4083 7630	-			
082				0.63 2.08	6.82	7630				
084				3.54	11.61	7630	-			
085				4.99	16.37	7630	+			
086				6.45	21.16	7630				<del> </del>
087				7.90	25.92	7630				
088				9.36	30.71	7630				
089				10.81	35.47	7630				
090				12.27	40.26	7630				
091				1.08	3.54	934				
092				2.54	8.33	934				
093				3.99	13.09	934				
094				5.45	17.88	934				
095				6.90	22.64	934				
096				8.36	27.43	934				
097				9.81	32.19	934				
098 099				0.48	1.57 6.33	930 930				
100				1.93 3.39	11.12	930	+			
1001				ა.ა <del>গ</del>	11.12	930				

NOTE: THE DIMENSIONS OF THE START, MID POSITION AND THE END OF THE FAULT LOCATION ZONE ARE MEASURED FROM THE START OF EACH APPLICABLE ITEM (WIRE OR FIN). ALL THE WIRE IDENTS ARE PREFIXED WITH 3622. THE OVERHEAT DETECTION SYSTEM CANNOT CALCULATE A FAULT LOCATION ZONE FOR THE CONNECTING CABLES OR WIRING. THUS, ONLY THE MID POSITION OF A FAULT IS GIVEN TO HELP YOU DO THE TROUBLESHOOTING PROCEDURE FOR THESE ITEMS. L\_TS\_362211\_2\_ADAA\_02\_00

> Figure 36-22-11-991-02400-A- / SHEET 2/2 - Engine 2 Pylon, Loop 'B' - Fault Location Zone and Access Table (Short Circuit/Overheat) ON A/C ALL

Print Date: January 19, 2016 Page 1 of 1