

Customer : ETD

Type: A380

Rev. Date: Jan 01, 2016

Manual : TSM Selected applicability: ALL

36-22-11-991-02600-00-A / SHEET 1/2 - Engine 3 Pylon, Loop 'B' - Fault Location Zone and Access Table (Short Circuit/Overheat)

	FAULT LOCATION ZONE									
Loc	STAF m	RT OF Z	ZONE ITEM	MID POSITION m ft ITEM			END OF ZONE m ft ITEM			ACCESS PANEL(S)
001				1.21	3.97	17				
002				2.42	7.94	17				
003				0.24	0.79	25				
004				1.44	4.72	25				
005				2.65	8.69	25				
006				3.86	12.66	25				
007				5.07	16.63	25				
008				6.28	20.60	25				
009				7.49	24.57	25				
010				8.70	28.54	25				
011				9.90	32.48	25				
012				0.29	0.95	7587				
013				1.50	4.92	7587				
014				2.71	8.89	7587				
015				3.92	12.86	7587				
016				5.13	16.83	7587				
017				6.34	20.80	7587				
018 019				7.54 8.75	24.74 28.71	7587 7587				
020				9.96	32.68	7587				
020				11.17	36.65	7587				
022				12.38	40.62	7587				
023				13.59	44.59	7587				
024				14.80	48.56	7587				
025				0.81	2.66	4140				
026				2.02	6.63	4140				
027				3.23	10.60	4140				
028				4.44	14.57	4140				
029				5.65	18.54	4140				
030				6.86	22.51	4140				
031				8.07	26.48	4140				
032				9.27	30.41	4140				
033				10.48	34.38	4140				
034				11.69	38.35	4140				
035				12.90	42.32	4140				
036				14.11	46.29	4140				
037				15.32	50.26	4140				
038				0.10	0.33	65				
039				1.30	4.27	65 65				
040				2.51	8.23	65 65				
041 042				3.72 0.70	12.20	110HF3				473AR
042				3.00		110HF3				473AR 473AR
043				5.29		110HF3				473AR 473AR
044	0.02	0.07	111HF3	0.03		111HF3	0.04	0.13	111HF3	
045	0.02		111HF3	0.03		111HF3	0.04		111HF3	
047	0.10		111HF3	0.07	0.23	111HF3	0.00		111HF3	
048	0.14		111HF3	0.15		111HF3	0.12		111HF3	
049	0.14	0.59	111HF3	0.19	0.62	111HF3	0.20		111HF3	
050	0.22		111HF3	0.23		111HF3	0.24		111HF3	
051	0.26		111HF3	0.27		111HF3	0.28		111HF3	
052	0.30	0.98	111HF3	0.31		111HF3	0.32		111HF3	

L\_TS\_362211\_2\_AFAA\_01\_00

Page 1 of 1

Figure 36-22-11-991-02600-A- / SHEET 1/2 - Engine 3 Pylon, Loop 'B' - Fault Location Zone and Access Table (Short Circuit/Overheat) ON A/C ALL

Print Date: January 19, 2016