

Customer : ETD

Rev. Date: Jan 01, 2016

Manual : TSM Type: A380 Selected applicability: ALL

> 36-22-11-991-02500-00-A / SHEET 1/2 - Engine 3 Pylon, Loop 'A' - Fault Location Zone and Access Table (Short Circuit/Overheat)

	FAULT LOCATION ZONE									
LOC	STAR m	START OF ZONE m ft ITEM			MID POSITION m ft ITEM			D OF Z	ONE ITEM	ACCESS PANEL(S)
001				1.17	3.84	981				
002				2.35	7.71	981				
003				3.52	11.55	981				
004				1.08	3.54	993				
005				2.25	7.38	993				
006				3.43	11.25	993				
007				4.60	15.09	993				
800				5.77	18.93	993				
009				6.95	22.80	993				
010				8.12	26.64	993				
011				9.30	30.51	993				
012				10.47	34.35	993				
013				0.62	2.03	7633 7633				
014				1.79 2.97	5.87 9.74	7633	+			
016	+			4.14	13.58	7633	+			
016	+			5.31	17.42	7633				
017				6.49	21.29	7633				
019				7.66	25.13	7633				
020				8.84	29.00	7633				
021				10.01	32.84	7633				
022				11.19	36.71	7633				
023				12.36	40.55	7633				
024				0.62	2.03	4074				
025				1.80	5.91	4074				
026				2.97	9.74	4074				
027				4.15	13.62	4074				
028				5.32	17.45	4074				
029				6.50	21.33	4074				
030				7.67	25.16	4074				
031				8.84	29.00	4074				
032				10.02	32.87 36.71	4074 4074				
033				11.19 12.37	40.58	4074	+			
034				13.54	44.42	4074	+			
036				14.72	48.29	4074	+			
037	+			15.89	52.13	4074	+			
038	+			0.64	2.10	1005				
039				1.81	5.94	1005				
040				2.98	9.78	1005				
041				4.16	13.65	1005				
042				1.22		100HF3				473AR
043				3.45	11.32	100HF3				473AR
044				5.68		100HF3				473AR
045	0.02		101HF3	0.03		101HF3	0.05	0.16		
046	0.06		101HF3	0.07		101HF3	0.08			
047	0.10		101HF3	0.11	0.36	101HF3	0.12	0.39		
048	0.14		101HF3	0.15		101HF3	0.16		101HF3	
049 050	0.18 0.22		101HF3 101HF3	0.19 0.23		101HF3 101HF3	0.20		101HF3 101HF3	
050	0.22		101HF3	0.23		101HF3	0.24			
051	0.20		101HF3	0.27		101HF3	0.20		101HF3	
002	0.00	0.90	10111113	0.01	1.02	10111113	0.02	1.00	10111110	710/111

L_TS_362211_2_AEAA_01_00

Figure 36-22-11-991-02500-A- / SHEET 1/2 - Engine 3 Pylon, Loop 'A' - Fault Location Zone and Access Table (Short Circuit/Overheat) ON A/C ALL

Print Date: January 19, 2016 Page 1 of 1