

Customer : ETD

Type: A380

Rev. Date: Jan 01, 2016

Manual : TSM Selected applicability : ALL

36-22-11-991-05700-00-A / SHEET 2/2 - Engine 1 Pylon, Loop 'A' - Fault Location Zone and Access Table (Short Circuit/Overheat)

	FAULT LOCATION ZONE									
Loc	START OF ZONE			MID POSITION			END OF ZONE			ACCESS PANEL(S)
1	m	ft	ITEM	m	ft	ITEM	m	ft	ITEM	4500
053	0.43	1.41	101HF1	0.45	1.48	101HF1	0.46	1.51	101HF1	453BL
054 055				3.25 0.70	10.66 2.30	109HF1 62				453BL
056				2.85	9.35	62				
057				5.00	16.40	62				
058				1.19	3.90	4089				
059				3.34	10.96	4089				
060				5.49	18.01	4089				
061				7.64	25.07	4089				
062				9.79	32.12	4089				
063				11.93	39.14	4089				
064				14.08	46.19	4089				
065				16.23	53.25	4089				
066				18.38	60.30	4089				
067				20.52	67.32	4089				
068				22.67	74.38	4089				
069				24.82	81.43	4089				
070				26.97	88.48	4089				
071				29.12	95.54	4089				
072					102.56	4089				
073					109.61	4089				
074				1.16	3.81	924				
075 076				3.31	10.86	924				
076				5.45 7.60	17.88 24.93	924 924				
077				9.75	31.99	924				
079				11.90	39.04	924				
080				14.04	46.06	924				
081				16.19	53.12	924				
082				18.34	60.17	924				
083				20.49	67.22	924				
084				22.64	74.28	924				
085				24.78	81.30	924				
086				26.93	88.35	924				
087				0.62	2.03	7592				
088				2.77	9.09	7592				
089				4.91	16.11	7592				
090				7.06	23.16	7592				
091				9.21	30.22	7592				
092				11.36	37.27	7592				
093				13.51	44.32	7592				
094				1.43	4.69	22				
095				3.58	11.75	22				
096				5.73	18.80	22				
097				7.88	25.85	22				
098				10.02	32.87	22				
099				1.42	4.66 11.71	14				
100				3.57	11.71	14				

NOTE: THE DIMENSIONS OF THE START, MID POSITION AND THE END OF THE FAULT LOCATION ZONE ARE MEASURED FROM THE START OF EACH APPLICABLE ITEM (WIRE OR FIN). ALL THE WIRE IDENTS ARE PREFIXED WITH 3622. THE OVERHEAT DETECTION SYSTEM CANNOT CALCULATE A FAULT LOCATION ZONE FOR THE CONNECTING CABLES OR WIRING. THUS, ONLY THE MID POSITION OF A FAULT IS GIVEN TO HELP YOU DO THE TROUBLESHOOTING PROCEDURE FOR THESE ITEMS.

L_TS_362211_2_AAAA_02_00

Figure 36-22-11-991-05700-A- / SHEET 2/2 - Engine 1 Pylon, Loop 'A' - Fault Location Zone and Access Table (Short Circuit/Overheat)

** ON A/C ALL

Print Date: January 19, 2016 Page 1 of 1