

Customer : ETD

Type: A380

Rev. Date : Jan 01, 2016

36-22-11-991-02300-00-A / SHEET 2/2 - Engine 2 Pylon, Loop 'A' - Fault Location Zone and Access Table (Short Circuit/Overheat)

Manual : TSM

Selected applicability: ALL

			F	AULT I						
Loc	OC START OF ZONE				MID POSITION			O OF Z	ONE	ACCESS PANEL(S)
	m				m ft ITEM			ft	ITEM	71002001711122(0)
053	0.34	1.12	101HF2	0.35	1.15	101HF2	0.37	1.21	101HF2	
054	0.38	1.25	101HF2	0.40		101HF2	0.41		101HF2	
055	0.42	1.38	101HF2	0.44	1.44	101HF2	0.45	1.48	101HF2	
056				1.01	3.31	109HF2				
057				3.35	10.99	109HF2				
058 059				5.70 1.08	3.54	109HF2 64				
060				2.31	7.58	64				
061				3.55	11.65	64				
062				4.78	15.68	64				
063				0.55	1.80	4083				
064				1.78	5.84	4083				
065				3.02	9.91	4083				
066				4.25	13.94	4083			_	
067				5.49	18.01	4083				
068				6.72	22.05	4083				
069				7.96	26.12	4083				
070				9.19	30.15	4083				
071				10.43	34.22	4083				
072 073				11.66 12.90	38.25 42.32	4083 4083				
073				14.13	46.36	4083				
074				15.37	50.43	4083				
076				0.21	0.69	7586				
077				1.45	4.76	7586				
078				2.68	8.79	7586				
079				3.92	12.86	7586				
080				5.15	16.90	7586				
081				6.39	20.96	7586				
082				7.62	25.00	7586				
083				8.86	29.07	7586				
084				10.09	33.10	7586				
085 086				11.33 12.56	37.17 41.21	7586 7586				
086				13.80	45.28	7586 7586				
088				15.03	49.31	7586				
089				1.03	3.38	24				
090				2.26	7.41	24				
091				3.50	11.48	24				
092				4.73	15.52	24				
093				5.97	19.59	24				
094				7.20	23.62	24				
095				8.44	27.69	24				
096				9.67	31.73	24				
097				10.91	35.79	24				
098				1.15	3.77	16				
099				2.39	7.84	16				
100				3.62	11.88	16				

NOTE: THE DIMENSIONS OF THE START, MID POSITION AND THE END OF THE FAULT LOCATION ZONE ARE MEASURED FROM THE START OF EACH APPLICABLE ITEM (WIRE OR FIN).
ALL THE WIRE IDENTS ARE PREFIXED WITH 3622. THE OVERHEAT DETECTION SYSTEM CANNOT CALCULATE A FAULT LOCATION ZONE FOR THE CONNECTING CABLES OR WIRING. THUS, ONLY THE MID POSITION OF A FAULT IS GIVEN TO HELP YOU DO THE TROUBLESHOOTING PROCEDURE FOR THESE ITEMS.

L\_TS\_362211\_2\_ACAA\_02\_00

Figure 36-22-11-991-02300-A- / SHEET 2/2 - Engine 2 Pylon, Loop 'A' - Fault Location Zone and Access Table (Short Circuit/Overheat)

\*\* ON A/C ALL

Print Date: January 19, 2016 Page 1 of 1