

ARMADA DE CHILE

DIRECCIÓN GENERAL DEL TERRITORIO MARÍTIMO Y DE MARINA MERCANTE

Copy to:

FORM A Master

Head Office PSCO

If ship is detained copy to: Flag State R.O.

PORT STATE CONTROL INSPECTION REPORT

Address: Av. Errázuriz 537 - Valparaíso - CHILE Telephone: +56 (32) 2208613 - 2208641

e-Mail: psc@dgtm.cl Latinamerican Agreement on Port State Control (Viña del Mar Agreement) 1992 and Memorandum of Understanding on Port State Control in the Asia-Pacific (Tokyo MOU) 1993

1.na	me of reporting authority		2.na	me of sh	ip	SAINT ALBANS	BAY
5.IIa	g of ship	MH - Marchall Iclande	A 1			Au	er (OILCHEM)
5.ca	II sign/MMSI	005189 6.IMO numbe r 9697648	7.gross	tonnage	298	niewbeek 8 408	ht 49990
o.uu	10.11.2015	_ 10.date of inspection 10.05.2	1024	lace of ir	rspection	CLQTY	Quintero
12.c	assification society	128 - DNV AS (DNV)		13.dat	te of rele	ase from deterition	12 AN
14a.	lassification society IMO company number	5562457 14b.particulars of c	company		Scorpio I	Marine Management Und	ial Pyt Ltd o
15.n	ame and signature of ma	aster to certify that the informat	tion under	14b is c	orrect:	12/1	10
	name	AJAY SINGH			signat	uro VA WM	ASTER 2
16.d	etails of ship certificates:				Signat	ule	/*/
Code	Title	Issuing authority	Date of	Date of	Data of	1 0	
		leading additionly	issue	expire	Date of survey	Surveying authority 1	A plurayed place
501	Cargo Ship Safety Construction	DNV AS (DNV) (128)	20,11,2021	13.10.2025	27.10.2023	DNIV AC (DNI) O (400)	
502	Cargo Ship Safety Equipment	DNV AS (DNV) (128)	20.11.2021	13.10.2025	10.10.2023	DNV AS (DNV) (128) DNV AS (DNV) (128)	ANTWERPEN, BE
503	Cargo Ship Safety Radio	DNV AS (DNV) (128)	20,11,2021	13.10.2025	10.10.2023	DNV AS (DNV) (128)	PASCAGOULA, US
505	International Oil Pollution Prevention	DNV AS (DNV) (128)	21.04.2022	24.08.2024	10.10.2023	DNV AS (DNV) (128)	PASCAGOULA, US
	(IOPP)		327188721-10-0		10.10.2020	DIV AS (DIV) (128)	PASCAGOULA, US
506	International Air Pollution Prevention	DNV AS (DNV) (128)	10.10.2023	13.10.2025			
507	International Sewage Pollution	DNV AS (DNV) (128)	20.11.2021	13.10.2025			
	Prevention						
508	Load Line	DNV AS (DNV) (128)	20.11.2021	13.10.2025	10.10.2023	DNV AS (DNV) (128)	PASCAGOULA, US
509	Document of Compliance	American Bureau of Shipping (101)	25.11.2022	28.01.2028	22.11.2023	American Bureau of Shipping (101)	MUMBAI, IN
510	Safety Management Certificate	DNV AS (DNV) (128)	20.11.2021	04.11.2025	22.02.2023	DNV AS (DNV) (128)	HOUSTON, US
511	International Ship Security	DNV AS (DNV) (128)	20.11.2021	04.11.2025	22,02,2023	DNV AS (DNV) (128)	HOUSTON, US
512	Minimum Safe Manning Document	Marshall Islands (MH)	27.03.2023				
515	Dangerous Chemicals in Bulk (ICoF/IBC Code)	DNV AS (DNV) (128)	20.11.2021	13.10.2025	10.10.2023	DNV AS (DNV) (128)	PASCAGOULA, US
523	Tonnage	DNV GL AS (278)	23.10,2020				
528	International Ballast Water	DNV AS (DNV) (128)	20.11.2021	13.10,2025	10.10.2023	DNV AS (DNV) (128)	PASCAGOULA, US
	Management				12-25/	PRODUCES A MEET A PERSON OF PROBABILITY IS	
529	International Anti-Fouling System	DNV AS (DNV) (128)	20,11,2021				
530	Civil Liability for Oil Pollution Damage	Marshall Islands (MH)	03.01.2024	20.02.2025			
531 532	Bunker Oil Pollution Damage	Marshall Islands (MH)	03.01.2024	20.02.2025			
0.000	International Energy Efficiency (IEE) Maritime Labour Certificate	DNV AS (DNV) (128)	10.10.2023				
		DNV AS (DNV) (128)	20.11.2021	04.11.2025	22.02.2023	DNV AS (DNV) (128)	HOUSTON, US
	tion actions taken: 26 - competent security aut	hority informed	17.0	leficiencie	s		yes
27 - ship expelled on security grounds						no 3)	
	40 - next port informed					ntation	
	30 - Hag state/consul informed						A Joseph
	55 - flag state consulted	577 a (n a n) 180 none (n a 1				n // /	
	70 - recognized organization	1 informed				7 11 1/12	
<u> </u>	151 - ILO informed	rention of discharge provisions (MA	RPOL)			Musical	
	152 - seafarers' organization	a lufa d				illy	
	155 - ship owner representa	i informed				land 1	
	100 - 3mp owner representa	tive informed				11.10	
12/2004	***	8			1	N/	
Issuing			PSCO	PSCO name JORGE IMHOFF			
Telepho			Signatu	Signature			
Telefax	î						-
		Armada de Chile IRECTEMAR					
ORIO AD MARIA							
PSC OFFICI					PSC OFFICER		
PSC OFFICER					JORGE IMHOFF		
		1	B W	44/	Mail: jorg	eimhoff@gmail.com	
					Tel: +56-940003354		
			OA DE		rei: +56	940003354	s

This report must be retained on board for period of two years and must be available for consultation by Port State Control Officers at all times.

VALPARAISO

¹⁾ This inspection report has been issued solely for the purpose of informing the master and other port States that an inspection by the port State, mentioned in the heading, has taken place. This inspection report cannot be construed as a seaworthiness certificate in excess of the certificates the ship is required to carry
2) To be completed in the event of a detention
3) Masters and companies are advised that detailed information on a detention may be subject to future publication



ARMADA DE CHILE

DIRECCIÓN GENERAL DEL TERRITORIO MARÍTIMO Y DE MARINA MERCANTE

Copy to:

FORM B Master Head Office

PSCO If ship is detained copy to:

Flag State R.O.

PORT STATE CONTROL INSPECTION REPORT

Av. Errázuriz 537 - Valparaiso - CHILE

Telephone: +56 (32) 2208613 - 2208641

e-Mail: osc@datm.cl

Latinamerican Agreement on Port State Control (Viña del Mar Agreement) 1992 and Memorandum of Understanding on Port State Control in the Asia-Pacific (Tokyo MOU) 1993

2.na	ame of	shipSAINT ALBANS BAY 6.IMO number9697648 _ 10.date o	f inspection _10.05.2	024 11.place of inspection	CLQTV - Quintero	
		eficiencies			O SUDAD MA	
no.	Code	Nature of deficiency 4)	Conventions 5)	Action(s) taken 6)	Responsible RO	
1		PROPULSION AND AUXILIARY MACHINERY/Gauges, thermometers, etc/AT THE ENGINE ROOM, INSIDE THE PURIFIER ROOM, THE AUXILIARY BOILER NUMBER ONE FUEL OIL PUMP SUCTION PRESSURE GAUGE, WAS FOUND UNREADABLE.	SOLAS ch. II-1 Parts C, D, E, F	17 - Rectify deficiency before depart	ure PSC OFFICER	
2		agreement (SEA)/AT THE TIME OF THE INSPECTION, THE SEAFARER EMPLOYMENT AGREEMENTS OF BOSUN AND CHIEF COOK WERE FOUND EXPIRED.	MLC 2006 Title 2	17 - Rectify deficiency before departure No-Deficiency rectified.		
3		FIRE SAFETY/Oil accumulation in engine room/AT THE ENGINE ROOM, INSIDE THE PURIFIERS ROOM, FUEL OIL PURIFIER NUMBER ONE AND TWO, WERE FOUND WITH PLENTIFUL OF FUEL OIL AT THE INSULATION MATERIAL AGAINST FIRE.	SOLAS ch. I	17 - Rectify deficiency before departs	ired. What PSC ONG ICER	
4	11132	LIFE SAVING APPLIANCES/Maintenance and inspections/AT THE RESCUE BOAT THE TOP LIGHT, WAS FOUND BUSTED.	LSA Code	17 - Rectify deficiency before departs	cited PSC OFFICER	
PSCO name JORGE IMHOFF			SAINT ALBANS OF A	Signature Signature	DATE OF ICER PSC OFFICER	
reconn	lenueu ma	on was not a full survey and deficiencies listed may not be exhaustive. In the event of a detention, it is it a full survey is carried out. All deficiencies should be rectified before an application for re-inspection is made.	MAJURO	AND OOZ CHE	JORGE IMHOFF Mail: jorgeimhoff@gmail.com Tel: +56-940003354 VALPARAISO CHILE	



Applicable Deficiency Action Codes (see reverse side of copy) to be entered.