



- Reporting Authority: Scheepvaartcontrole Antwerpen - Address: FPS Mobility - DG Shipping

- Telephone: +32 3 229 00 30

Port State Control Entrepotplaats 1 bus 7 2000 Antwerpen

Belgium

- Email: PSC@mobilit.fgov.be - Website:

SHIP PARTICULARS										
Name	ELEGANT VOYAGER	IMO Number	9547506	Gross Tonnage	28777					
Flag	Marshall Islands	MMSI Number	538010955	Old Tonnage						
Туре	Oil tanker	Date Keel Laid/Major Conv.	19/12/2008	Main Engine (KW)	9480					
Call Sign	V7A6364	Deadweight	48006	Emission Abatement Method						

ISM COMPANY									
Name	Scorpio Marine Management		IMO Company Number	5562457					
Address		City		Country	India				

MLC SHIPOWNER								
Name	ne Scorpio Marine Management (India) Private Limited							
Address		City		Country	India			

^{*)} This inspection report has been issued solely for the purpose of informing the master and other port States that an inspection by the port State, mentioned in the heading, has taken place. This inspection report cannot be construed as a seaworthiness certificate in excess of the certificates the ship is required to carry.

^{**)} Masters, Shipowners and/or Operators are advised that detailed information on the inspection will be reported to the appropriate authorities and organisations and is subject to publication.

^{***) &}quot;Outstanding deficiencies" are listed for information only and will not be taken into account for the calculation of the Ship Risk Profile and Company performance.





Name Of Ship	р	ELEGAI	NT VOYAGER	IMO Number		9547506	Date Of Report	01/08/20)24	Place Of Inspection	on	Antwerpen	
CHARTERE	ER (only ship	s carryir	ng liquid or solid	cargoes in bu	ılk, pref. 1st	charterer record)							
Name			Repsol Trading S	.A.									
Address					City		Madrid		Country		Spain		
	Demise Cha	arter				Time Charter				Voyage Charter			
Name and s	signature of r	master to	confirm the rec	eipt of the ins	pection repo	ort and to certify that the in	nformation on charterer is	correct:					
Name							Signature						
Classification	n Society/io	c) rocno	ncible for iccurre	on of class of	rtificatos								
Classification Society(ies) responsible for issuance of class certificates Issuing Entity RINA Services S.p.A. Date Of Issue						Issue	06/05/2024 Date Of Expiry			06/10/20	724		
looding Entity			111111111111111111111111111111111111111	P., t.	24.0 01	10000	00/00/2021		Date of Expliy		00/10/2	<i>5</i> 2 1	
Recognised	Organizatio	n(s) resp	ponsible for issua	ance of certifi	cates on bel	nalf of the flag State							
Issuing Entity	,		American Bureau	of Shipping									
Issuing Entity	•		RINA Services S.	p.A.									
INIODEOTIO	NI DADTIOLI	II A D.O. **	.										
	N PARTICU	ILARS **	<u>-</u>				DI 041 II			•			
Date Of First				01/08/2024			Place Of Inspection			Antwerpen			
Date Of Repo	ort			01/08/2024			If detained: Date Of Issue Of	Of Detenti	on No				
Type Of Ins	pection												
	Initial Inspecti	on		П м	ore Detailed I	nspection	Expanded Inspect	ion		CIC			
Checked	Operational	Control	(if any)		Additional (Comment							
				ency generator under load, simulated black out									

^{*)} This inspection report has been issued solely for the purpose of informing the master and other port States that an inspection by the port State, mentioned in the heading, has taken place. This inspection report cannot be construed as a seaworthiness certificate in excess of the certificates the ship is required to carry.

^{**)} Masters, Shipowners and/or Operators are advised that detailed information on the inspection will be reported to the appropriate authorities and organisations and is subject to publication.

^{***) &}quot;Outstanding deficiencies" are listed for information only and will not be taken into account for the calculation of the Ship Risk Profile and Company performance.





Name Of Shi	p	ELEGANT VOYAGER	IMO Number		9547506	Date Of Report	01/08/2024	Place Of Inspection	Antwerpen
	Abandon shi	p drill							
	Damage Cor	ntrol drill							
	Enclosed spa	ace entry drill							
\boxtimes	Emergency	steering drill							
\boxtimes	Fire drill			in emergenc	y generator room				
	Man Over Bo	oard drill							
	Rescue Boa	t drill							
	SMPEP drill								
	SOPEP drill								
Checked	Areas Inspe	ected		Additional (Comment				
\boxtimes	Accommoda	tion and galley							
	Ballast tank(s) - internal							
\boxtimes	Ballast tank(s) - from manhole		1P & 4P					
	Vehicle deck	(
\boxtimes	Cargo area			HLA					
\boxtimes	Engine room	1							
\boxtimes	Navigation b	ridge							
\boxtimes	Decks and fo	precastle							
	Passenger s	paces							

^{*)} This inspection report has been issued solely for the purpose of informing the master and other port States that an inspection by the port State, mentioned in the heading, has taken place. This inspection report cannot be construed as a seaworthiness certificate in excess of the certificates the ship is required to carry.

^{**)} Masters, Shipowners and/or Operators are advised that detailed information on the inspection will be reported to the appropriate authorities and organisations and is subject to publication.

^{***) &}quot;Outstanding deficiencies" are listed for information only and will not be taken into account for the calculation of the Ship Risk Profile and Company performance.





Name Of Sh	ip	ELEGANT VOYAGER	IMO Number	9547506	Date Of Report	01/08/2024	Place Of Inspection	Antwerpen
\boxtimes	Steering-roor	m						

RELEVANT CERTIFICATES						
				Information of	on last intermediate, period	ical or annual
Title Certificate	Issuing Authority	Date Of Issue	Date Of Expiry	Date Of Survey	Surveying Authority	Country
Bunker Oil Pollution Damage	Marshall Islands	08/05/2024	20/02/2025			
Cargo Ship Safety Construction	RINA	06/05/2024	06/10/2024			
Cargo Ship Safety Equipment	RINA	06/05/2024	06/10/2024			
Cargo Ship Safety Radio	RINA	06/05/2024	06/10/2024			
Civil Liability for Oil Pollution Damage	Marshall Islands	08/05/2024	20/02/2025			
Continuous Synopsis Record[8]	Marshall Islands	15/05/2024				
Document of Compliance	ABS	25/11/2022	28/01/2028	22/11/2023	ABS	India
Engine International Air Pollution Prevention[MAC119924XT/003]	RINA	06/05/2024				
Engine International Air Pollution Prevention[MAC119924XT/001]	RINA	06/05/2024				
Engine International Air Pollution Prevention[MAC119924XT/004]	RINA	06/05/2024				
Engine International Air Pollution Prevention[MAC119924XT/002]	RINA	06/05/2024				
International Air Pollution Prevention	RINA	06/05/2024	06/10/2024			
International Anti-Fouling System	RINA	06/05/2024				
International Ballast Water Management	RINA	06/05/2024	06/10/2024			

^{*)} This inspection report has been issued solely for the purpose of informing the master and other port States that an inspection by the port State, mentioned in the heading, has taken place. This inspection report cannot be construed as a seaworthiness certificate in excess of the certificates the ship is required to carry.

^{**)} Masters, Shipowners and/or Operators are advised that detailed information on the inspection will be reported to the appropriate authorities and organisations and is subject to publication.

^{***) &}quot;Outstanding deficiencies" are listed for information only and will not be taken into account for the calculation of the Ship Risk Profile and Company performance.





Name Of Ship	ELEGANT VOYAGER	IMO Number	9547506	Date Of Report	01/08/2024	Place Of Inspection	Antwerpen
International Ene	ergy Efficiency Certificate	RINA	06/05/2024				
International Oil P	ollution Prevention (IOPP)	ABS	06/05/2024	06/10/2024			
International Sewage Pollution Prevention		RINA	06/05/2024	06/10/2024			
International Ship Security		Marshall Islands	08/05/2024	07/11/2024			
Load Line		RINA	06/05/2024	06/10/2024			
Maritime	Labour Certificate	Marshall Islands	08/05/2024	07/11/2024			
Minimum Saf	e Manning Document	Marshall Islands	18/12/2023				
	Convention on the Removal of Wrecks	Marshall Islands	08/05/2024	20/02/2025			
Safety Man	agement Certificate	Marshall Islands	08/05/2024	07/11/2024			
Tonnage		ABS	26/12/2023				

INSPECTIO	ON ACTIONS	
Checked	Ship related inspection action taken (if any)	Additional Comment
	Inspection suspended	
	Dismissed on AFS grounds	
	Excluded on AFS grounds	
	Vessel expelled on other grounds	
	Vessel expelled on security grounds	
	Marpol investigation of contravention of discharge provision	

^{*)} This inspection report has been issued solely for the purpose of informing the master and other port States that an inspection by the port State, mentioned in the heading, has taken place. This inspection report cannot be construed as a seaworthiness certificate in excess of the certificates the ship is required to carry.

^{**)} Masters, Shipowners and/or Operators are advised that detailed information on the inspection will be reported to the appropriate authorities and organisations and is subject to publication.

^{***) &}quot;Outstanding deficiencies" are listed for information only and will not be taken into account for the calculation of the Ship Risk Profile and Company performance.





Name Of Shi	ip	ELEGANT VOYAGER	IMO Number		9547506	Date Of Report	01/08/2024	Place Of Inspection	Antwerpen
Checked	Ship related	d reporting action taken (if any)	Additional (Comment				
	Coastal State	e informed							
	ILO informed	d							
	Other author	rity informed							
	Observations	s to inspection							
	Shipowner a	and seafarer organization info	ormed						
	Overriding F	actor							
	Flag State re	equested to submit action pla	an within						
	Next port info	ormed							
	Flag State in	formed							
	RO informed	i							
DEFICIENC	<u>CIES</u>			no	Σ	yes (see attached FORM B)			
OUTSTANI	DING DEFIC	EIENCIES***		no	Σ	yes (see attached FORM B)			
SUPPORTI	ING DOCUM	<u>IENTATION</u>		no no		yes (see annex)			

^{*)} This inspection report has been issued solely for the purpose of informing the master and other port States that an inspection by the port State, mentioned in the heading, has taken place. This inspection report cannot be construed as a seaworthiness certificate in excess of the certificates the ship is required to carry.

^{**)} Masters, Shipowners and/or Operators are advised that detailed information on the inspection will be reported to the appropriate authorities and organisations and is subject to publication.

^{***) &}quot;Outstanding deficiencies" are listed for information only and will not be taken into account for the calculation of the Ship Risk Profile and Company performance.





Name Of Ship	ELEGANT VOYAGER IMO Number		IMO Number	9547506	Date Of Report	01/08/2024		Place Of Inspection	Antwerpen
PORT STATE PARTICI	<u>ULARS</u>								
Head Office/District Office Scheepvaartcontrole Antwerpen					Telephone	Telephone		0 30	
Address FPS Mobility – DG Shipping Port State Control Entrepotplaats 1 bus 7 2000 Antwerpen Belgium				Email	Email PSC@mo		obilit.fgov.be		
				Website	Website				
Name(s) of duly au	Name(s) of duly authorized PSCO(s) of reporting authority		ng authority	Signature			Visit Date		
CLAUS HEYVAERTS						01/08/2024			
Caroline CORNAND								01/08/2024	

This report must be retained on board for a period of at least three years and must be readily available for consultation by Port State Control Officers at all times.

^{*)} This inspection report has been issued solely for the purpose of informing the master and other port States that an inspection by the port State, mentioned in the heading, has taken place. This inspection report cannot be construed as a seaworthiness certificate in excess of the certificates the ship is required to carry.

^{**)} Masters, Shipowners and/or Operators are advised that detailed information on the inspection will be reported to the appropriate authorities and organisations and is subject to publication.

^{***) &}quot;Outstanding deficiencies" are listed for information only and will not be taken into account for the calculation of the Ship Risk Profile and Company performance.





Name Of Ship ELEGANT VOYAGER IMO Number	9547506 Dat	ate Of Report 01/08/2024	Place Of Inspection	Antwerpen
---	-------------	--------------------------	---------------------	-----------

DE	DEFICIENCIES FOUND AND FOLLOW UP ACTIONS											
Nr.	Code	Defective Item	Nature Of Defect*	Convention Reference	Action Taken	Due Date	Ground For Detention	Accidental Damage**	RO resp.	ISM Related	Additional Comments	
1	01199	Other (certificates)	Other	SOLAS ch. I - SOLAS ch. I	17 - To be rectified before departure	01/08/2024					Most of the statutory certificates (e;g; safety certificates, Ballast water,) have been issued as 'INTERIM' certificates based upon the date of the survey on which these certificates are based. The recurrent 'completion date' on which these surveys are based is 06-05-2024. However, no proof of completed renewal surveys, at this date, could be shown.	
2	14802	Ballast Water Record Book	Not properly filled	Ballast Water Management - BWM 2004 Convention / ANNEX / Regulation B-2	99 - Master instructed to	01/08/2024					Not each operation concerning Ballast Water has been fully recorded without delay in the Ballast Water record book. The vessel tends to enter only one ballast operation at the end of all separate ballast operations conducted. The Master is instructed to comply with the Ballast Management code requirements, as from today, 01-08-2024, onwards.	
3	07111	Personal equipment for fire safety	Not approved	SOLAS ch. II-2 - SOLAS 2012 Amend / Chapter II-2 / Reg. 10.10.1	17 - To be rectified before departure	01/08/2024					Vessel not equipped with approved firefighting outfits - 4 pieces complete with helmets/boots/gloves/costumes have to be ordered before departure of the vessel	
4	07125	Evaluation of crew performance (fire drills)	Lack of training	SOLAS ch. II-2 - SOLAS 2013 Amend / Chapter III / Reg. 19	17 - To be rectified before departure	01/08/2024					insufficient training in firefighting, proper donning of approved fireman outfits, communication, awareness of present alarms (e.g. low pressure whistle on breathing apparatus did not result in any action from the participants)	

^{*)} This inspection was not a full survey and deficiencies listed may not be exhaustive. In the event of a detention, it is recommended that a full survey is carried out. All deficiencies should be rectified before an application for reinspection is made.

^{**)} Deficiencies marked as Accidental Damage are not taken into account for calculating the company performance and Ship Risk Profile.





Nar	me Of Ship	FLEGANT	VOYAGER IM	IO Number	9547506	Date Of F	Report	01/08/2024		Place Of	Inspection	Antwerpen	
1401	110 01 01111	LEEG/III	VOTAGER III	Trainisor	0047000	Date 011	1	01/00/2024		1 1000 01	1	7 tittworpon	
Nr.	Code	Defective Item	Nature Of Defe	ct* Convention Reference	Action Taken	Due Date	Ground For Detention	Accidental Damage**	RO resp.	ISM Related	Add	itional Comments	
5	04102	Emergency fire pump and its pipes	Not properly maintained	SOLAS ch. II-2 - SOLAS 1999/2000 Amend / Chapter II- / Reg. 14.2	17 - To be rectified before departure	01/08/2024					deck fire line is closing	deck fire line isolation valve not fully closing	
6	03108	Ventilators, air pipes, casings Not properly maintained		Load Lines - ICLL 2003 Amend / ANNEX I / Reg. 19	16 - To be rectified within 14 days	15/08/2024					several ventillation flaps gaskets in pool condition, some ventillation flaps are no easily accessible for closing by a persor steps missing to reach it for shorter peo		
7	02107	Ballast, fuel and other tanks	Not as required	SOLAS ch. II-1 Part A, A-1, B, B-1,B-2, I 3, B-4 - SOLAS 200 Amend / Chapter II- / Reg. 3-6	rectified within 14 days	15/08/2024					gaskets of son	ne ballast tanks deteriorated	
8	07113	Fire pumps and its pipes	Not as required	SOLAS ch. II-2 - SOLAS 1999/2000 Amend / Chapter II- / Reg. 14.2	17 - To be rectified before departure	01/08/2024					several valves monitors not re	from hydrants / foam eadily oprable	
9	13104	Bilge pumping arrangements Inoperative		SOLAS ch. II-1 Part C, D, E, F - SOLAS 1989/1990 Amend / Chapter II-1 / Reg. 21.1	s 17 - To be rectified before departure	01/08/2024					the pumps cor bilge pumping pumps, direct inoperative wh 2) The same of priming/vacuu seawater cool	cuum systems, installed on nected to the engine room arrangements (main fire suction), are found frozen, nen tested. Condition found on the m unit installed the main ing pump, connected to the ction bilge engine room	

^{*)} This inspection was not a full survey and deficiencies listed may not be exhaustive. In the event of a detention, it is recommended that a full survey is carried out. All deficiencies should be rectified before an application for reinspection is made.

^{**)} Deficiencies marked as Accidental Damage are not taken into account for calculating the company performance and Ship Risk Profile.





Name Of Ship		ELEGANT VOYAGER IMO Number		IMO Number	95	9547506		Date Of Report		01/08/2024		Inspection	Antwerpen	
Nr.	Code	Defective Item	Nature Of D	efect*	nvention ference	Action Taken	Due Date	Ground For Detention	Accidental Damage**	RO resp.	ISM Related	Additional Comments		
10	07113	Fire pumps and its pipes	Not as require	SOLAS	1999/2000 Chapter II-2	16 - To be rectified within 14 days	15/08/2024					Fire and G.S pump: suction line is temporarily repaired by means of double plate and leaking besides the mentioned repair. In the meantime, the suction valvis kept closed, and the fire pump is not readily available for immediate use (can be started remotely)		
	Name(s	s) of duly authorized PS0	CO(s) of reportir	ng authority		Signature					Visit Date			
		CLAUS HEYV	/AERTS			01/08/2024								
		Caroline COF	RNAND							01/08/2024				

^{*)} This inspection was not a full survey and deficiencies listed may not be exhaustive. In the event of a detention, it is recommended that a full survey is carried out. All deficiencies should be rectified before an application for reinspection is made.

^{**)} Deficiencies marked as Accidental Damage are not taken into account for calculating the company performance and Ship Risk Profile.





Name Of Ship		ELEGANT VOYAGER IMO Number		9547506		Date Of Report	01/08/2024			Place Of Inspection		Antwerpen		
<u>OL</u>	OUTSTANDING DEFICIENCIES FOUND													
Nr.	Code	e Defective Item		Nature Of Defect*		Convention Reference		Inspection	Rectif	etified RO resp.		ISM Related	Additional Comments	
1	18425	Access / st (ship)	ructural features	Damage	d	MLC	2006 Title 4 - Reg 4.3	2023-05-25 - Canada, Quebec City						el grating on the foward and main deck is badly corroded
2	07108 Ready availability of fire Inoperating fighting equipment		Inoperati	ive	SOLA	AS ch. II-2 - Reg. 14.1	2023-05-25 - Canada, Quebec City					need to be repa	ompressor is defective, ired or replaced by 2023- ed Flag Condition.	
	Name(s) of duly authorized PSCO(s) of reporting authority Signature Visit Date													
	CLAUS HEYVAERTS					S.g. addio					01/08/2024			
Caroline CORNAND										01/08/2024				

^{*)} This inspection was not a full survey and deficiencies listed may not be exhaustive. In the event of a detention, it is recommended that a full survey is carried out. All deficiencies should be rectified before an application for reinspection is made.