

REPORT OF INSPECTION IN ACCORDANCE WITH IMO AND ILO PORT STATE CONTROL PROCEDURES

GPO Box 2181 CANBERRA ACT 2601 AUSTRALIA • Contact: Manager Ship Inspection Group • Phone: +61 2 6279 5048 • Fax: +61 2 6279 5058 • Email: psc@amsa.gov.au

1	name of reporting authority	Australia	2	name of ship	SUNN	Y LIGER			
3	flag of ship	Marshall Islands	4	type of ship	oil tan	ker	5	call sign	V7A4949
5(b)	MMSI	538009607	6	IMO number	IMO 9	332626	7	gross tonnage	42893
8	deadweight (t)	74997	9	date keel laid	02.02	.2008	10	date of inspection	14.05.2024
11	place of inspection	Sydney, NSW, Australia	12	classification	society	American Bure	au (of Shipping (ABS)	
13	date of release from detention	14.05.2024 08:30							
14	IMO company number	5562457	14((b) particulars of country of re	company gistration	Scorpio Marine India	: M	anagement (india)	Private Limited

name and signature of master to certify that the information under 14 is correct

Cptn. GREGORIS DIAS

signature

I acknowledge the obligations on the master or owner under SOLAS chapter I regulation 11(c)

16 details of ship certificates at last intermediate or annual survey

title	issuing authority	issue date	expiry date	survey date	survey authority	survey place
Cargo Ship Safety Construction	American Bureau of Shipping (ABS)	14.12.2023	13.11.2028			
Cargo Ship Safety Equipment	American Bureau of Shipping (ABS)	14.12.2023	13.11.2028			
Cargo Ship Safety Radio	American Bureau of Shipping (ABS)	14.12.2023	13.11.2028			
International Air Pollution Prevention	American Bureau of Shipping (ABS)	14.12.2023	13.11.2028			
International Anti-Fouling System	American Bureau of Shipping (ABS)	14.12.2023				
International Ballast Water Management	American Bureau of Shipping (ABS)	24.12.2023	13.11.2028			
International Energy Efficiency	American Bureau of Shipping (ABS)	25,01,2024				
International Oil Pollution Prevention	American Bureau of Shipping (ABS)	14.12.2023	13.11.2028			
International Sewage Pollution Prevention	American Bureau of Shipping (ABS)	14,12,2023	13.11.2028			
International Ship Security	American Bureau of Shipping (ABS)	01.06,2022	31.05.2027			
Load Line	American Bureau of Shipping (ABS)	14.12.2023	13.11.2028			
Tonnage	American Bureau of Shipping (ABS)	25,10,2021				
Document of Compliance (DoC/ISM Code)	American Bureau of Shipping (ABS)	25,11,2022	28.01.2028	22,11,2023	American Bureau of Shipping (ABS)	MUMBAI
Safety Management Certificate (SMC/ISM Code)	American Bureau of Shipping (ABS)	01.06.2022	31,05,2027			
Civil Liability for Oil Pollution Damage	Marshall Islands	15.02,2024	20.02.2025			
Maritime Labour	American Bureau of Shipping (ABS)	01.06.2022	31.05.2027			
Minimum Safe Manning Document	Marshall Islands	18,05,2023				

17 deficiencies **Yes** 18 ship detained **Yes** 19 supporting documentation **BNo** (see annex)

issuing office Sydney Office phone +61(2) 8918 1300 fa

name GOSLING, David (Mr)

(duly authorised PSCO of reporting authority)

signature



REPORT OF INSPECTION IN ACCORDANCE WITH IMO AND ILO PORT STATE CONTROL PROCEDURES

GPO Box 2181 CANBERRA ACT 2601 AUSTRALIA • Contact: Manager Ship Inspection Group • Phone: +61 2 6279 5048 • Fax: +61 2 6279 5058 • Email: psc@amsa.gov.au

r	name of repo	rting authority	Australia	2	name of ship	SUNNY LIGER		6 IMO	number IMO 93	32626
C	date of inspe	ction	14.05.2024	11	place of inspection	Sydney, NSW, A	ustralia			
	seq code	nature of def	iciency ¹⁾				convention	21 actio	on taken 22	responsible RO
1	1 07114 Remote control system for engine room quick closing valves defective. Valves cannot be closed from \$74-1/CII-2/R4.2 30 10 No outside the space.									
i	2 14108 No sampling through 15ppm monitor of discharge from oily water separator. 17 10									
-	3 02105 Insufficient reserve oil in the hydraulic steering gear reserve oil tank. 17 10									
	OUTST	ANDING I	DEFICIENCIES TO	BE REC	TIFIED					
te	20	seg code	nature of deficiency	1)			convention	21 actio	on taken 22	responsible RO

name GOSLING, David (Mr)

(duly authorised PSCO of reporting authority)

deficiency action codes					
10	deficiency rectified				
15	rectify deficiency at next port				
16	rectify deficiency within 14 days				
17	rectify deficiency before departure				
18	rectify deficiency within 3 months				
30	detainable deficiency				
99	other				

signatur

inspection action codes

☑Yes 55 flag State administration informed

☑Yes 150 coastal State informed

☑Yes 153 other authority informed

This inspection was not a full survey and deficiencies listed may not be exhaustive. In the event of a detention, it is recommended that full survey is carried out and all deficiencies are rectified before an application for re-inspection is made.