

FORM A

- Reporting Authority: Hull Marine Office (Beverley)

- Address: Crosskill House, Mill Lane, Beverley, Hull, HU17 9JB

- Telephone:

+44 (0) 20 3817 2018

- Email:

HullMO@mcga.gov.uk

- Website:

Name	STI MERAUX	IMO Number	9681118	Gross Tonnage	29838
Flag	Marshall Islands	MMSI Number	538005419	Old Tonnage	
Туре	Chemical tanker	Date Keel Laid/Major Conv.	21/11/2013	Main Engine (KW)	7240
Call Sign	V7DQ5	Deadweight	49990	Emission Abatement Method	Exhaust gas cleaning systems

Name	Scorpio Marine Management		IMO Company Number	5562457
Address		City	Country	India
MLC SHIPOWNER				
Name	Scorpio Marine Management			¥
Address		City	Country	India

^{*)} This inspection report has been issued solely for the purpose of informing the master and other port States that an inspection by the port State, mentioned in the heading, has taken place. This inspection report cannot be construed as a seaworthiness certificate in excess of the certificates the ship is required to carry.

^{**)} Masters, Shipowners and/or Operators are advised that detailed information on the inspection will be reported to the appropriate authorities and organisations and is subject to publication.

^{***) &}quot;Outstanding deficiencies" are listed for information only and will not be taken into account for the calculation of the Ship Risk Profile and Company performance.



Name Of Shi	ip	STI MERAUX	IMO Number	9681118	Date Of Report	02/11/2024	Place Of Inspection	Immingham
CHARTER	ER (only :	ships carrying liquid	or solid cargoes in bulk	, pref. 1st charterer record)				
Name		SCORPI	O MR POOL LTD					
Address				City		Country	Mona	aco
	Demise	Charter		∑ Time C	Charter		Voyage Charter	
Name and	signature	of master to confirm	the receipt of the inspe	ection report and to certify th	nat the information on charte	rer is correct:	M/T	
Name C P	APT.	MURADAL	I R. MAC	SRE	Signature	Dust	STI	
Classification	on Society	y(ies) responsible for	issuance of class cert	ificates			*/	
Issuing Entity	у	America	Bureau of Shipping	Date Of Issue	28/06/2024	Date Of Exp	iry 29/0	4/2029
Recognised	d Organiz	ation(s) responsible	or issuance of certifica	ites on behalf of the flag Sta	ite			
Issuing Entity	у	America	Bureau of Shipping					
INSPECTIO	ON PART	ICULARS **				STEERS OF STREET		
Date Of First			02/11/2024		Place Of Inspection		Immingham	
Date Of Repo	ort		02/11/2024		If detained: Date Of Is	ssue Of Detention No		
Type Of Ins	spection		The Later of the Later	edebatore years have			MARK TERROR	
	Initial Insp	pection	Mor	e Detailed Inspection	Expanded In	spection	⊠ cic	
Checked	Operation	onal Control (if any)	· ·	Additional Comment				
\boxtimes	Other		E	EDG Secondary Means of Starti	ing, Lifeboat Engines, Bilge Alar	ms		

^{*)} This inspection report has been issued solely for the purpose of informing the master and other port States that an inspection by the port State, mentioned in the heading, has taken place. This inspection report cannot be construed as a seaworthiness certificate in excess of the certificates the ship is required to carry.

^{**)} Masters, Shipowners and/or Operators are advised that detailed information on the inspection will be reported to the appropriate authorities and organisations and is subject to publication.

^{***) &}quot;Outstanding deficiencies" are listed for information only and will not be taken into account for the calculation of the Ship Risk Profile and Company performance.



Name Of Sh	ip	STI MERAUX	IMO Number		9681118	Date Of Report	02/11/2024	Place Of Inspection	Immingham
	Abandon sh	ip drill							
	Damage Co	ntrol drill							
	Enclosed sp	pace entry drill							
×	Emergency	steering drill							
	Fire drill								
	Man Over B	oard drill							
	Rescue Boa	t drill							
	SMPEP drill								
	SOPEP drill								
Checked	Areas Insp	octod		Additional 0	Commont				
⊠ ⊠		ation and galley	Markeyes	Additional	Somment				Harting College Co.
	Ballast tank								
		(s) - from manhole							
	Vehicle deck	K							
	Cargo area								
\boxtimes	Engine room	1							
\boxtimes	Navigation b	oridge							
\boxtimes	Decks and f	orecastle							
	Passenger s	spaces							

^{*)} This inspection report has been issued solely for the purpose of informing the master and other port States that an inspection by the port State, mentioned in the heading, has taken place. This inspection report cannot be construed as a seaworthiness certificate in excess of the certificates the ship is required to carry.

^{**)} Masters, Shipowners and/or Operators are advised that detailed information on the inspection will be reported to the appropriate authorities and organisations and is subject to publication.

^{***) &}quot;Outstanding deficiencies" are listed for information only and will not be taken into account for the calculation of the Ship Risk Profile and Company performance.





Name Of Sh	nip	STI MERAUX	IMO Number	9681118	Date Of Report	02/11/2024	Place Of Inspection	Immingham
\boxtimes	Steering	-room						

		Nach 6 上生 1970年	HUN THE THE S	Information of	on last intermediate, periodica	l or annual
Title Certificate	Issuing Authority	Date Of Issue	Date Of Expiry	Date Of Survey	Surveying Authority	Country
Bunker Oil Pollution Damage	Marshall Islands	12/02/2024	20/02/2025			
Cargo Ship Safety Construction	ABS	28/06/2024	29/04/2029			
Cargo Ship Safety Equipment	ABS	28/06/2024	29/04/2029			
Cargo Ship Safety Radio	ABS	02/04/2024	29/04/2029			
Civil Liability for Oil Pollution Damage	Marshall Islands	12/02/2024	20/02/2025			
Continuous Synopsis Record[5]	Marshall Islands	27/12/2022				
Dangerous Chemicals in Bulk (ICoF/IBC Code)	ABS	28/04/2024	29/04/2029			
Document of Compliance	ABS	25/11/2022	28/01/2028	22/11/2023	ABS	India
Engine International Air Pollution Prevention	ABS	15/01/2014				
International Air Pollution Prevention	ABS	28/06/2024	29/04/2029			
International Anti-Fouling System	ABS	28/06/2024				
International Ballast Water Management	ABS	28/06/2024	29/04/2029			
International Energy Efficiency Certificate	ABS	28/05/2023				
International Oil Pollution Prevention (IOPP)	ABS	28/06/2024	29/04/2029			

^{*)} This inspection report has been issued solely for the purpose of informing the master and other port States that an inspection by the port State, mentioned in the heading, has taken place. This inspection report cannot be construed as a seaworthiness certificate in excess of the certificates the ship is required to carry.

^{**)} Masters, Shipowners and/or Operators are advised that detailed information on the inspection will be reported to the appropriate authorities and organisations and is subject to publication.

^{****) &}quot;Outstanding deficiencies" are listed for information only and will not be taken into account for the calculation of the Ship Risk Profile and Company performance.

Name Of Ship	STI MERAUX	IMO Number	9681118	Date Of Report	02/11/2024	Place Of Inspection	Immingham
International Sev	wage Pollution Prevention	ABS	02/04/2024	29/04/2029			
Internation	onal Ship Security	ABS	09/09/2024	08/10/2029			
	Load Line	ABS	28/06/2024	29/04/2029			
Maritime	Labour Certificate	ABS	04/09/2024	08/10/2029			
Minimum Sai	fe Manning Document	Marshall Islands	27/03/2023				
Nairobi International	Convention on the Removal of Wrecks	Marshall Islands	12/02/2024	20/02/2025			
Safety Mar	nagement Certificate	ABS	04/09/2024	08/10/2029			
	Tonnage	ABS	05/10/2021				

INSPECTION	ON ACTIONS	
Checked	Ship related inspection action taken (if any)	Additional Comment
	Inspection suspended	
	Dismissed on AFS grounds	
	Excluded on AFS grounds	
	Vessel expelled on other grounds	
	Vessel expelled on security grounds	
	Marpol investigation of contravention of discharge provision	
Checked	Ship related reporting action taken (if any)	Additional Comment
	Coastal State informed	
	ILO informed	

^{*)} This inspection report has been issued solely for the purpose of informing the master and other port States that an inspection by the port State, mentioned in the heading, has taken place. This inspection report cannot be construed as a seaworthiness certificate in excess of the certificates the ship is required to carry.

^{**)} Masters, Shipowners and/or Operators are advised that detailed information on the inspection will be reported to the appropriate authorities and organisations and is subject to publication.

^{***) &}quot;Outstanding deficiencies" are listed for information only and will not be taken into account for the calculation of the Ship Risk Profile and Company performance.



Name Of Sh	ip	STI MERAUX	IMO Number		9681118	Date Of Report	02/11/2024	Place Of Inspection	Immingham		
	Other author	rity informed									
×	Observation	s to inspection		OCM develo	OCM developed fault when tested during inspection and was replaced with a spare, allowing for proper test. The DMLC part 2 was endorsed by A top of a previous endorsement, which could be misleading and should be corrected.						
	Shipowner a	and seafarer organization info	ormed								
	Flag State requested to submit action plan within deadline										
	Next port info	ormed									
	Flag State in	nformed									
	RO informed	1									
		YARENIANE PENERATA	ant ve								
DEFICIENC	CIES			no		yes (see attached FORM B)					
OUTSTANDING DEFICIENCIES***				no		yes (see attached FORM B)					
SUPPORTING DOCUMENTATION				no		yes (see annex)					

^{*)} This inspection report has been issued solely for the purpose of informing the master and other port States that an inspection by the port State, mentioned in the heading, has taken place. This inspection report cannot be construed as a seaworthiness certificate in excess of the certificates the ship is required to carry.

^{**)} Masters, Shipowners and/or Operators are advised that detailed information on the inspection will be reported to the appropriate authorities and organisations and is subject to publication.

^{***) &}quot;Outstanding deficiencies" are listed for information only and will not be taken into account for the calculation of the Ship Risk Profile and Company performance.



FORM A

Name Of Ship	STI MERAUX	IMO Number	9681118	Date Of Report	02/11/2024	Place Of Inspection	Immingham	
PORT STATE PAR	TICULARS		VERNEN PROPERTY					
Head Office/District O	ffice	ull Marine Office (Beverley)		Telephone	+44 (0)	20 3817 2018		
			aday Ibili IIIIA70ID	Email	HullMO	HullMO@mcga.gov.uk		
Address	C	rosskill House, Mill Lane, Bev	eriey, Hull, HU17 9JB	Website				
Name(s) of du	ly authorized PSCO(s) of reporting authority		Signature		Visit Date		
	Trevor Hughes		1.5	INCA IMB		02/11/2024		

This report must be retained on board for a period of at least three years and must be readily available for consultation by Port State Control Officers at all times.

^{*)} This inspection report has been issued solely for the purpose of informing the master and other port States that an inspection by the port State, mentioned in the heading, has taken place. This inspection report cannot be construed as a seaworthiness certificate in excess of the certificates the ship is required to carry.

^{**)} Masters, Shipowners and/or Operators are advised that detailed information on the inspection will be reported to the appropriate authorities and organisations and is subject to publication.

^{***) &}quot;Outstanding deficiencies" are listed for information only and will not be taken into account for the calculation of the Ship Risk Profile and Company performance.



FORM B

Nan	ne Of Ship	STIMERA	UX IMO	Number	9681118	Date Of F	Report	02/11/2024		Place Of	nspection	Immingham
DE	FICIENCI	ES FOUND AND FOL	LOW UP ACTIONS									
Nr.	Code	Defective Item	Nature Of Defect*	Convention Reference	Action Taken	Due Date	Ground For Detention	Accidental Damage**	RO resp.	ISM Related	Addi	tional Comments
1	10109	Lights, shapes, sound-signals	Not as required	COLREG - COLREG*** / Annex	10 - Rectified							ns speckled with paint, obstruction of the light.
2	18408	Electrical	Not as required	MLC 2006 Title 4 - MLC 2006 / The Regulations and the Code / Standard A4							earth bonding deck around a forecastle. The motor was not electrician's st stowage of ca	ound with missing/broken in several locations on main commodation and at a Starboard Lifeboat Davit earthed. Additionally, the ore found with excessive raboard boxes around and ck of the main switchboard ibution.
3	18312	Galley, handlingroom (maintenance)	Not as required	MLC 2006 Title 3 - MLC 2006 / The Regulations and the Code / Standard A3.	Law III	5					I Charles and the second	ash sink found with hot ected and diverted to a
	Name(s) of duly authorized PS0	CO(s) of reporting auth	ority		Signature					Visit Date	
30.00		Trevor Hu	ghes				MIENGES WAS			Siesyle Well	02/11/2024	

^{*)} This inspection was not a full survey and deficiencies listed may not be exhaustive. In the event of a detention, it is recommended that a full survey is carried out. All deficiencies should be rectified before an application for reinspection is made.

^{**)} Deficiencies marked as Accidental Damage are not taken into account for calculating the company performance and Ship Risk Profile.





FORM B

Nar	ne Of Ship	STI MERAUX	IMO Number	9681118	Date Of Report	02/11/2024		Place Of	Inspection	Immingham
OU	TSTANDI	NG DEFICIENCIES FOUN	D							
Nr.	Code	Defective Item	Nature Of Defect*	Convention Reference	Inspection	Rectified	RO resp.	ISM Related	Add	itional Comments
1	01310	Signs, indications	Not as required	SOLAS ch. III - SOLAS 1996-1998 Amend / Chapter III / Reg. 9	2022-07-03 - United Kingdom, Fawley				observed that is launching procured were posted.	he inspection, it was ncorrect signage for the edures for the port lifeboat D Signage not holding their parge.
2	18499	Other (Health protection, medical care)	Other	MLC 2006 Title 4 - MLC 2006 Title 4	2022-07-03 - United Kingdom, Fawley	⊠		×	At the time of the inspection, an unkn chemical was found within the Bosun' store within the accommodation area upper deck in a unlabelled open buck	
3	18305	Hospital accomodation (Sickbay)	Not as required	MLC 2006 Title 3 - MLC 2006 / The Regulations and the Code / Regulation 3.1	2022-07-03 - United Kingdom, Fawley	\boxtimes			and the second s	he inspection the flush on the hospital was unable to be
4	18315	Provisions quality and nutritional value	Rotten	MLC 2006 Title 3 - MLC 2006 / The Regulations and the Code / Regulation 3.2	2022-07-03 - United Kingdom, Fawley	×			vegetables were and vegetable At the time of the	ne inspection rotten re observed within the galley provision room. ne inspection the freezer pantry was found with food od in the base.
5	18326	Laundry, Adequate Locker	Not as required	MLC 2006 Title 3 - MLC 2006 / The Regulations and the Code / Standard A3.1	2022-07-03 - United Kingdom, Fawley	×		×	trunking from the	ne inspection the exhaust ne tumble dryers within the er laundrettes were not
6	11101	Lifeboats	Not ready for use	LSA Code - LSA 2011 Amend / CHAPTER IV / 4.4	2022-07-03 - United Kingdom, Fawley	⊠		×	observed that t	ne inspection it was he painter lines for the not properly rigged.

^{*)} This inspection was not a full survey and deficiencies listed may not be exhaustive. In the event of a detention, it is recommended that a full survey is carried out. All deficiencies should be rectified before an application for reinspection is made.



FORM B

Name Of Ship		STI MERAUX	IMO Number	9681118	Date Of Report	02/11/2024		Place Of Inspection		Immingham
Nr.	Code	Defective Item	Nature Of Defect*	Convention Reference	Inspection	Rectified	RO resp.	ISM Related	Additional Comments	
7	14108	15 PPM Alarm arrangmts.	Not as required	MARPOL Annex I - MARPOL 2015 Amend / Annex I / Reg. 14	2022-07-03 - United Kingdom, Fawley	×			At the time of the inspection homemade modifications were observed to have been made to the discharge side of the Rivertrace alarm unit, resulting in extended length of unsupported copper pipework and hoses	
8	05114	Reserve source of energy	Not as required	SOLAS ch. IV - SOLAS ch. IV reg 13.2	2022-07-03 - United Kingdom, Fawley				At the time of the inspection the batteries within the battery locker for the GMDSS equipment were not stowed as required.	
9	13101	Propulsion main engine	Not as required	SOLAS ch. II-1 Parts C, D, E, F - SOLAS 1981 Amend / Chapter II-1 / Reg. 27	2022-07-03 - United Kingdom, Fawley	×			At the time of the inspection, the main engine was observed to be leaking jacket cooling water in area the area of the cylinder heads. Master instructed to discuss with class and agree rectification plan.	
10	15150	ISM	Not as required	ISM Code - SOLAS 1999/2000 Amend / Chapter IX / Reg. 3	2022-07-03 - United Kingdom, Fawley				by the Compa months. Defic objective evic effectiveness ISM Code. The	tion taken on the ISM system any is required within 3 ciencies marked ISM are dence of a failure, or lack of , of the implementation of the ne ship will be eligible for after 3 months from the final port.
	Name(s	s) of duly authorized PSCO(s)	of reporting authority		Signature				Visit Date	
Trevor Hughes				1 286 Manure S.			02/11/2024			

^{*)} This inspection was not a full survey and deficiencies listed may not be exhaustive. In the event of a detention, it is recommended that a full survey is carried out. All deficiencies should be rectified before an application for reinspection is made.