

A32NX

BEFORE	START
COCKPIT PREP	COMPLETED (BOTH)
GEAR PINS and COVER	S REMOVED
SIGNS	ON/AUTO
ADIRS	NAV
FUEL QUANTITY	KG.LB
TO DATA	SET
BARO REF	SET (BOTH)
WINDOWS/DOORS	CLOSED (BOTH)
BEACON	ON
THR LEVERS	IDLE
PARKING BRAKE	AS RQRD

AFTER STAI	RT
ANTI ICE	AS RQRD
ECAM STATUS	CHECKED
PITCH TRIM	% SET
RUDDER TRIM	

BEFORE TAKEOFF
FLIGHT CONTROLS CHECKED (BOTH)
FLT INST CHECKED (BOTH)
BRIEFINGCONFIRMED
FLAP SETTING CONF (BOTH)
V1, VR, V2/FLX TEMP(BOTH)
ATC SET
ECAM MEMO TO NO BLUE
- AUTO BRK MAX
- SIGNS ON
- CABIN READY
- SPLRS ARM
- FLAPS TO
- TO CONFIRM NORM
TAKEOFF RWY CONFIRMED (BOTH)
CABIN CREW ADVISED
TCAS TA OR TA/RA
ENG MODE SEL AS RQRD
PACKS AS RQRD

AFTER TAKEOFF/CLIMB	
LDG GEAR	. UP
FLAPSRETRAC	TED
PACKS	ON
BARO REF SET (BC	

APPROACI	Н
BRIEFING	CONFIRMED
ECAM STATUS	CHECKED
SEAT BELTS	ON
BARO REF	SET (BOTH)
MINIMUM	SET (BOTH)
ENG MODE SEL	

LANDING	
CABIN CREW	ADVISED
A/THR	
AUTOBRAKE	AS RQRD
ECAM MEMO	. LDG NO BLUE
- LDG GEAR DN	
- SIGNS ON	
 CABIN READY 	
- SPLRS ARM	

AFTER LANDING
FLAPS RETRACTED
SPOILERSDISARMED
APUSTART
RADAROFF
PREDICTIVE WINDSHEAR SYSTEMOFF

FLAPS SET

PARKING
APU BLEEDON
ENGINESOFF
SEAT BELTSOFF
EXT LT AS RQRD
FUEL PUMPSOFF
PARK BRK and CHOCKS AS RQRD
Consider HEAVY REAIN

SECURING THE AIRCRAFT
ADIRSOFF
OXYGENOFF
APU BLEEDOFF
EMER EXIT LTOFF
SIGNSOFF
APU AND BATOFF
Consider COLD WEATHER

