



on the side of

the rack. 6.85

A.Amp.Sig

A.Dummy.Sig

3/2/97 Added 4.7K resistor in series with DASH input. Doesn't work without it and current through diodes when DASH positive could be catastrophic!



