FLYSKY

Release Notes for FS-ST16 Transmitter Software/FS-ST16 软件版本更新记录

Software Version 软件版本	1.0.25	Date 日期	05/2026

新增功能 :

- 无

修改功能 :

1. 修复假性微调相关问题。
2. 适配 WEB 端遥控管家使用。

特殊变化 :

- 无

注意事项

- 发射机固件更新完成后，模型数据会被复位。在固件更新之前，可通过遥控管家进行数据备份，然后导入该版本使用。
- 使用遥控管家备份数据时，须注意以下版本兼容性问题：3.3.5 及以后版本不兼容 3.3.5 之前版本（即 3.0.4 及更早版本互相兼容，3.3.5、4.0.1 及以后版本互相兼容）。因此，导出或导入模型数据时，必须使用相互兼容版本的遥控管家进行操作。
- 发射机固件更新完成后，需完成摇杆校准。
- 发射机和接收机更新完成后需要重新对码。

New functions:

- None

Modified functions:

1. Fixed issue where trim scale is displayed on the interface without the trim switch being moved.
2. Adapt for use with the web-based Flysky Assistant.

Special changes:

- None

Notes

1. In case of updating the firmware, it is recommended to back up the model data via FlySkyAssistant. And after the firmware has been upgroaded, then import the backup model data to the new firmware.
2. When using FlySkyAssistant to back up data, observe the following version-compatibility rules.
   - 3.3.5 and later are incompatible with any release before 3.3.5.
   - 3.0.4 and earlier are mutually compatible.
   - 3.3.5, 4.0.1,and all later releases are mutually compatible.

   Therefore, export or import model data only with mutually compatible versions of FlySkyAssistant.
3. Done the **Stick Calibration** function after the transmitter firmware update is finished.
4. The transmitter and the receiver need to be rebound after the update is finished.

FLYSKY

Release Notes for FS-ST16 Transmitter Software/FS-ST16 软件版本更新记录

Software Version 软件版本	1.0.20	Date 日期	09/2025

新增功能：

1. [模型设置] 功能下新增 [设置为竞赛模式] 功能。通过它可快速关闭 [低信号报警] 功能和 [遥测丢失报警] 功能。
2. [接收机设置] 功能下新增 [高频设置] 功能。用来设置本机高频开启 / 关闭，以及外置高频的相关功能选择，如接收机接口协议、信号强度等设置。
3. [接收机设置] 功能下新增 [低信号报警] 功能。
   - 可设置报警声音；
   - 可设置报警值和报警重复周期；
   - 可以开启或关闭此功能。
4. [接收机设置] 功能下新增 [遥测报警] 功能。
   - 可设置遥测丢失时报警声音；
   - 可以设置报警灵敏度，避免短暂干扰导致丢失报警；
   - 可以开启或关闭此功能。
5. [接收机设置] 功能下的 [失控保护] 功能新增 [失控保护判断时间] 功能：可设置当前模型失控保护判断时间。
6. [系统设置] 功能下新增 [油门模式] 功能：可设置油门回中或者油门不回中。
7. [设置] 功能下新增 [电池电压] 功能：可校准发射机电池电压。
8. 外置 FRM303 高频头开启时，接收机设置中新增相关功能，如：
   - [对码设置] 中 [RF 系统] 功能中新增 5 种 RF 模式选项：Classic 18、C-Fast 10、Routin 18、Lora 12、Fast 8；
   - 新增 [接口协议] 功能，接口协议根据所选 RF 系统类型而变化；
   - 新增适配外置高频相关的 [失控保护] 功能项；
   - 新增 [响应速度] 功能，根据 RF 系统类型而变化；
   - 新增适配外置高频的 [i-BUS 设置] 相关功能；
   - 新增适配外置高频的 [低信号报警] 功能；
   - 新增适配外置高频的 [遥测报警] 功能；
   - 新增 [信号强度] 功能，即 [接收机设置] 下新增信号强度输出设置功能。

修改功能：

1. 计时器相关报警语音、振动由归属 [系统] 改为归属 [报警]。
2. 修复其他已知问题。

特殊变化：

- 无

注意事项

- 发射机固件更新完成后，模型数据会被复位。在固件更新之前，可通过遥控管家进行数据备份，然后导入该版本使用。
- 使用遥控管家备份数据时，须注意以下版本兼容性问题：3.3.5 及以后版本不兼容 3.3.5 之前版本（即 3.0.4 及更早版本互相兼容，3.3.5、4.0.1 及以后版本互相兼容）。因此，导出或导入模型数据时，必须使用相互兼容版本的遥控管家进行操作。

FLYSKY

Release Notes for FS-ST16 Transmitter Software/FS-ST16 软件版本更新记录

Software Version 软件版本	1.0.20	Date 日期	09/2025

注意事项

- 发射机固件更新完成后，需完成摇杆校准。
- 发射机和接收机更新完成后需要重新对码。

New functions:

1. Added a [Set Race Mode] feature within [Model Set]. Quickly disables both [Low Signal Alarm] and [Telemetry Alarm] functions.
2. Added a [RF Setup] feature within [RX Menu], used to enable/disable built-in RF module, or configure external RF module features including: RX Interface Protocol, Signal Strength, etc.
3. Added a [Low Signa] (Low Signal Alarm) feature within [RX Menu]:
   - Alarm sound can be set.
   - Alarm value and alarm repetition cycle can be set.
   - The function can be enabled or disabled.
4. Added a [TLM Loss] (Telemetry Alarm) feature within [RX Menu]:
   - Alarm sound can be set when telemetry is lost.
   - Alarm sensitivity can be set to avoid loss alarms due to briefinterference.
   - The function can be enabled or disabled.
5. Added a [Failsafe time setting] feature within [RX Menu] to configure model's failsafe trigger delay.
6. Added a [Thro mode] feature within [System Menu]: Set throttle to self-centering or non-self-centering.
7. Added a [Battery Voltage] feature within [Setup]: Calibrate the transmitter's battery voltage.
8. External FRM303 RF Module Features (when enabled):
   - Added 5 [RF System] mode options within [Bind Setup]: Classic 18, C-Fast 10, Routine 18, LoRa 12, and Fast 8.
   - Added a [Interface](Inteface Protocol) feature (dynamic options based on selected RF system).
   - Added a [Failsafe] parameters for external RF.
   - Added a [Frequency] feature (adjustable per RF system type).
   - Added an [i-BUS Set] feature for external RF compatibility.
   - Added a [Low Signa] (Low Signal Alarm) feature for external RF.
   - Added a [TLM Loss] (Telemetry loss Alarm) feature for external RF.
   - Added a [Signal Stre] (Signal Strength) feature, namely adding a signal strength output setting feature within the [RX Setup] menu.

Modified functions:

1. Timer-related voice alerts and vibration have been reassigned from [System] to [Alarm].
2. Fixed other known issues.

FLYSKY

Release Notes for FS-ST16 Transmitter Software/FS-ST16 软件版本更新记录

Software Version 软件版本	1.0.20	Date 日期	09/2025

Special changes:

- None

Notes

1. After the transmitter firmware update is finished, the model data will be reset. It is recommended to back up data through the **FlySkyAssistant**, and then import the data after the update is finished.
2. When using FlySkyAssistant to back up data, observe the following version-compatibility rules:
   - 3.3.5 and later are incompatible with any release before 3.3.5.
   - 3.0.4 and earlier are mutually compatible.
   - 3.3.5, 4.0.1, and all later releases are mutually compatible.

   Therefore, export or import model data only with mutually-compatible versions of FlySkyAssistant.
3. Done the **Stick Calibration** function after the transmitter firmware update is finished.
4. The transmitter and the receiver need to be rebound after the update is finished.

FLYSKY

Release Notes for FS-ST16 Transmitter Software/FS-ST16 软件版本更新记录

Software Version 软件版本	1.0.19	Date 日期	05/2025

新增功能：

- 无

修改功能：

1. 修复 BVD 电压显示异常问题。
2. 修复 USB 模拟器无法正常使用的问题。
3. 修复其他已知问题。

特殊变化：

- 无

注意事项

- 发射机固件更新完成后，模型数据会被复位。在固件更新之前，可通过遥控管家进行数据备份，然后导入该版本使用。
- 使用遥控管家备份数据时，需注意以下版本兼容性问题：遥控管家 3.0.4 版本和 3.3.5 版本目前互不兼容。因此，导出和导入模型数据时，必须使用相同版本的遥控管家进行操作。
- 发射机固件更新完成后，需完成摇杆校准。
- 发射机和接收机更新完成后需要重新对码。

New functions:

- None

Modified functions:

1. Fixed the issue of BVD voltage display.
2. Fixed the issue of the USB emulator not working properly.
3. Fixed other known issues.

Special changes:

- None

Notes

- After the transmitter firmware update is finished, the model data will be reset. It is recommended to back up data through the **FlySkyAssistant**, and then import the data after the update is finished.
- When using FlySkyAssistant to back up data, please note the following version compatibility issues: FlySkyAssistant versions 3.0.4 and 3.3.5 are currently incompatible with each other. Therefore, when exporting and importing model data, you must use the same version of FlySkyAssistant for the operation.
- Done the **Stick Calibration** function after the transmitter firmware update is finished.
- The transmitter and the receiver need to be rebound after the update is finished.