

Office Update

Generated: 2026-03-23 01:05

Job #	Customer	Progress	Inspection	Paperwork	Shop	Damage	Office Notes
26498280	RICHARD EVANKO	Supplement - Waiting For Paperwork	-	Yes	Lobalbo West Auto Body	Make:	3/11 MARY ANN OF LOBALBO WEST AUTO BODY CALLED IN A SUPPLEMENT. THE VEHICLE IS THERE. Appraisal Notes:
26498720	PAUL SPILLANE	Supplement - Waiting For Paperwork	-	Yes	BMW of Darien	Make:	3/20 - EMAIL FROM VINCENT AT BMW - SENT YOU WHAT TH EY SENT HERE./GF Appraisal Notes:
26498770	Mike Lafeve	Supplement - Waiting For Paperwork	-	Yes	MY WAY AUTO BODY	-	-
26498779	ELLIOTT & SHONA GOLDENBERG	Written - Under Review	03/21/26	No	-	Make:	OEM PARTS PACKAGE: Preferred 5 Year. ENDORSEMENTS: ASSURANCE PREFERRED PACKAGE Insured vehicle in accident at intersection controlled by stop sign - IV had S/S - I was in traffic near LGA airport NYC. Traffic was merging at the lights from three direction -LD Appraisal Notes:

26498861	TOWN OF NEW CANAAN	Appointment Scheduled	03/23/26	No	-	Make:	Car OV backed out of driveway into IV plowing./GF Appraisal Notes:
26498933	ERNEST WHITTLE	Supplement - Waiting For Paperwork	-	Yes	Darien Auto Body	Make:	CONFIREMD AT SHOP WITH BILL. HE ASKED FOR JL TO HANDLE AND WAS GOING TO CALL HIM.. NON DRIVABLE LEFT FRONT PILLAR LEFT DRIVER SIDE FRONT FENDER DAMAGED, STEERING PULLING TO THE LEFT, LEFT FRONT TIRE BLOWN OUT. POSSIBLE DAMAGE TO UNDERCARRIAGE. IV WAS TRAVELING HOME, BEGAN TO DRIVER AROUND CURB AND BC OF SUNSHINE, IV TIRE STRUCK SIDE OF ROAD, ONCE SIDE OF ROAD WAS STRUCK, IV STRUCK TREE AND WENT OVER BOLDER CAUSING DAMAGES TO IV-LD Appraisal Notes:
26498986	KATHERINE	No Contact Yet	-	No	-	Make:	LABEL PHOTOS

	MURALLES						AND NEED DATE STAMPED PHOTOS. NATURE OF LOSS NOT LISTED. SENT FEDERATED GUIDELINES TO FERNANDO AND SAVED IN APPTRAK -LD Appraisal Notes:
26498992	ALEXIS MUNOZ	No Contact Yet	-	No	-	Make:	Instructions to Estimator: Spanish Speaker Damages: Front drivers side headlight and bumper. Facts of Loss: IV struck the CV parked vehicle-LD Instructions to Estimator: Spanish Speaker Damages: Front drivers side headlight and bumper. Facts of Loss: IV struck the CV parked vehicle-LD Appraisal Notes: