

Field Biologist Site Inspection for Family Mart

FamilyMart Sura Gate	Dungun /	10 Jul	2025
----------------------	----------	--------	------

Complete

Document No.	000135
Audit Title	Post-Opening Site Inspection
Site Name	FamilyMart Sura Gate Dungun
Location	Lot 9940, Sura Gate Business Center, 23000 Kuala Dungun, Terengganu, Malaysia (4.7583533, 103.41745019999999)
Contractor Present	Yes
Name	Ho Kok Wai
Project PIC Present	Yes
Name	Yuziir
Inspected by	
Arif Zulrushdi	
Inspection Date	10.07.2025
Prepared by	Arif Zulrushdi

Disclaimer

The assessors believe the information contained within this inspection report to be correct at the time of printing. The assessors do not accept responsibility for any consequences arising from the use of the information herein. The report is based on matters which were observed or came to the attention of the assessors during the day of the inspection and should not be relied upon as an exhaustive record of all possible risks or hazards that may exist or potential improvements that can be made.

Introduction

Our inspections are based on Integrated Pest Management (IPM) principles. Where pests are concerned we believe prevention is better than cure.

IPM achieves best results when we are able to work in partnership with our clients in order to minimise conditions that are, or could be conducive to pest activity.

Conditions observed during the inspection and consequent remedial actions needed are categorised as follows:

- Environmental/habitat management externally to minimize potential pest harborage and/or any other attraction for pests (eg food source).
- Proofing of buildings to reduce the risk of pest ingress
- Stacking of stored items to minimize the potential for pest harborage and to allow access for inspection and cleaning
- Housekeeping to minimize potential sources of food and harborage for pests.

Recommendations are allocated Red - Yellow - Green status as follows:

Red

High priority is the urgency to implement recommendation given. Negligence of recommendation may contribute to pest outbreak or re-occurrence of pest infestation.

Yellow

Medium priority is the action to be considered. Conditions attractive to pests. The action required to be accomplished.

Green

Low priority is the preventive action to be taken. If neglected, conditions may become attractive to pests.

Instructions for Inspection Report

$\begin{tabular}{l} \hline \end{tabular}$ FB to check all area in the premise for potential entry points and potential harbourage areas in the premise.
Proposition in the second second in the second in the second second second in the second seco
To ensure findings on pre-inspection to be remained on post-inspection with remark with current proofing condition (whether it's done or not up to satisfaction).
Please send all pest related reports to fm-pestgroup@ql.com.my and CC to NKAM and servicing branch personnel.

Inspection Checklist for External Area

To identify any potential entry points and harbourage area from external perimeter.

Inspection Checklist for Entrance

To identify any potential entry points and harbourage area at front door and its perimeter.

Inspection Checklist for Front Ceiling

To identify any potential entry points and harbourage area from overhead trunking connected to external perimeter.

Inspection Checklist for Counter

To identify any potential entry points and harbourage area at counter area and its surrounding area.

Sink

- Piping gaps Floor trap
- Grease trap
- Crevices along sink structures

Findings

Updates on 10.7.2025:

Proofing done for floor drain traps.



Photo 1

Inspection Checklist for Sales Floor

To identify any potential entry points and harbourage area at sales floor, seating/dining area, waste bins, chillers, etc.

Chillers; Reach-in-chiller/ Open-case-chiller

- Compressor conduits Drain trap/piping

Findings

Updates on 10.7.2025:

Proofing done for floor pipe.



Photo 2

Inspection Checklist for Sales Floor Ceiling

To identify any potential entry points and harbourage area from overhead trunking connecting between internal areas/external.

Inspection Checklist for Back Room

To identify any potential entry points and harbourage area at storage area, manager area, back entrance.

Manager Area

- Wiring holes/trunking/ducting
- Server rack
- Plug points

Observation






Photo 3

Photo 4

Remarks: Potential Pests

Ants	Cockroach	Termites
------	-----------	----------

Findings

Gaps observed between desk and wall may provide hiding spots for pests.

Recommendation

Please close the gaps.

Updates on 10.7.2025:

1: DONE




Photo 5

Inspection Checklist for Back Room Ceiling

To identify any potential entry points and harbourage area from overhead trunking connected to external perimeter.

Ducting/trunking

- DB box/panel AC conduits

Observation





Photo 6

Remarks: Potential Pests

Rats	Cockroach	Termites
		Ants

Findings

1. No casing installed yet on wiring chase.

Recommendation

1. Please install the casing after installation was done and make sure no gaps left between the ceiling and chase.

Updates on 10.7.2025:

2: DONE




Photo 8

Inspection Checklist for Toilet

To identify any potential entry points and harbourage area for outlet with in-house toilet.

Inspection Checklist for Monitoring Units

To verify and recommend location for monitoring trap(s) at site.

Insect Light Traps

Post-Opening Inspection

Summary

Summary

Overall Remarks

The outlet is ready for opening.

Above are the recommendations provided to your site based on our inspection at the current moment. Please act on the recommendations for better control of pest activity in the premise. Together with our planned pest control programme, we believe the level of pest infestation will be reduced further.

Thank you for selecting Rentokil Initial as your Pest Control service provider.

Do contact us if there's a need for further clarification.

Inspector's Signature



Arif Zulrushdi 10.07.2025 13:34 +08

Media summary



Photo 1




Photo 2



Photo 3




Photo 4




Photo 5



Photo 6




Photo 7




Photo 8