

FamilyMart

Pest Inspection Report

Post-Inspection Report / MFM0077 Cheras Mahkota / 24 Jul 2025

Complete

Inspection	Post-Inspection Report
Store ID and Name	MFM0077 Cheras Mahkota
Tracker	Other pest
Inspector	Huda
Project Team PIC	Faiz
Project Team Present	Yes
Contractor PIC	Sam
Contractor Present	Yes
Issue Date	24.07.2025
Inspection Date	24.07.2025
Report Date	24.07.2025
Handover Date	24.07.2025

Findings

Findings #1

Location

Kitchen Area - TV

Observations



Photo 1



Photo 2



Photo 3

Findings

TV pole connected to the ceiling
noted with gaps

Recommendation

Kindly assist to seal

Status

Done



Photo 4



Photo 5

Findings #2

Location

Kitchen Area - Under coffee machine

Observations



Photo 6



Photo 7

Findings

Piping noted with gaps

Recommendation

Kindly assist to seal

Status

Pending



Photo 8



Photo 9

Findings #3

Location

Kitchen Area - Cabinet

Observations



Photo 10



Photo 11

Findings

Piping connected to the floor noted with gaps

Recommendation

Kindly assist to seal

Status

Pending



Photo 12




Photo 13

Findings #4

Location

Kitchen Area - Cabinet

Observations




Photo 14



Photo 15

Findings

Cabinet noted with uneven base

Recommendation

Kindly assist to seal

Status

Pending




Photo 16



Photo 17

Findings #5

Location

Kitchen Area - Cabinet

Observations



Photo 18



Photo 19



Photo 20

Findings

Cabinet noted with gaps

Recommendation

Kindly assist to seal

Status

Pending



Photo 21



Photo 22



Photo 23

Findings #6

Location

Kitchen Area - Cabinet

Observations



Photo 24



Photo 25

Findings

Drawers noted damaged

Recommendation

Kindly assist to replace new

Status

Done



Photo 26



Photo 27

Findings #7**Location**

Kitchen Area - Plug Point

Observations

Photo 28



Photo 29



Photo 30

Findings

Plug point detached and noted with gaps

Recommendation

Kindly assist to seal

Status

Done



Photo 31



Photo 32



Photo 33

Findings #8**Location**

Kitchen Area - Floor tiles

Observations

Photo 34



Photo 35

Findings

Floor tiles noted cracked with hole

Recommendation

Kindly assist to seal

Status

Done



Photo 36



Photo 37

Findings #9

Location

Selling floor - Underneath reach in chiller

Observations



Photo 38



Photo 39



Photo 40



Photo 41

Findings

Piping connected to the floor noted with gaps

Recommendation

Kindly assist to seal

Status

Pending



Photo 42



Photo 43



Photo 44



Photo 45

Findings #10

Location

Selling floor - Cabinet

Observations



Photo 46



Photo 47



Photo 48

Findings

Bottom cabinet noted with gaps

Recommendation

Kindly assist to seal

Status

Pending



Photo 49




Photo 50



Photo 51

Findings #11

Location

Selling floor - Underneath OCC

Observations



Photo 52



Photo 53



Photo 54



Photo 55

Findings

Piping connected to the floor
noted with gaps

Recommendation

Kindly assist to seal

Status

Done



Photo 56



Photo 57



Photo 58




Photo 59

Findings #12

Location

Selling floor - Walls

Observations




Photo 60



Photo 61

Findings

Metal panel for walls noted
detached

Recommendation

Kindly assist to patch up

Status

Done



Photo 62



Photo 63

Findings #13

Location

Customer toilet

Observations



Photo 64



Photo 65

Findings

Floor drain noted without strainer

Recommendation

Kindly replace floor drain with a strainer

Status

Pending



Photo 66



Photo 67

Findings #14

Location

Customer toilet

Observations



Photo 68



Photo 69



Photo 70



Photo 71



Photo 72

Findings

Piping connected to the walls noted with gaps

Recommendation

Kindly assist to seal

Status

Pending



Photo 73



Photo 74




Photo 75



Photo 76



Photo 77



Photo 78

Findings #15

Location

Backroom Area

Observations



Photo 79




Photo 80



Photo 81

Findings

Backroom door walls noted deteriorate

Recommendation

Kindly assist to patch up

Status

Done




Photo 82



Photo 83

Findings #16

Location

Backroom Area

Observations




Photo 84



Photo 85



Photo 86

Findings

Orange trucking connected to the fuse box noted with gaps

Recommendation

Kindly assist to seal

Status

Done



Photo 87



Photo 88

Findings #17

Location

Backroom Area

Observations



Photo 89



Photo 90



Photo 91

Findings

Wire case connected to the ceiling noted with gaps

Recommendation

Kindly assist to seal

Status

Pending



Photo 92



Photo 93



Photo 94

Findings #18

Location

Backroom Area - Near backdoor

Observations



Photo 95




Photo 96

Findings

Wiring connected to the ceiling noted with gaps

Recommendation

Kindly assist to seal

Status

Done



Photo 97



Photo 98

Findings #19

Location

Backroom Area - Server box

Observations




Photo 99



Photo 100



Photo 101

Findings

Internet wiring connected to the server box noted with gaps

Recommendation

Kindly assist to seal

Status

Pending



Photo 102



Photo 103



Photo 104

Findings #20

Location

Backroom - Manager desk

Observations



Photo 105



Photo 106



Photo 107

Findings

Plug point noted with gaps

Recommendation

Kindly assist to seal

Status

Pending



Photo 108



Photo 109



Photo 110

Findings #21**Location**

Backroom Area - Manager desk

Observations

Photo 111



Photo 112



Photo 113

Findings

Walls behind manager desk noted with gaps

Recommendation

Kindly assist to patch up

Status

Pending



Photo 114



Photo 115

Findings #22**Location**

Selling floor - Entrance door

Observations

Photo 116



Photo 117



Photo 118



Photo 119

Findings

Entrance door noted with gaps

Recommendation

Kindly assist to seal

Status

Done



Photo 120



Photo 121



Photo 122



Photo 123

Findings #23

Location

Backdoor

Observations



Photo 124




Photo 125



Photo 126

Findings

Backdoor noted with gaps

Recommendation

Kindly assist to seal

Status

Done



Photo 127



Photo 128



Photo 129

Findings #24

Location

Above ceiling - Main entrance door

Observations



Photo 130



Photo 131




Photo 132

Findings

Wall facing main entrance noted with gaps

Recommendation

Kindly assist to seal

Status

Pending



Photo 133



Photo 134

Findings #25

Location

Selling floor - above ceiling

Observations




Photo 135




Photo 136




Photo 137

Findings

Piping connected to the ceiling noted with gaps

Recommendation

Kindly assist to seal

Status

Pending



Photo 138




Photo 139



Photo 140




Photo 141

Findings #26

Location

Backroom - above ceiling

Observations



Photo 142



Photo 143

Findings

Pipe connected to the ceiling noted with gaps

Recommendation

Kindly assist to seal

Status

Pending



Photo 144




Photo 145

Findings #27

Location

Backroom Area - Floor

Observations



Photo 146



Photo 147

Findings

In between wall and floor noted with gaps

Recommendation

Kindly assist to seal

Status

Done



Photo 148



Photo 149

Findings #28

Location

Backroom - Walls

Observations



Photo 150



Photo 151

Findings

Walls noted deteriorate

Recommendation

Kindly assist to patch up

Status

Done



Photo 152



Photo 153

Findings #29

Location

Backroom - Walls

Observations



Photo 154



Photo 155



Photo 156

Findings

Wiring connected to the wall noted with gaps

Recommendation

Kindly assist to seal

Status

Pending



Photo 157




Photo 158



Photo 159

Findings #30

Location

Kitchen Area - Wiring

Observations



Photo 160



Photo 161

Findings

Wiring casing noted with gaps

Recommendation

Kindly assist to seal

Status

New Findings

Findings #31

Location

Kitchen Area - Ventilation hood

Observations



Photo 162



Photo 163




Photo 164

Findings

Yet to install LED lights and noted with holes

Recommendation

Kindly assist to install

Status

New Findings

Findings #32

Location

Selling floor - Plug point

Observations




Photo 165



Photo 166



Photo 167

Findings

Plug point noted with gaps

Recommendation

Kindly assist to seal

Status

New Findings

Findings #33

Location

Selling floor - LED lights

Observations



Photo 168



Photo 169

Findings

LED lights connected to the walls noted with holes

Recommendation

Kindly assist to seal

Status

New Findings

Findings #34

Location

Backroom Area - Above ceiling

Observations



Photo 170



Photo 171

Findings

Copper piping connected to the wall noted with gaps

Recommendation

Kindly assist to seal

Status

New Findings

Findings #35

Location

Kitchen Area - Wiring at cabinet area

Observations



Photo 172



Photo 173

Findings

Wiring connected into the cabinet noted with holes

Recommendation

Kindly assist to seal

Status

New Findings

Findings #36

Location

Kitchen Area - TV area

Observations



Photo 174



Photo 175



Photo 176

Findings

Internet wiring connected to the walls noted with gaps

Recommendation

Kindly assist to seal

Status

New Findings

Media summary



Photo 1




Photo 2



Photo 3



Photo 4



Photo 5




Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21




Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32



Photo 33



Photo 34




Photo 35



Photo 36



Photo 37



Photo 38



Photo 39



Photo 40



Photo 41



Photo 42



Photo 43



Photo 44



Photo 45



Photo 46



Photo 47




Photo 48



Photo 49




Photo 50



Photo 51



Photo 52



Photo 53



Photo 54



Photo 55



Photo 56



Photo 57



Photo 58



Photo 59



Photo 60



Photo 61



Photo 62



Photo 63




Photo 64




Photo 65



Photo 66



Photo 67



Photo 68



Photo 69



Photo 70




Photo 71



Photo 72



Photo 73



Photo 74




Photo 75



Photo 76



Photo 77



Photo 78



Photo 79



Photo 80



Photo 81



Photo 82



Photo 83



Photo 84



Photo 85



Photo 86



Photo 87



Photo 88




Photo 89



Photo 90



Photo 91



Photo 92



Photo 93



Photo 94



Photo 95



Photo 96



Photo 97




Photo 98



Photo 99



Photo 100



Photo 101



Photo 102




Photo 103



Photo 104




Photo 105



Photo 106



Photo 107




Photo 108



Photo 109




Photo 110



Photo 111



Photo 112



Photo 113



Photo 114



Photo 115



Photo 116




Photo 117



Photo 118




Photo 119



Photo 120



Photo 121



Photo 122



Photo 123



Photo 124



Photo 125



Photo 126



Photo 127



Photo 128



Photo 129



Photo 130



Photo 131



Photo 132



Photo 133



Photo 134



Photo 135



Photo 136




Photo 137



Photo 138



Photo 139




Photo 140




Photo 141




Photo 142



Photo 143



Photo 144



Photo 145



Photo 146



Photo 147



Photo 148



Photo 149



Photo 150



Photo 151



Photo 152



Photo 153




Photo 154




Photo 155



Photo 156



Photo 157



Photo 158



Photo 159




Photo 160



Photo 161



Photo 162



Photo 163




Photo 164




Photo 165



Photo 166



Photo 167



Photo 168



Photo 169



Photo 170



Photo 171



Photo 172



Photo 173



Photo 174



Photo 175




Photo 176