



# **Pest Inspection Report (Entopest)**

Post-Inspection Report / MFM0519 FamilyMart Alam Avenue / 29 Jul 2025

Complete

Score	0 / 0 (0%)	Flagged items	1	Actions	0
Inspection				Post-Inspection Report	
Store ID and Name				MFM0519 FamilyMart Alam Avenue	
Tracker				Other pest	
Inspector				Aina	
Project Team PIC				Ken	
Project Team Present				Yes	
Contractor PIC				Sam	
Contractor Present				Yes	
Inspection Date				29.07.2025	
Report Date				29.07.2025	
Handover Date				29.07.2025	



# Flagged items 1 flagged

Findings / Findings #2

## Status





Photo 8

Photo 9

Private & confidential 2/46



**Findings** 1 flagged

Findings #1

Location Front Area

#### **Observations**





Photo 1

Photo 2

**Findings** Ceiling opening observed

### Recommendation

Kindly completely close the ceiling

### **Status**



Photo 3

Findings #2 1 flagged

Location Front area (glass door)

### **Observations**









Photo 5

Photo 6

Door gaps were observed **Findings** 

### Recommendation

Advice to install door sealants

### **Status**





Photo 8

Photo 9



## Findings #3

**Location** Selling floor

## **Observations**





Photo 10

Photo 11

## **Findings**

Small gaps at corner of the wall

#### Recommendation

Advice to completely seal

Done

## **Status**



Photo 12

## Findings #4

**Location** Selling floor

## **Observations**





Photo 13

Photo 14

## **Findings**

Small gaps on ceiling observed

### Recommendation

Kindly completely seal

### **Status**

Done



Photo 15

## Findings #5

Private & confidential 4/46



**Location** Selling floor

### **Observations**





Photo 16

Photo 17

**Findings** Small gaps in between chiller

**Recommendation** Kindly completely seal the gap

Status Done



Photo 18

Findings #6

**Location** Selling floor

#### **Observations**





Photo 19

Photo 20

**Findings** Gaps in between chiller observed

**Recommendation** Please completely seal the gap

Status Done



Photo 21

Findings #7

**Location** Selling floor



## **Observations**







Photo 22

Photo 23

Photo 24

## **Findings**

Small gaps at corner of the chiller

## Recommendation

Kindly completely seal the gaps

## Status



Photo 25

## Findings #8

**Location** Selling floor

#### **Observations**





Photo 27



Photo 26

Photo 28

## **Findings**

Small gaps along ceiling observed

## Recommendation

Kindly completely seal the gaps

#### **Status**







Photo 29

Photo 30

Photo 31

Findings #9

#### Location

Customers toilet (front)

6/46

Done



## **Observations**





Photo 32

Photo 33

## **Findings**

Small gaps observed along ceiling

### Recommendation

Kindly completely seal the gap

## **Status**





Photo 34

Photo 35

## Findings #10

Customers toilet (front) Location

#### **Observations**





Photo 36

Photo 37

# **Findings**

Small gaps observed at ceiling

### Recommendation

Kindly completely seal the gap

#### **Status**









Photo 38

Photo 39

Photo 40

Photo 41

Findings #11

Location Customers toilet

#### **Observations**

Done














Photo 42

Photo 43 Photo 44

Photo 45

Photo 46

## **Findings**

Gaps around piping were observed

#### Recommendation

Please completely seal gaps around piping

# Status









Photo 47

Photo 48

Photo 49

Photo 50

Findings #12

**Location** Customers toilet

## **Observations**





Photo 51

**Findings** 

Photo 52

Small gaps at ceiling were observed

Done

#### Recommendation

Kindly completely seal the gaps

### **Status**









Photo 53 Photo 54

Photo 55

Photo 56

Findings #13

**Location** Food preparation area














Photo 57

Photo 59

Photo 60

Photo 61

## **Findings**

Small gaps at ceiling were observed

### Recommendation

Kindly completely seal the gaps

## Status





Photo 62

Photo 63

Findings #14

### Location

Food preparation area

#### **Observations**







Photo 64

Photo 65

Photo 66

## **Findings**

Ceiling gaps were observed

## Recommendation

Kindly completely seal the gaps

#### **Status**

Done





Photo 67

Photo 68

## Findings #15

Location

Food preparation area







Photo 69

Photo 70

## **Findings**

Gaps were found along side partition

### Recommendation

Advice to completely seal the gaps

#### **Status**







Photo 71

Photo 72

## Findings #16

**Location** Food preparation area

#### **Observations**





Photo 73

Photo 74

# **Findings**

Gaps along counter were observed

### Recommendation

Please completely seal the gaps

## **Status**







Photo 75

Photo 76

## Findings #17

**Location** Food preparation area







Photo 77

Photo 78

**Findings** Ceiling gaps were observed

Recommendation

Kindly completely seal the gaps

**Status** 



Photo 79

Findings #18

**Location** Food preparation area

### **Observations**







Photo 80

**Findings** 

Photo 82

Recommendation

Kindly completely seal all gaps around cable

Gaps around cable were observed

Status

Done





Photo 83

Photo 84

Findings #19

**Location** Backroom area







Photo 85

Photo 86

## **Findings**

Detached door sealant observed

#### Recommendation

Kindly rectify door sealant highlighted

#### **Status**





Photo 87

Photo 88

## Findings #20

**Location** Backroom area

#### **Observations**







Photo 89

Photo 90

Photo 91

# **Findings**

observed

Kindly reseal the gaps completely

Incompletely sealed gaps

## Recommendation

## **Status**



Photo 92

## Findings #21

**Location** Backroom area

## **Observations**

Done







Photo 93

Photo 94

**Findings** Wall cable cover have gaps

### Recommendation

Kindly completely seal the gaps

#### Status



Photo 95

## Findings #22

**Location** Backroom area

# **Observations**





Photo 96

Photo 97

## Findings

Gap around piping conduit was observed

## Recommendation

Advice to seal the gap

#### **Status**

Done



Photo 98

## Findings #23

**Location** Staff toilet







Photo 99

Photo 100

## **Findings**

Small gaps along ceiling were observed

### Recommendation

Advice to completely seal the gaps

#### **Status**









Photo 101

Photo 102 Photo 103

# Findings #24

**Location** Staff toilet

### **Observations**





Photo 104

Photo 105

## **Findings**

Gaps around drainage cover trap were observed

## Recommendation

Kindly completely seal gaps around drainage cover trap

### **Status**





Photo 106

# Findings #25

**Location** Staff toilet







Photo 107

## **Findings**

Gaps around piping were obseved

## Recommendation

Kindly completely seal the gap

#### **Status**






Photo 109

Findings #26

## Ceiling (in front of customers toilet)

# Location



**Observations** 



Photo 110

Photo 111

# **Findings**

Ceiling opening were observed

#### Recommendation

Kindly install ceiling at highlighted

## **Status**

Done





Photo 112

Photo 113

# Findings #27

Location ILT Location 1







Photo 114

Photo 115

# Findings #28

**Location** ILT Location 2





Photo 116

Photo 117



# Media summary



Photo 1



Photo 3



Photo 2




Photo 4






Photo 5



Photo 7




Photo 6



Photo 8





Photo 9




Photo 11



Photo 10




Photo 12

Private & confidential










Photo 15




Photo 14




Photo 16

Private & confidential 20/46










Photo 19



Photo 18



Photo 20

Private & confidential 21/46





Photo 21



Photo 23




Photo 22



Photo 24

Private & confidential 22/46









Photo 27




Photo 26




Photo 28

Private & confidential 23/46










Photo 31



Photo 30




Photo 32

Private & confidential 24/46









Photo 35




Photo 34



Photo 36

Private & confidential 25/46









Photo 39



Photo 38



Photo 40

Private & confidential 26/46









Photo 43



Photo 42



Photo 44

Private & confidential 27/46










Photo 47




Photo 46



Photo 48

Private & confidential 28/46










Photo 51



Photo 50




Photo 52

Private & confidential 29/46









Photo 55



Photo 54



Photo 56

Private & confidential 30/46










Photo 59




Photo 58



Photo 60

Private & confidential 31/46






Photo 61




Photo 63




Photo 62



Photo 64

Private & confidential 32/46





Photo 65




Photo 67



Photo 66



Photo 68






Photo 69



Photo 71



Photo 70



Photo 72

Private & confidential 34/46





Photo 73



Photo 75



Photo 74




Photo 76

Private & confidential 35/46










Photo 79




Photo 78




Photo 80

Private & confidential 36/46






Photo 81



Photo 83




Photo 82



Photo 84

Private & confidential 37/46





Photo 85



Photo 87




Photo 86



Photo 88

Private & confidential 38/46





Photo 89



Photo 90



Photo 91



Photo 92

Private & confidential 39/46





Photo 93




Photo 95



Photo 94





Photo 96

Private & confidential 40/46










Photo 99



Photo 98



Photo 100

Private & confidential 41/46









Photo 103



Photo 102



Photo 104

Private & confidential 42/46





Photo 105



Photo 107



Photo 106



Photo 108

Private & confidential 43/46






Photo 109




Photo 111



Photo 110



Photo 112

Private & confidential 44/46





Photo 113




Photo 115



Photo 114



Photo 116

Private & confidential 45/46



Photo 117

Private & confidential 46/46