

CM-RS232-485

Plug-in communication module

SW version 1.0.2

1 General information	2
2 Changes in the version 1.0.2	3
3 Notes	4

1 General information

1.1 Version information

The version 1.0.2 is a minor release.

1.2 Clarification of Notation

Note: *This type of paragraph calls the reader's attention to a notice or related theme.*

IMPORTANT: This type of paragraph highlights a procedure, adjustment etc., which can cause a damage or improper function of the equipment if not performed correctly and may not be clear at first sight.

WARNING: This type of paragraph highlights a procedure, adjustment etc., which can cause a damage or improper function of the equipment if not performed correctly and may not be clear at first sight.

Example: This type of paragraph contains information that is used to illustrate how a specific function works.

2 Changes in the version 1.0.2

Note: *This version is the first update after initial release 1.0.1.*

2.1 Bug fixes

- Occasional dropouts at RS485
 - If there were multiple devices at the RS485 bus it may had come to occasional dropouts, i.e. the device had occasionally not responded to the request from the master.

3 Notes

3.1 Document history

Revision number	Related sw. version	Date	Author
1	1.0.2	5.6.2024	Jan Tomandl