

Task Hazard Analysis (THA) Worksheet

(See ES&H Manual Chapter 3210 Appendix T1
Work Planning, Control, and Authorization Procedure)

Click For Word

Author:	Step	Stepan Stepanyan			August 17 2016		Task #: If applicable	
	Complete all information. Use as many sheets as necessary							
Task Title:	k Title: CLAS12 Electromagnetic Calorimeter (EC) System			tem	Task Location: Ha		Hall B	
Division:	P	hysics		Department:	Hall B F		Frequency of use:	continuously
Lead Worker:								
Mitigation already in place: Standard Protecting Measures Work Control Documents All workers on the EC system measures			em must complete	e SAF111 (Hall B saf	ety training)			

Sequence of Task Steps	Task Steps/Potential Hazards	Consequence Level	Probability Level	Risk Code (before mitigation)	Proposed Mitigation (Required for Risk Code >2)	Safety Procedures/ Practices/Controls/Training	Risk Code (after mitigation
1	Energize EC HVPS (-2500 V @ 500 uA max V/I settings) - possible exposure to high voltage	М	L	2		SHV cables terminated properly at voltage divider and supply; supply properly grounds to racks	0
2	Servicing detector components – manlift or ladder access, potential fall hazards	Н	М	3	A harness must be used for manlift operations or on ladders where a fall of more than 4 ft. may occur.	Harness training, manlift training, ladder training, fall protection training	1
3	Servicing cables below floor gratings. Potential fall hazard due to grating removal.	L	M	2		Warning cones, signs and ropes to identify and isolate areas with removed floor gratings.	1

Highest Risk Code before Mitigation:	3	Highest <u>Risk Code</u> after Mitigation:	1
--------------------------------------	---	--	---



Task Hazard Analysis (THA) Worksheet

(See ES&H Manual Chapter 3210 Appendix T1 Work Planning, Control, and Authorization Procedure)

When completed, if the analysis indicates that the <u>Risk Code</u> before mitigation for any steps is "medium" or higher (RC≥3), then a formal <u>Work Control Document</u> (WCD) is developed for the task. Attach this completed Task Hazard Analysis Worksheet. Have the package reviewed and approved prior to beginning work. (See <u>ES&H Manual Chapter 3310 Operational Safety Procedure Program.</u>)



Task Hazard Analysis (THA) Worksheet

(See ES&H Manual Chapter 3210 Appendix T1 Work Planning, Control, and Authorization Procedure)

Form Revision Summary

Periodic Review – 08/13/15 – No changes per TPOC

Revision 0.1 – 06/19/12 - Triennial Review. Update to format.

Revision 0.0 – 10/05/09 – Written to document current laboratory operational procedure.

ISSUING AUTHORITY	TECHNICAL POINT-OF-CONTACT	APPROVAL DATE	REVIEW DATE	REV.
ESH&Q Division	Harry Fanning	08/13/15	08/13/18	0.1

This document is controlled as an on line file. It may be printed but the print copy is not a controlled document. It is the user's responsibility to ensure that the document is the same revision as the current on line file. This copy was printed on 8/23/2016.