ETAS ISOLAR-A/B 12.7.0

Read Me

www.etas.com

Copyright

The data in this document may not be altered or amended without special notification from ETA S GmbH. ETAS GmbH undertakes no further obligation in relation to this document. The software described in it can only be used if the customer is in possession of a general license agreement or single license. Using and copying is only allowed in concurrence with the specifications stipulated in the contract.

Under no circumstances may any part of this document be copied, reproduced, transmitted, stored in a retrieval system or translated into another language without the express written permission of ETAS GmbH.

© Copyright 2024 ETAS GmbH, Stuttgart

The names and designations used in this document are trademarks or brands belonging to the respective owners.

ETAS ISOLAR-A/B 12.7.0 – Read Me R01 EN – 04.2025

Contents

1 What is ISOLAR-A/B 4

2 Eclipse Performance Issue 5

3 ISOLAR-A/B Start up Issue ..... **Error! Bookmark not defined.**

4 Installing updatesite via UserInterface of ISOLAR-A/B 6

5 Use of Update Site- installed Features with Later Versions of ISOLAR-A/B 7

6 Removal of com.bosch.bsw.fwd.performance entry from buildSettings.properties 8

7 Contact Information 9

1 What is ISOLAR-A/B

ISOLAR-A/B V12.7.0 is ETAS next step of integrating AUTOSAR Authoring and BSW Configuration tools. At the same it is our first step to deliver improvements like shorter turnaround times and higher productivity employing a common data object model, support of iterative workflows, replacing many manual efforts by automated ('zero') configuration techniques, and many more.

ISOLAR-A/B consists of:

- **ISOLAR-A V12.7.0**, the established ETAS AUTOSAR System and Application software product
- **ISOLAR-A/B V12.7.0**, the established ETAS AUTOSAR Basic Software configuration product

2 Eclipse Performance Issue

Problem Description:

Windows 10 defender if enabled, significantly slows down eclipse which might impact the performance of ISOLAR-A/B.

Root Cause:

Windows 10 defender continuously scans the JAR files in the background, thereby slowing down eclipse. which would impact ISOLAR-A/B (cf. BugZilla ID: https://bugs.eclipse.org/bugs/show_bug.cgi?id=548443)

Workaround:

Add eclipse root directory to windows 10 defender's exclusion list.

1. Open Windows 10 settings.
2. Search for "Virus & threat protection" and open it.
3. Now click on "Virus & threat protection settings" section.
4. Now click "Add or remove exclusions" under "Exclusions" section.
5. Now click "Add an exclusion" then select "Folder"
6. Point to directory where product is installed (C:\ETAS\ISOLAR-AB_V12.x) and press "Select Folder"

3 Installing updatesite via UserInterface of ISOLAR-A/B

Update sites can be installed on top of ISOLAR-A/B to add new features and to enhance existing features.

To install additional or later software to ISOLAR-A/B via an update site:

1. Launch ISOLAR-A/B
2. Go to menu Help > Install New Software… > Add > Local… or Archive… (zipped format)
3. Browse and choose the update site to be installed
4. Select the features that need to be installed
5. Click on Next & Finish

Note:

- To ensure consistent behaviour, after installing update site always click No on the Re-start Now prompt and manually close and open the tool immediately

4 Use of Update Site- installed Features with Later Versions of ISO-LAR-A/B

Update site features need to be installed (again) on-top of later tool versions, and cannot – for reasons of compatibility or availability after an uninstallation – be re-used from any previous installation.

Please cf. topic Installing Update sites for further details.

5 Removal of com.bosch.bsw.fwd.performance entry from buildSettings.properties

If the entry “com.bosch.bsw.fwd.performance=<Value>” exist in a project’s buildSettings.properties file, then it should be removed or the <Value> should be set to “false”.

6 Contact Information

Technical Support

For details of your local sales office as well as your local technical support team and product hotlines, take a look at the website: www.etas.com/hotlines

ETAS Headquarters

ETAS GmbH
Borsigstraße 24
70469 Stuttgart
Germany

Phone: +49 711 3423-0
Fax: +49 711 3423-2106
Internet: www.etas.com