
# PHASETRACKER Fabrication Document

## Top Test Points (Scale 1:1)




| Ref. | Net | X [mm] | Y [mm] |
|---|---|---|---|
| TP1 | | -64.00 | 106.00 |
| TP2 | | -64.00 | 106.00 |
| TP7 | | -64.00 | 106.00 |
| TP8 | | -64.00 | 106.00 |
| TP13 | | -64.00 | 106.00 |
| TP14 | | -64.00 | 106.00 |

| Ref. | Net | X [mm] | Y [mm] |
|---|---|---|---|

All dimensions are in millimeters unless otherwise specified.

| | | | | | |
|---|---|---|---|---|---|
| | Comments: | Company: OPEN THRUST LAB | | Variant: PRELIMINARY | Git Hash: 9f53c40 |
| | | Board Name: **PHASETRACKER** | | Project Name: **OPEN_PHASE** | |
| | Sheet Title: Top Test Points (Scale 1:1) | File Name: OPEN_PHASE.kicad_pcb | Designer: SIEBERT DIMITRY | Date: 2024-04-13 | Revision: + (Unreleased) |
| | Sheet Path: | | Reviewer: | Size: **A4** | Sheet: **4** of **9** |