ate	TSN	eller TSO	A/C Hrs	Service D	ion of all operations perta locuments, Overhaul, Ma	jor or Minor Repair, and I	Inspections.
				2/21/2022	TSN 51B UNK been serviced as per the under Work Order aft Propeller Service, Lake Zurich, Illinois	140273	
		9			9		
	Engine - Type: IC 2381.70 ***Propeller*** Completed an an operational, and technical data. It determined to be Benjamin J. Pitte A&P390747277		nual inspection in accordate the checks - no defects in arrive that this propeller he in airworthy condition.		(BP). Performed ground run, cordance with approved/curren ce with an Annual inspection a	t	

Make: Hartzell Model: PHC-J3YF-1RF/F7392-1 Serial No.: FP3061B	CONTINENTAL SERVICES	Date: 11/10/2022 THOBBS Time: 2387.8 Total Time: 2387.8 Time SOH: 65.5
The work performed as described bel Administration and found to be in airw	Fairhope, AL 36532 251-990-5080 FAA Repair Station No. 9 ow has been inspected in accordance with current forthy condition with respect to the work performed	regulations of the Federal Aviation i.
Work Performed: This propeller was torqued to specification.—END—— Authorized Signature for Repair Statio of the work performed are on file under	on 9CER853B: OCC BY ON 1	1457 N700ZG with new o ring and Details
Make: Hartzell Model: PHC-J3YF-1RF/F7392-1 Serial No.: FP3061B	CONTINENTAL SERVICES	Date: 11/18/2022 THOBBS Time: 2390.8 Total Time: 2390.8 Time SOH: 68.5
The work performed as described Administration and found to be in a	32, Fairhope, AL 36532 251-990-5080 FAA Repair Station Nobelow has been inspected in accordance with curredirectly condition with respect to the work performance by BALANCED PROPELLER TO WITHIN .08 II ation 9CER853B:	ned.
of the work performed are on file u	nder Work Order No. AC-11029	9
0		