

AST-57-4

Aircraft Record General Inform	nation			
Manufacturer Cirrus Design	90	of 95 tepow		
Serial 1457		Registration Num	ber N700 Z G	
Date of Manufacture 9 - 2004				
Engine(s) currently installed:				
Manufacturer	Model		Serial	
Manufacturer	Model		Serial	
Propeller(s) currently installed:				
Manufacturer		Model		
HUB Model	Serial		Serial	
Blade Model	Serial	Serial	Serial	
Blade Model	Serial	Serial	Serial	

nd Alterations Date: 6/03/2020; Aircroft: N700ZG, Type: CIRRUS SR20; S/N: 1457; Hobbe: 1762.70; Total Time: 1762.70; cate Number of Engine - Type: IO-360-E36, S/N: 357840, Time: 1762.70; Prop - Type: PHC-J3YF-IRF, S/N: FP30618, Time: specific entries.) 1762.70 \*\*\*Airtrame\*\*\* Completed an Annual inspection in accordance with FAR 43, Appendix D. Replaced ELT batteries o/n MN1300 with new, next due 03/2027 (des). Inspected and tested ELT in accordance with FAR 91.207(d), no defects noted. Next due 6/21. ELT bettery due 3/2027 (des). Complied with Cirrus SB2X-52-08R2 (4/22/16) Catcher/Diverter and Gas Strut Replacement by installation of p/n 70542-001 and inspection (tkb). Replaced moture cable clamp clip p/n 11669-903 with new (des). Replaced alternator 2 gasket p/n 653487 with new (des). Replaced left brake linings p/n RA066-14100 and brake rivets p/n RA106-00200 with new (des). Replaced right brake over temp sticker pin 51698-003 with new (des). Replaced left and right gear fairing upper bracket pin 13522-001 with new (dos). Completed composite repair on nose wheel fairing per Chap. 51-20 (CSH). Replaced left and right upper landing gear fairing well nots pin 50802-001 and pin 50803-001 with new (des). Replaced left and right upper landing gear fairing scrows with new (des). Replaced pilot step tape p/n 12683-006 with new (CSH), Replaced CAPS placards p/n 12430-001 and NO PUSH placards p/n 12431-013 with new (CSH). Repaired, isolated, and secured flap sensor wire (des). Adjusted and secured pilot and copilot door striker pins (CSH). Repaired and adjusted pilot and copilot latches (CSH). Swung compass and completed correction card (des). Cleaned and replaced air oil separator seas p/n ORK-OS850 with new (CSH). Replaced induction air filter pin BA-24 with new (des). Performed ground run, operational, and leak checks - no defects noted. All work performed in accordance with approved/current technical data. I certify that this Aircraft has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition. DJQ 1A369765035 Doug Seibel A&P399785035 IA Wisconsin Aviation - Madison Wisconsin Aviation - Watertown 1741 River Drive 3606 Corben Court Watertown, WI 53094 Madison, WI 53704 920-261-4567 608-268-5003

STATE OF

PAA.

East A

Tall.

Action

Test A

Tal.

Acres

CERT

CERT

CONG

CERT

TRAN

The air maint

Description of Inspections, Tests, Repairs and Alteration YEAR RECORDING TOTAL TODAY'S TACH FLIGHT TIME IN Entries must be endorsed with Name, Rating and Certificate Number of 20 ALTIMETER, STATIC, AND TRANPONDER CERTIFICATE N700ZG STBY ALTIMETER Wisconsin Aviation - Four Lakes Inc. Madison, W1 53704 608-268-5006 FAA CRS No. DBKR124D Test Alt. x 1k Ft -1 D 3 1.5 2 3 6 8 10 12 14 16 18 Tol. + Ft. 20 20 20 20 25 30: 30 35 40 80 60 90 100 110 120 Actual + Ft. 20 -201 fi. -10 -10 0 0 D. ō 0 ō. 0 15 3 50 Case Hysteresis. Test Alt x 1k Fu 26 22 25 25 30 35 405 50 OK Leak ALTIMETER Tol + 73 Ft. 30% Tol. Tol. + Ft. 130 340 155 180 205 230 255 260 20 15 MAKE, United 100 Pt Max MODEL: 39340-3 Actual | Ft. Temp 40% S/N: 439975 96 × X X X X X X 17 20 Max CERTIFIED STATIC PRESSURE SYSTEM PER FAR 43 APP. E (8) BLIND ENCOGER CERTIFIED ALTIMETER PER FAR 43 APP. E. (b) TO (20) THOUSAND FEET. CERTIFIED AUTOMATIC PRESSURE ALTITUDE REPORTING EQUIPMENT PER FAR 43 APP. E (c). MAKE: ACK COMPLIED WITH RECORDS KEEPING PER PAR 43 APP E (d). MODEL: A-30 CERTIFIED TRANSPONDER SYSTEM PER FAR 43 APP. F. SAN: 103813 TRANSPONDER MAKE: Garmin MODEL: GTX345 S/N- 3EG029194 #2 TRANSPONDER The aircraft and/or component identified hereon was repaired and dispected to accordance with the current MAKE: X maintenance rules of the Federal Aviation Regulations and is airworthy and environed forceturn to service. MODEL, X SAN: X Date: June 8, 2020 W.O., AV20-0185 Hobbs: 1763 4 Signed

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility (See back pages for other specific entries.)
1760 ***Ai SR2 Gers	ne - Type 10-36 2.70 irframe*** ieplaced #3 CHT 0 Maintenance M ard Maier	probe p/n 1	357840, Tam	tRUS SR20; S/N: 1457, Hobbs: 1762.70; Total Time: 1762.70; e: 1762.70; Prop - Type: PHC-J3YF-IRF, S/N: FP3061B, Time: h new (gm). All work performed in accordance with Circus Design
	Wisconsin A 3606 Corben Madison, W 608-268-500	Court I 53704	Madison	Wisconsin Aviation - Watertown 1741 River Drive Watertown, WI 53094 920-261-4567
20				bbs: 1795.9
€ 30	ent on	+ fol	- ber	ALTZ light is on, Removed ALTZ och test. Found ALTZ Checks
900	dont	£5+.	3454	em needs further trouble shooting
		-		1603-2484, 14 8

YEAR 20 DATE	RECORDING TACH TIME	TOBAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries
April	22,20	121	Hobb	ts ALT field C/B pops and displayed Remove ALTI and coon check. Reinstalled alt s/n. H-L080709. Repaired field re. Elec sys exs good on gra
4171	Pile	tr	coor	displayed Remove ALTI and
KLI	t on	+ 10	ras	Joohn check. Reinstalled alt
PIN-	ES-4	1024	LPR	5/n-H-L080709. Repaired field
wir	e 2 00	x+ pu	+ wi	re. Elec sys exs good on gra
rur	MP			A & B 3 2 484/168
			-	
_				
_		-		
-				
	1			

v	'n	
£	ε	3
2	n	

BAT

Date: 7/13/2021; Aircraft: N70029y-Type- CIRRUS SR20; S/N: 1457, Hobbs: 2168.10, Total Time: 2168.10; Engine - Type: IO-360-ES6, S/N: 357840, Time: 2168.10; Prop - Type: PHC-J3YF-IRF, S/N: FP3051B, Time: ₹2168.10

Completed an Annual inspection in accordance with FAR 43, Appendix D. AD 20-19-06 (11/03/2020) McCauley Propeller Systems governors idler gear bearing inspection N/A by no governor work completed affect dates (bw). Comply with AD 08-11-18 exhaust pressure test. Next due 2268.1 (jw). Complied with SB2X-32-18R4. Nose Landing Gear Strut Assembly Inspection, no defects noted. Next due 2268.1 hobbs (jw). Inspected and tested ELT in accordance with FAR 91.207(d), no defects noted. Next due 6/2022. ELT battery due 3/2027 (jw). Replaced # 2 batteries with new. p/n 50979-001 (tkb) Completed cabin fire extinguisher weight check, failed weight check (jw). Replaced fire extinguisher and bracket p/n 12533-004 with new (CSH). Replaced air filter p/n BA-24 with new (jw). Removed aircraft bettery. Completed battery capacity check. Battery checked normal and pessed at 109%. Top charged battery and reinstalled (jw). Replaced nose landing gear puck p/n 11879-005 with new(CSH). Removed and sent electric fuel pump for repair (CSH). Installed electric fuel pump, p/n 5217-00-3, s/n 1635, after overhaul by Aeromotors, LLC, CRS# 01MR357Y, Wolf M2107024, dated 7/12/2021 (CSH). Replaced all exhaust valve cover gaskets with new (jw). Replaced left brake caliper o ring with new (jw). Replaced all exhaust valve cover gaskets with new (jw). Replaced left main gear inboard wheel pant bracket with new (iw).

Removed Rudder -Alteron Interconnect Assembly in accordance with Cirrus S82X-27-18R2. (gm) Replaced ELT remote battery p/n 50479-001 with new. Replaced brake linings p/n 066-141-00, and disks p/n 164-241400 with new. Replaced nose tire with new, p/n 072-312-0, s/n 1064T00225 and tube p/n 097-908-0. Cleaned, inspected, and repacked wheel bearings. Reinstalled wheel and tire assembly (jw). Replaced nose wheel bearing cone p/n 06125, and cup 08231 on valve stem side with new (jw). Replaced left and right door seals in accordance with Cirrus S82X-53-10. (gm) Replaced door catcher p/n 17582-008 with new (lkb). Removed and sent prop governor to Tiffin Aire, Inc (or repair (CSH). Installed prop governor, p/n C290D3-R/T23, s/n 040828, after repair by Tiffin Aire. Inc, CRS# DTXR341D, Wo# 8863, dated 5/10/2021 (CSH). Performed ground run, operational, and leak checks - no defects noted. All work performed in accordance with approved/current technical data. I certify that this Aircraft has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition.

Jon Weigand A&P 3678294

> Wisconsin Aviation - Madison 3606 Corben Court



Wisconsin Aviation - Watertown 1741 River Drive Iterations Number of

tific entries.)

J. Approving Civil Aviation Authority/Country: FAA/UNITED STATES	Al Al	UTHORIZED RELE FAA Form 8130-3, AIRWOR			s	cking Number. O# 15513257
Cognization Name and Address:	GARMIN International	1 1200 E 151st Oluthe, KS 65062	Certificate No. GhX!	R582Y	147.5 C 17.3 G C 19.3 C	der/Contract/Invoice Number: O A 15513257
5. hem: 7. Description: 1. GMA340	8	Part Number: 011-00401-10	9 Quantity:	10. Serial Number: 96297916		11. Status/Work: OVERHAULED
This unit complies with Mod I This unit complies with Mod I This unit complies with Mod I This and complies with Mod I This and complies with Mod I This and complies with Mod I This unit complies with Mod I The unit complies with Mod I The work that was performed on this unit was for the GII-00001-10 unit that was precessed.	dono to rises the requirements	of all sections of the maintenance numeral part and	mber 190-00364-00 Sev- A	.Y, Rovisani Dato 12/16/2020. Refer	ence: 018-50152-10 is	the Gamin stocking/shipping part mander
13a. Certifies the items identified abo  Approved design data and are in o	endition for safe operation		Certifies that unle Block 12 was acc	complished in accordance with rk, the items are approved for r	12, the work identif Title 14, Code of Fe	ons specified in Block 12 ied in Block 13 and described in deral Regulations, part 43 and in 14c. Approval/Certificate No.:
13b. Anthorized Signature N / A		N / A	(4v. Automized Sign	Doubs	~	G6XR582Y
13d. Name (Typed or Printed N / A		13e. Date (dd/mmm/yyyy) N / A	14d. Name (Typed or	Printed) Houng Tran		14e. Date (dd/mmm/yyyy) 14 May 2021
18.7 A			r Responsibilities			5.0.00000000000000000000000000000000000
Where the user/installer performs work the user/installer ensures that his/her ai	in accordance with the na recethings authority accor- t constitute installation co-	lone does not automatically constitute with ficial regulations of an airworthiness author pls aircraft engine(s)/propeller(s)/article(s) nification. In all excess aircraft maintenance	rity different than the a from the Airworthness	irworthiness authority of the co Authority of the country specif	ied in block 1.	

Iterations Number of life entries.)	YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	A	igust	27,	2021	Hobbs: 2228. 6 H brake deed on saliper
	_	RE	Place	cad R	H brake decal on galiper
-		AII	CK		Tay Facts
de					77.71,00000110,77.
ba.	-				
	-				
	-				
_		Marie Co.			

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries must	be endor	sed with Na	Tests, Repairs and Alt me, Rating and Cortificate N back pages for other specif	lumber of
	(	HICAGO AVIATION SERVICES	Aircraft # 5 Date:	: N700ZG 11/01/2021	Model: WO#:	SR20 21-395	Serial π: 1457	
	нов	BS: 2283	.8					
	The	following v	ork was ac	complished:				
		overh: dated	uled MCU 19 August : t Road, Dul	2021 from Cirru	-011(s), S/ s Design i	N 02005. Se Factory Serv	placed with se FAA From 8130-3 ice Center, 4961 DLH6171-07-2021 for	
	-			1/8 turn coun	terclockw	ise.		
		<ul> <li>Re-cri</li> <li>Remore</li> <li>overheated</li> </ul>	mped #5 CF ved alterna auled altern 15 Septem	IT connector. O tor 2 P/N BC410 nator 2 P/N BC4	k for serv 0-1, S/N 0 10-1, S/N Aerotech	ice. 742854X an 0887319K. of Louisville,	d replaced with See FAA Form 8130-3 , Inc., 2209 Watterson 45 for details.	-

CONTINUED

and Alterations YEAR RECORDING TODAY'S TOTAL Description of Inspections, Tests, Repairs and Alterations ficate Number of TACH FLIGHT TIME IN 20 Entries must be endorsed with Name, Rating and Certificate Number of TIME SERVICE er apecific entries.) Technician or Repair Facility (See back pages for other specific entries.) BATE Aircraft #: N700ZG Model: 5R20 Serial #: 1457 AVIATION Date: 11/01/2021 WO#: 21-395 I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED OR REPAIRED IN ACCORDANCE WITH APPLICABLE TITLE 14 CODE OF FEDERAL REGULATIONS AND MANUFACTURER'S SPECIFICATIONS AND IS APPROVED FOR RETURN TO SERVICE AS IT RELATES TO THE WORK PERFORMED. for Mark Palazzo, AP 201711 IA END 0-3 300

PEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	ME IN Entries must be endorsed with Name, Rating and Certificate Number of							
		ATION	Aircraft #: N Date: 1	700ZG 1/01/2021	Model: WO#;	SR20 21-395	Serial #: 1457	-			
	I CERTIF WITH AI SPECIFIC WORK P	Removed after ove Ontario L Ontario, Y THAT TH PPLICABLE CATIONS A PERFORME	rhaul. See E/ td., Canadia Canada, Auti IIS ENGINE H TITLE 14 CO ND IS APPRO	pter P/N 64 ASA Form Or n Aero Man horization N HAS BEEN IN DDE OF FEDE OVED FOR R	ne dated ufacturin lo. 384-9 SPECTED RAL REG	21 April 202 g, 2648 Ego 1, WO# 21-0 OR REPAIRI ULATIONS A	1-067 and reinstalled 21 from 978652 Sideroad, Severn, 067 for details. ED IN ACCORDANCE AND MANUFACTURER'S AS IT RELATES TO THE				

-94	rovingCivil Aviation in rity/Country: UNITED STATES	2.	AUTHORIZED REL FAA Form 8130-3, AIRW			3.	Form Tracking Number: 141245
4. Organiz	zation Name and Add	ess: otech of Louis	ville, Inc. 2209 Watterson	Trail L	ouisville, KY 40299		k Order, Contract, or Invoice Number WO: 141245
ā Item:	7. Desc	ription:	8. Part See 9	Quantity	10. Serial Number:		11. Stalus/Work;
1	B C ALTERN	V.	BC410-1	1	s/n 0887319K		Overhauled
টেৰ ও	AS MOOINO & ORM THE FOLLOWING S	S MFG. COMPLIES SERVICE BULLETINS Jentified above we	WITH SGA-1000 REV. 3 05/21/2020 S & AD NOTES HAVE BEEN COMPLIED WITH Bre manufactured in conformity to:	14a X Certific Block	14 CFR 43.9 Return to Service es that unless otherwise specification and described in Block 12	X Other relied in block 2 was acco	gulation specified in Block 12 12, the work identified in mplished in accordance
()) ()	Non-app	Foved design data	a specified w 574-1-12		itle 14, Code of Federal Regula the items are approved for retu		
13b. Auth	norized Signature.		13c. Approval/Authorization	No: 14b Auth	orized Signature:		14c. Approval/Certificate No PU4R453M
13d, Nan	ne (Typed or Printed):		15e. Date (dd/mm/yyyy).	14d. Nami	MIKE EVANS	4812-G	14e. Date: (dd/mm/yyyy): 15/SEPT/2021
			User/Installer	Responsibili	ties		
Where to country airworth	the user/installer p specified in Block liness authority of ents in Blocks 13a	erforms work in a 1, it is essential to the country speci- and 14a do not c	nce of this document alone does not a necessary with the national regulation hat the user/installer ensures that his/lified in Block 1. constitute installation certification. In a dations by the user/installer before the	s of an airwo er airworthin I cases, aircra	rthiness authority different than ess authority accepts aircraft er aft maintenance records must c	the airworth	niness authority of the peller(s)/article(s) from th

## Aerotech of Louisville Inc.

2209 Watterson Trail Louisville, KY 40299

## FAA Certified Repair Station # PU4R453M 5GA-1000 Maintenance Release

Model 14/28V 20A	Part No. BC410-1	Serial No. 0887319K
Work Order No. 141245	Technician CHRIS FAJARDO	Date 15/SEPT/2021

This unit was disassembled, cleaned, inspected, reassembled, and tested in accordance with current manufacturer's overhaul manual specifications and in accordance with current F.A.A. regulations concerning this unit.

Oty. P	art#	Desc.	Qty.	Part#	Desc.	Otv.	Part#	Desc.
† SK	(F 6202-2RSJEM	DE Bearing	-			1 500		1
1 SK	CF 6002 2RSJEM	CE Bearing						
1 3	J&N 150-52000	BRUSH SET			- Harris			
- "					1017-0115	mi		
					-01	TO I	CK1-171	
							This in	
		100						
								L
								Janes and
							-	

	AD Notes										
AD No.	Int.	Method of Compliance	AD No.	Int.	Method of Compliance						
	-		-								
10 8		720 T		90.5							

1740	Service Bulle	tins Complied V	Vith	
			5-31 (1-5)	
-				
-	-	-	_	
			10 No. 10	

This unit is approved for return to service


Signature	Mi	Date	15/SEPT/2021	
	4/	16.373.00		

Ant	ving Civil Aviation thority/Country: A/United States	AUTHORIZED REI FAA FOTIO 8130-3, AIRW			3. Form Tracking Number: DLH6171-07-2021
	ization Name and Address: s Design Factory Se				5. Work Order/Contract/Invoice Number: DL.H6171-07-2021
6. Item:	7. Description:	8. Part Number:	9. Quantity:	18. Serial Number:	11. Status/Work:
1	MCU120	Factory Service Center, 4961 Airport Road, Dult blios:  8. Part Namber:  MCU120  16600-011(S)  MPLETE DESCRIPTION OF WORK PERFORMED IS ON FILE A NOE NUMBER INDICATED IN BLOCKS 3 AND 5. Inspected/Te Overhauf Batch Traveler CDCFSC FORM 506 Rev 14. Article is hiness Directive may apply to the article(s) described hereon. The complete compliance with any applicable Airworthiness Directive ral-Part. This is not an Export Approval.		02005	OVERHAULED
This Certi service u	ifies that the work specifie nder EASA Approval Certi nities the Heins identified als	d in block 11/12 was carried out in accordance with E ficate Number EASA, 145 5632 and Cirrus Design Fa overwire manufactured in cumformity to:	14a. 🗷 14 Certif and de Feder	CFR 43.9 Return to Service les that unless otherwise specified in service as recomplish	Misconsidered ready for release to Misconsidered ready for release to Misconsidered ready for release to Misconsidered in Block 12.  Block 12, the work identified in Block 14 and in necondance with Title 14, Code of at the that work, the items are approved for
13h, Aut	horized Signature:	13e: Approval/Anthorization No	1000	rized Signature:	14c. Approvnt/Certificate No.: YD5R855Y
t3d. Nan	ne (Typed or Printed):	13c; Date (dd/mmag/yyyy):		(Typed or Printed): C. McGovern	14e. Date (dd/mmm/yyyy): 19/AUG/2021
		User/Instal	ler Responsib	ilities	
Where th Block 1, i specified	e user/installer performs w it is essential that the user/i in Block 1.	e existence of this document alone does not automatical ork in accordance with the national regulations of an a usualler ensures that his/her aleworthiness authority are not constitute installation certification. In all cases, at	irvortkiness ant cepts niveraff en	hority different than the nitworthin just(s)/propeller(s)/article(s) from th	ess anthority of the country specified in se airworthiness authority of the country

from Display 5 men. to department and families Section Congress AUTHORIZED RELEASE CERTIFICATE 7984567 Annicker that Cinker. EARLESS RESEARCH CONTRACTOR NAMES APPROPRIATE TAXABLE CARL STREET, ARREST STREET a respective tracted later. -Textron Aviation Inc. (PC4) Textron Aviation Inc. 4555945 1 Cessna Blvd, Wichita, KS 67215 Ed James Beek A Same IV-month T Carl Marine 1 Same and the state of the state of the 30 14077 New POWER SUPPLY 91-0770062-05 17 2 ---PO#: 7031 The Designation of the District Administration of the Park III Life Tradition the dependent of the free months that he enforcement with the land and the state of the state of the first the land of the state of the Agree of the parties and the proposition for all accounts. If per tracked in the Consultant while water face with the Trade of February Supplement for that and in proper makes made the comme The agency from the professor black (1) contract in more returned 78. holomorthogen No. Special Parketon Co. PENDONNESSI PE his Apparent Confirmation PC4 The Day of the second 10 Name Of page on French 2 As The visit show and of Survey Consults Pressult. JENNIFER FISHER 08/Nov/2021 Coordinateller Responsibilities. But invokable managing that the country of the foreign that the state of the country of the coun When the same problems have a freely as providing with the desired continuous, at the continuous problems, and the continuous problems are a second or continuous problems. as News it is a covered that he are insulty became that his her accomplished a providence and red in a part of the covered that he covered the covered that he make you had a 19 of 1 fraction to the local size and light department of the finance of the first of the accordance with the current regulations in the arise socialis. Nation the competitors to flame

d Alterations ate Number of pecific entries.)	YEAR 20 Date	RECORDING TACP-	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility (See back pages for other specific entries.)			
	Nov	emb. Pil	r9 ot v	2021 epor	Hobbs: 2288,6 + strobe lights C/B pops.			
	Ke	place	wun	H Wir	atip strobe power supply 1-01-077 0062-05. 3/n-14077.  on test.			
	54	STEM	CK:	s 9001	CON TEST. Kanh Parts			
-								
	+-							

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name. Rating and Sentificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	III.
Dec	empe	v 20	,2021	Hobbs: 2318.5  TI light on and NBR.I ALT  mittently Removed NBRI ALT  Systems for repair. Repaired  minal leads Replaced Brashes  134. Reinstalled ALT and  CCS agod on KST Hay facts	Į.
Pold	CIB	ref	inter	mittently Removed NBRIALT	
and	sent	to Ai	revafi	Systems for repair Repaired	
VEC	ti tiev	+0 A	UX te	minal leads Replaced Brashes	ŀ
ele	etrica	1 34	stem	CCS good on +5+ familiants	
		/		H 53248.168	Į.
					t
					L
					F
					t
					-
-					H
- 16	-			Table 1	1



Description of Inspections, Tests, Repairs and Alterations TODAY'S TOTAL RECORDING YEAR Entries must be endorsed with Name, Rating and Certificate Number of FLIGHT TIME IN TACH Tuchnician or Repair Facility. (See back pages for other specific entries.) SERVICE TIME DATE Removed prop & sent to Aircraft Propeller Service for inspection & repair. Par Vit Feb. 22,2022 Hobbs: 2322.3 ## 33248UB
Reinstalled propon SR20 N700ZG
Collowing major overhaul. See Prop Log
For details. Leak CKE op CK 9000.