
	DeKalb Avionics	
EAR	(815)981-8284	ns, Tests, Repairs and Alterations
MATE	Date: 7-1-22 N# 7002 G Work order no: 2022-157	Name, Rating and Certificate Number of iee back pages for other specific entries.)
-	I certify that the static system checks required by 14 CFR	
	Part 91.411 have been performed this date and filed to	
	comply with 14 CFR part 43, appendix E Para A	
	1	
-	Signed for CRS2WWR159D	
	DeKalb Avionics	
	(815)981-8284	
	0.00 300 300 300	
	I Certify that the ATC Transponder Test and Inspections	
	required by 14 CFR 91.413 were performed this date and	
	found to complywith 14 CFR part 43 Appendix E para F	
	Transponder #1 Transponder #2	
	Make: GARMIN Make: W/A Model: GTX 345 Model: W/A	
	2/-(120/01	
	Serial no: 3EG029194. Serial no: WIA	
	(/1/	
	Signed for CRS2WWR159D	
	SIGNED TO CKSEWWK159D	
	I certify that the automatic pressure altitude reporting system	
	checks required by 14 CFR part 91.217 and 14 CFR part 91.411	
	have been performed and filed to comply with 14 CFR part 43	
	appendix E, para C	
	Encoder #1 Encoder #2	
3	STREET, T.C.	
3	Make: ACK Make: WA	
	Model: A-30 Model: WIA	
	Serial no: 103813 Serial no: NIA	
	TXP SN: 3FG 029194, TXP SN: W/R	

**DeKalb Avionics** ons, Tests, Repairs and Alterations YEAR (815)981-8284 th Name, Rating and Certificate Number of 20 (See back pages for other specific entries.) Alt Model: UI 59340-3 N# 700ZG DATE Alt Serial : 439975 WO# 2022-157 Alt Tested to: 20 000 ff Date: 7-/-22. I certify that the altimeter checks required by 14 CFR 91.411 Have been performed this date and found to comply with with FAR part 43, Appendix E, Paragraph B Signed for CRS2WWR159D STBY Location: Alt Reads Tol Error Alt Reads Tol Error -1000 20 -10 14000 100 +20 20 -20 0 15000 105 NA 500 20 -10 16000 110 +20 1000 20 18000 120 -5 140 1500 25 +5 20000 130 +90 30 +10 2000 22000 140 3000 30 155 25000 +10 4000 35 +20 30000 180 6000 40 35000 205 +30 8000 60 +30 40000 230 10000 80 +10 45000 255 12000 90 50000 280 120 HY 50% 75 HY 40% 75 10 20 After Effec 30 0 Scale Error Pass 1655 Hysterresis Pass After Effect Friction 1455 Pass Case Leak Barometer Scale Error 1455



		19		
YEAR 20 Date	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	Engine - Type 2381.70 ***Airframe** Completed at (7/7/08) SR2t Completed with noted (BP). It ELT bettery destinguisher aircraft batter battery and r 097-500-0. CReplaced rig wheel pant in Replaced he M83481/1-2 oil cooler bu Stop drilled end bolt (BP box as requiaircraft has items dated Benjamin J. A&P390747 Wiscons 3606 Co.	e: IO-360-E3  n annual ins 0 heat excha- n SB 2X-32- nspected and due 3/2027 weight chec ry. Complete reinstalled (to Cleaned, insight nose whe nounting ho hat tape on le 24 and over imper p/n 63 and filled led ired (BP). Al been inspec- 08/12/2022 Pitterle r277 IA sin Aviation, WI 537  n, WI 537	pection in accanger by pres- 18 by visual in dested ELT (BP). Replaced to the second s	ype: CIRRUS SR20; S/N: 1457; Hobbs: 2381.70; Total Time: 2381.70; 340, Time: 2381.70; Prop - Type: PHC-J3YF-IRF, S/N: FP3061B, Time: cordance with FAR 43, Appendix D (BP). Complied with AD 08-11-18 issure test and inspection, no defects noted. Next due 2481.7 hobbs (BP). Inspection of NLG upper gusset plate and attach point arms, no defects of induction air filter p/n BA-24 with new (BP). Completed cabin fine odel A344, NO. G-42446855, Dated 2021, no defects noted (BP). Removed pecity check. Battery checked normal and passed at 88%. Top charged dright main tire with new, p/n 070-449-0, s/n 2063T00139 and tube p/n especked wheel bearings. Reinstalled wheel and tire assembly (BP). required (BP). Re-sealed right brake caliper and bled, replaced oring p/n sp/n 51698-001 blue and p/n 51698-003 yellow with new (BP). Replaced with (BP). Replaced left exhaust collector bolt p/n AN4C-32 with new (BP). fuselage fairing as required (BP). Tightened and secured rudder control rod upside down placard p/n 12437-007 with new (BP). Re-secured #2 battery med in accordance with approved/current technical data. I certify that this lance with an Annual inspection and a list of discrepancies and unainworthy provided for the aircraft owner or operator.  **Control of the aircraft owner or operator.**  Wisconsin Aviation - Watertown 1741 River Drive Watertown, WI 53094 920-261-4567

erations

umber of c entries.)

TACH

RECORDING

TODAY'S FLIGHT

TOTAL TIME IN Description of Inspections, Tests, Repairs and Alterations

Entries must be endorsed with Name Reting and Octave

N700ZG

YEAR

28

like/Model: Cirrus SR20

rial No: 1457

CONTINENTAL SERVICES

Date: 11/10/2022

Hobbs: 2387.8

setinental Services, 8600 County Road 32, Fairhope, AL 36532 251-990-5080 FAA Repair Station No. 9CER853B

work performed as described below has been inspected in accordance with current regulations of the Federal Aviation ministration and found to be in airworthy condition with respect to the work performed.

■ wrk Performed: THE ANNUAL INSPECTION DATED 8/12/2022 PERFORMED BY WISCONSIN AVIATION NDER SHOP ORDER MX22-0256 NOTED LIFTER CORROSION AND CAM SHAFT LOBE CORROSION EYOND SPECIFICATION UNDER DISCREPANCIES 44 AND 45 AS THE LIST OF UNAIRWORTHY ITEMS ROVIDED TO THE OWNER. ENGINE 10360ES6 SN 357840 WAS REMOVED, OVERHAULED BY CONTINENTAL SERVICES UNDER WORK ORDER ES-11079 AND REINSTALLED IN CIRRUS SR20 SN 1457 \$200ZG POST OVERHAUL WITH NEW ENGINE ISOLATOR MOUNTS/HARDWARE AND TORQUED TO SPECIFICATION. ENGINE WAS SERVICED WITH AEROSHELL 100 MINERAL OIL. CLEANED, SPECTED, REPAIRED ENGINE BAFFLES AS REQUIRED. OVERHAULED #2 ALTERNATOR PN BC410-1 SN 0887319K WAS INSTALLED 11/1/2021 AT HOBBS 2283.8 TIME IN SERVICE. UNIT CURRENTLY HAS 104 BOURS TIS. TRANSFERRED B&C ALTERNATOR TO ENGINE POST OVERHAUL. CLEANED, INSPECTED AND REINSTALLED EXHAUST SYSTEM WITH NEW GASKETS AND HARDWARE. REPLACED FIREWALL FORWARD HOSES AS REQUIRED. PERFORMED INITIAL GROUND BREAK IN, OPERATIONAL CHECKS ND LEAK CHECKS. THIS REPAIR SATIFIES THE NOTED UNAIRWORTHY NOTED ITEMS.---END---

\*\* thorized Signature for Repair Station 9CER853B:

Details of the work performed are on file under Work Order No. AC 11029

YEAR 20 Date	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Test Entries must be endorsed with Name, R Technician or Repair Facility. (See back	Rating and Certificate Number of
Reg: N7 Make/Mo Serial No	odel: Cirrus S	R20	C	ONTINENTAL SERVICES	Date: 11/18/2022 Hobbs: 2390.8
The work Administ	performed as ration and four	described nd to be in	below has airworthy c	been inspected in accordance with curren ondition with respect to the work performe U PN 29435-002 SN 13785 AND INSTAL	ed.