




POSTER PRESENTATION ON MINITAB USAGE









0.17

0.89

5.12

4.89

1.89

4.23

Strength

0.83931

1.12253

1.11309

1.10000

0.70705

0.49751

0.53000

0.52062

0.19287

0.54000

0.39086

0.42000

0.18348

0.24000

36.89

59.63


92.16


112.47

211.68


181.89

Cause and effect diagram






Histogram





Bubble Plot



Boxplot







Probability Plot

Contact

S.M.Foysal Haque Roll:201636010

Level: 03

Missing button

Misaligned fabric

Stitching errors

Hemming errors

21

23

112

43

Porosity

0.500150

0.410000

0.450000

0.550000

0.440000

0.240000

0.470000

0.700000

0.800000

0.220000

0.880000

0.720000

0.750000

0.700000

Loose thread

Fabric flaws

Hydrogen

0.180000

0.210000

0.210000

0.210000

0.220000

0.220000

0.230000

0.230000

0.240000

0.240000

0.250000

0.260000

0.270000

0.280000

Department of Industrial and Production Military Institute of Science and Technology