






### BANK13 is not exist in xc7a35T





















### MGTAVTT 4.7uF(1) 0.1uF(2)





## MGTAVCC 4.7uF(1) 0.1uF(2)















# SYSTEM CLOCK



# 3 am PLL CLS MHz 125MHz 125M

