

tenable Platform Products Solutions Why Tenable Resources Partners Support Company









Unauthenticated Command Injection in TP-Link Archer AX21 (AX1800)

High

← View More Research Advisories

Synopsis

Researchers at Tenable discovered an unauthenticated command injection in the web management interface of the TP-Link Archer AX21 (AX1800). This issue was also independently discovered by other research teams, as noted in ZDI-23-451.

Update 24 April 2023: As indicated in a blog released by the Zero Day Initiative, when combined with ZDI-23-452 / CVE-2023-27359 this bug can lead to unauthenticated command injection via the WAN interface.

Technical Details

The country parameter, of the write callback for the country form at the /cgibin/luci/;stok=/locale endpoint is vulnerable to a simple command injection vulnerability. The country parameter was used in a call to **popen()**, which executes as **root**, but only after first being set in an initial request.

That is to say, to exploit the issue, an attacker would first have to send the payload as part of the country parameter to set the value, and upon sending a second request (identical or not) to the country endpoint, the first payload would be executed as part of the **popen** command.

Proof of Concept:

Sending a request similar to the following twice in a row would run the \$(id>/tmp/out) command on the second request, creating the /tmp/out file containing the output of the id command.

POST /cgi-bin/luci/;stok=/locale?form=country HTTP/1.1

Host: <target router> Content-Type: application/x-www-form-urlencoded

Tracking Preferences

We use cookies and similar technologies on our websites and applications to help provide you with the best possible online experience. By selecting "Opt in" below, you agree that we may store and access cookies and similar technologies on your device. Read more in our privacy policy.

Opt in

Opt out

Build 20230219 which fixes the issue by

pad/archer-ax21/v3/#Firmware

s/ZDI-23-451/

s/ZDI-23-452/

3/4/21/tp-link-wan-side-vulnerability-cve-

Risk Information

CVE ID: CVE-2023-1389

Tenable Advisory ID: TRA-2023-11

Credit:

Jimi Sebree

Evan Grant

CVSSv3 Base / Temporal Score:

8.8 / 8.2

CVSSv3 Vector:

AV:A/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H

Affected Products:

TP-Link Archer AX21 (AX1800) < 1.1.4 Build 20230219

Risk Factor:

High

Advisory Timeline

14 March 2023 - Advisory Published 24 April 2023 - Updated with references to ZDI-23-451 & ZDI-23-452

eace openion to alcoloce to the followay managed after intringential

tenable Platform Products Solutions Why Tenable Resources Partners Support Company









22 January 2023 - Case closed by ZDI with no communication

23 January 2023 - Tenable seeks clarification on case being closed

1 February 2023 - ZDI informs Tenable that the case was closed as an unsuccessful attempt, and that Tenable could resubmit

2 February 2023 - Tenable notes that the case was submitted after the competition, as an unsuccessful attempt, asks for clarification on whether the case should be resubmitted

7 February 2023 - Tenable informs ZDI that the case will not be reopened

7 February 2023 - Tenable reports the issue to TP-Link

8 February 2023 - TP-Link acknowledges

22 February 2023 - Tenable requests an update

24 February 2023 - TP-Link sends a firmware version and asks if it fixes the issue

24 February 2023 - Tenable notes it does not fix the issue

14 March 2023 - TP-Link informs Tenable that version 1.1.4 Build 20230219 has been released and fixes the issue

14 March 2023 - Tenable confirms the fix

All information within TRA advisories is provided "as is", without warranty of any kind, including the implied warranties of merchantability and fitness for a particular purpose, and with no guarantee of completeness, accuracy, or timeliness. Individuals and organizations are responsible for assessing the impact of any actual or potential security vulnerability.

Tenable takes product security very seriously. If you believe you have found a vulnerability in one of our products, we ask that you please work with us to quickly resolve it in order to protect customers. Tenable believes in responding quickly to such reports, maintaining communication with researchers, and providing a solution in short order.

For more details on submitting vulnerability information, please see our Vulnerability Reporting Guidelines page.

If you have questions or corrections about this advisory, please email bughunters@tenable.com

tenable

Featured products

Tenable One Exposure Management Platform

Tenable Cloud Security

Tracking Preferences

We use cookies and similar technologies on our websites and applications to help provide you with the best possible online experience. By selecting "Opt in" below, you agree that we may store and access cookies and similar technologies on your device. Read more in our privacy policy.

Featured solutions

Active Directory

Building management

systems

security posture gement

liance

ure management

al manufacturing

ative Al

care

cloud security

Customer resources

Resource library

Community & support

Customer education

Tenable Research

Documentation

Nessus resource center

Cybersecurity guide

Why Tenable

Trust

System status

Connections

Blog

Contact us

Careers

Investors

Tenable Ventures

Events

Media



Tenable Platform Products Solutions Why Tenable Resources Partners Support Company









Vulnerability management

Zero trust

View all >

Privacy policy | Do not sell/share my personal information | Legal | 508 compliance

© 2024 Tenable®, Inc. All rights reserved

Tracking Preferences

We use cookies and similar technologies on our websites and applications to help provide you with the best possible online experience. By selecting "Opt in" below, you agree that we may store and access cookies and similar technologies on your device. Read more in our privacy policy.