

## Report (1/1/2026 12:00:00 AM - 1/29/2026 12:00:00 AM 24 / 7)

Probe, Group, Device	Sensor	Average Total	Uptime Downtime	Good Failed
Local Probe (Local Probe) »				
Serenity Spa Links »				
<b>Gigiri DD</b>	<b>LAN</b>	5.87 Mbit/s 1,658,801 MB	97.941 % 2.059 %	[27d 10h 03m 17s [13h 50m 00s] 97.924 % 2.076 % [39481] [837]
Local Probe (Local Probe) »				
Serenity Spa Links »				
<b>Gigiri DD</b>	<b>DD-Link</b>	2.42 Mbit/s 682,867 MB	97.941 % 2.059 %	[27d 10h 03m 22s [13h 50m 00s] 97.922 % 2.078 % [39480] [838]
Local Probe (Local Probe) »				
Serenity Spa Links »				
<b>Gigiri DD</b>	<b>Guest LAN</b>	0 Mbit/s 0 MB	97.941 % 2.059 %	[27d 10h 04m 22s [13h 50m 00s] 97.924 % 2.076 % [39482] [837]
Local Probe (Local Probe) »				
Serenity Spa Links »				
<b>Gigiri-JTL-197.232.140.107</b>	<b>LAN</b>	5.88 Mbit/s 1,657,791 MB	97.849 % 2.151 %	[27d 09h 25m 44s [14h 27m 00s] 97.825 % 2.175 % [39441] [877]
Local Probe (Local Probe) »				
Serenity Spa Links »				
<b>Gigiri-JTL-197.232.140.107</b>	<b>JTL-WAN</b>	1.92 Mbit/s 543,014 MB	97.849 % 2.151 %	[27d 09h 25m 39s [14h 27m 00s] 97.815 % 2.185 % [39437] [881]
Local Probe (Local Probe) »				
Serenity Spa Links »				
<b>Kitisuru - JTL</b>	<b>Cameras-LAN</b>	2.72 Mbit/s 784,506 MB	100 % 0 %	[27d 23h 53m 25s [00s] 99.975 % 0.025 % [40306] [10]
Local Probe (Local Probe) »				
Serenity Spa Links »				
<b>Kitisuru - JTL</b>	<b>JTL-WAN</b>	3.37 Mbit/s 970,408 MB	100 % 0 %	[27d 23h 53m 35s [00s] 99.975 % 0.025 % [40306] [10]
Local Probe (Local Probe) »				
Serenity Spa Links »				
<b>Kitisuru - JTL</b>	<b>(008) Port4 Traffic</b>	0.08 Mbit/s 23,188 MB	100 % 0 %	[27d 23h 54m 30s [00s] 99.975 % 0.025 % [40307] [10]
Local Probe (Local Probe) »				
Serenity Spa Links »				
<b>Kitisuru DD-197.254.29.114</b>	<b>Staff LAN</b>	3.12 Mbit/s 271,887 MB	30 % 70 %	[08d 08h 52m 48s [19d 15h 01m 00s] 30 % 70 % [12041] [28341]
Local Probe (Local Probe) »				
Serenity Spa Links »				
<b>Kitisuru DD-197.254.29.114</b>	<b>Cameras LAN</b>	< 0.01 Mbit/s 50 MB	30 % 70 %	[08d 08h 53m 53s [19d 15h 00m 00s] 30 % 70 % [12044] [28345]
Local Probe (Local Probe) »				
Serenity Spa Links »				
<b>Kitisuru DD-197.254.29.114</b>	<b>Availability</b>	62 msec	30 % 70 %	[08d 08h 53m 48s [19d 14h 59m 00s] 30 % 70 % [12052] [28327]
Local Probe (Local Probe) »				
Serenity Spa Links »				
<b>Kitisuru DD-197.254.29.114</b>	<b>DD</b>	3.15 Mbit/s 274,337 MB	30 % 70 %	[08d 08h 51m 43s [19d 15h 02m 00s] 30 % 70 % [12044] [28334]
Local Probe (Local Probe) »				
Serenity Spa Links »				
<b>41.215.60.10 JANI (Tigoni DD)</b>	<b>Ping</b>	72 msec	97.384 % 2.616 %	[27d 06h 20m 36s [17h 34m 30s] 97.365 % 2.635 % [78518] [2125]
Local Probe (Local Probe) »				
Serenity Spa Links »				
<b>41.215.60.10 JANI (Tigoni DD)</b>	<b>Tigoni_DD</b>	2.47 Mbit/s 692,075 MB	100 % 0 %	[27d 06h 08m 12s [00s] 99.982 % 0.018 % [39247] [7]
Local Probe (Local Probe) »				
Serenity Spa Links »				
<b>DD-SPA_KAREN</b>	<b>Ping</b>	67 msec	96.334 % 3.666 %	[26d 23h 16m 19s [01d 00h 38m 00s] 96.256 % 3.744 % [38821] [1510]
Local Probe (Local Probe) »				
Serenity Spa Links »				
<b>DD-SPA_KAREN</b>	<b>DD_WAN Port2</b>	0.83 Mbit/s 229,474 MB	96.325 % 3.675 %	[26d 23h 11m 52s [01d 00h 41m 32s] 96.225 % 3.775 % [38799] [1522]

Probe, Group, Device	Sensor	Average Total	Uptime Downtime	Good Failed
Local Probe (Local Probe) »				
Serenity Spa Links »				
DD-SPA_KAREN	LAN Port3	2.09 Mbit/s 579,825 MB	96.324 % 3.676 %	[26d 23h 12m 09s [01d 00h 42m 00s] 96.23 % 3.77 % [38801] [1520]
Local Probe (Local Probe) »				
Serenity Spa Links »				
DD-SPA_KAREN	CCTV Port8	< 0.01 Mbit/s 403 MB	96.326 % 3.674 %	[26d 23h 12m 14s [01d 00h 41m 00s] 96.225 % 3.775 % [38798] [1522]
Local Probe (Local Probe) »				
Serenity Spa Links »				
JTL-KAREN	Ping	64 msec	96.319 % 3.681 %	[26d 23h 10m 15s [01d 00h 44m 00s] 96.244 % 3.756 % [38816] [1515]
Local Probe (Local Probe) »				
Serenity Spa Links »				
JTL-KAREN	JTL Port7	1.26 Mbit/s 349,999 MB	96.311 % 3.689 %	[26d 23h 06m 21s [01d 00h 47m 00s] 96.235 % 3.765 % [38801] [1518]
Local Probe (Local Probe) »				
Serenity Spa Links »				
Spa_TIGONI_Airtel	Ping	75 msec	48 % 52 %	[13d 11h 31m 22s [14d 12h 23m 00s] 48 % 52 % [19402] [20971]
Local Probe (Local Probe) »				
Serenity Spa Links »				
Spa_TIGONI_Airtel	Airtel_WAN_PortF1	< 0.01 Mbit/s 217 MB	48 % 52 %	[13d 11h 28m 36s [14d 12h 24m 00s] 48 % 52 % [19392] [20977]
Local Probe (Local Probe) »				
Serenity Spa Links »				
Spa_TIGONI_JTL	JTL-Port6	1.71 Mbit/s 480,186 MB	97.537 % 2.463 %	[27d 07h 19m 56s [16h 33m 00s] 97.411 % 2.589 % [39274] [1044]

PAESSLER 20.2.59.1689+ 1/29/2026 2:28:36 PM