

HOME INSPECTION REPORT

Inspector: John Smith, License #CA-2019-12345

Property: 456 Crooked Lane, San Jose CA 95123

Date: June 18, 2026

ROOF: Composition shingle, approx 22 years. Curling observed on south side.
Recommend: Budget for replacement in 2-3 years (\$12,000-\$16,000)

FOUNDATION: Concrete perimeter. Hairline crack east wall, ~3ft. Monitor.
Recommend: Mark and monitor seasonally

PLUMBING: Main shutoff at front. Water heater gas 40gal, 9 years old.
Kitchen faucet drips. Washer replacement needed (\$100-\$150)

ELECTRICAL: 200 amp panel. Two outlets tested open ground in garage.
Recommend: Repair open grounds (\$150-\$250)

HVAC: Forced air gas furnace, approx 18 years. Filter dirty at time of inspection.
A/C condenser shows corrosion. Functional but aging.

EXTERIOR: Wood siding with peeling paint on north exposure.
Recommend: Scrape and repaint (\$2,000-\$3,500)

INTERIOR: Water stain on ceiling in master bedroom. Source undetermined.
Recommend: Investigate source - may be related to roof flashing