Window knuckle inter surface radius R100.80 has centre coordinate (190, 149) VIEW "B" VIEW "A" ∠24 OFF M8 CLEARANCE HOLES ON PCD 354, EQUI-SPACED. C-C ✓ 4 OFF M8 TAP THRU HOLES ON PCD 354, EQUI-SPACED.

NOTE:
Window crown inner surface radius R140 has centre coordinate (0,0)
Window crown outer surface radius R142.45 has centre coordinate (-2.27, 0)
Window knuckle outer surface radius R102.08 has centre coordinate (190, 150)