

OpenHandProject





MODEL: MS-F05M01


























Finger-Palm Assembly П [] П ц

Main Parts	Parts	the num of parts		Amount
	STL file	Ring	Index	
Index &	IR-Link1	1	1	2
Ring Fingers	IR-Link1Cover	1	1	2
	IR-Link2A	1	1	2
	IR-Link2B	1	1	2
	IR-LINK2Cover	1	1	2
	IR-LINk3	1	1	2
	R-Base	1	0	1
	I-Base	0	1	1
	STL file	Middle	Little	
Middle&	LF-Link1	0	1	1
Little Fngers	LF-Link1Cover	0	1	1
	MF-Link1	1	0	1
	MF-Link1Cover	1	0	1
	ML-Link2A	1	1	2
	ML-Link2B	1	1	2
	ML-LINK2Cover	1	1	2
	ML-LINk3	1	1	2
	M-Base	1	0	1
	L-Base	0	1	1
	STL file	Thumb		
Thumb	TH-Link1	1		1
	TH-Link1Cover	1		1
	TH-Link2	1		1
	TH-Link3	1		1
	T-Base	1		1

Gears

STL file	Thumb	Index	Middle	Ring	Little	Amount
26Servo	0	1	1	1	1	4
24Servo	1	0	0	0	0	1
18Servo	1	0	0	0	0	1
20F	0	1	1	1	1	4
20T	1	0	0	0	0	1
18T	1	0	0	0	0	1
16F	0	1	1	1	1	4
12FS	0	1	1	1	1	4
12TS	1	0	0	0	0	1
12F	0	0	2	0	0	2
10FS	0	1	1	1	1	4
10T	2	0	0	0	0	2
10F	0	2	0	2	2	6
08F	0	2	0	2	2	6

	STL file	the number of pars	Amount
	PalmA	1	1
Palm	PalmB	1	1
	PalmC	1	1

	STL file	the number of pars	Amount
	WristA	1	1
Wrist	WristB	1	1
	WristC	1	1