Pseudo Code for Lab 3_1

```
compiler directives
declare global variables
function prototypes
main function
   declare local variables
   initialize system, ports and PCA
   begin infinite loop
      calibrate motor speed
   end infinite loop
end main function
```

calibrate motor speed

```
declare local variables
wait for key stroke
if 'f', increase motor pw by 10
    if pw > max value, limit it to max value
else if 'r', decrease motor pw by 10
    if pw < min value, limit it to min value
else if another letter, give a reminder
update speed command
print motor pw
```

update speed command

update lo byte of CCModule 1 update hi byte of CCModule 1

Interrupt subroutine

```
If PCA interrupt flag is set

write lo byte of start_count in PCA0

write hi byte of start_count in PCA0

clear interrupt flag

else

handle other PCA interrupts
```