







USB Type-C power management



V_SYS to 3.3V BUCK converter



V_SYS to 5V BUCK converter



Sheet: /power/
File: power.kicad_sch


Title:

Size: A4
KiCad E.D.A. 10.0.0



Date:

Rev:
Id: 2/6

Battery power management



Battery monitoring



Sheet: /power/BMS/
File: bms.kicad_sch






Title:


Size: A4 Date:

KiCad E.D.A. 10.0.0

Rev:

Id: 3/6





Add a pull-up for THERMAL FLAG signal
CS goes from 0V to 3.3V (0A to 3A)


Sheet: /motor_right/
File: motors.kicad_sch

Title:

Size: A4 Date:

KiCad E.D.A. 10.0.0

Rev:
Id: 5/6



Sheet: /motor_left/
File: motors.kicad_sch

Title:

Size: A4

Date:

KiCad E.D.A. 10.0.0

Rev:

Id: 6/6