Release Notes for AT32 MCU Keil5 Package V2

V2.1.1-2022/04/02

- 1. ArteryTek. AT32F403A_407_DFP.2.0.8 Updated AT32F403A_407 firmware library
- 2. ArteryTek. AT32F435_437_DFP.2.0.8 Updated AT32F435_437 firmware library
- 3. ArteryTek. AT32F421_DFP.2.0.5 Updated AT32F421 firmware library
- 4. ArteryTek. AT32F413_DFP.2.0.4 Updated AT32F413 firmware library
- 5. ArteryTek. AT32F415_DFP.2.0.4 Updated AT32F415 firmware library
- ArteryTek. AT32F425_DFP.2.0.2 Updated AT32F425 firmware library
- 7. ArteryTek. AT32F403_DFP.2.0.1 Updated AT32F403 firmware library
- ArteryTek. AT32WB415_DFP.2.0.0 Updated AT32WB415 firmware library

V2.1.0-2022/03/11

ArteryTek.AT32F435_437_DFP.2.0.4
 Updated AT32F403A_407 firmware library

V2.0.9-2022/02/11

- ArteryTek.AT32F403A_407_DFP.2.0.7
 Updated AT32F403A_407 firmware library and svd file
- 2. ArteryTek.AT32F435_437_DFP.2.0.6
 Updated AT32F435_437 firmware library and svd file
- 3. ArteryTek.AT32F421_DFP.2.0.4 Updated AT32F421 firmware library
- ArteryTek.AT32F413_DFP.2.0.3
 Updated AT32F413 firmware library and svd file
- ArteryTek.AT32F415_DFP.2.0.3 Updated AT32F415 firmware library and svd file
- ArteryTek.AT32F425_DFP.2.0.1
 Updated AT32F425 firmware library and svd file, revised sram size

- 7. ArteryTek.AT32F403_DFP.2.0.0 Added AT32F403 pack
- 8. ArteryTek.AT32WB415_DFP.2.0.0 Added AT32WB415 pack

V2.0.8-2021/12/31

- ArteryTek.AT32F403A_407_DFP.2.0.6
 Updated AT32F403A_407 firmware library and svd file
- ArteryTek.AT32F435_437_DFP.2.0.5
 Updated AT32F435_437 firmware library and svd file
- ArteryTek.AT32F421_DFP.2.0.3 Updated AT32F421 firmware library
- 4. ArteryTek.AT32F413_DFP.2.0.2 Updated AT32F413 firmware library
- ArteryTek.AT32F415_DFP.2.0.2 Updated AT32F415 firmware library
- ArteryTek.AT32F425_DFP.2.0.0 Added AT32F425 pack

V2.0.7-2021/12/17

- ArteryTek.AT32F403A_407_DFP.2.0.5
 Updated AT32F403A_407 firmware library and svd file
- 2. ArteryTek.AT32F435_437_DFP.2.0.4 Updated AT32F435_437 firmware library and svd file
- ArteryTek.AT32F421_DFP.2.0.2 Updated AT32F421 firmware library and svd file
- 4. ArteryTek.AT32F413_DFP.2.0.1 Updated AT32F413 firmware library
- ArteryTek.AT32F415_DFP.2.0.1 Updated AT32F415 firmware library

V2.0.6-2021/11/26

- ArteryTek.AT32F403A_407_DFP.2.0.4 Updated AT32F403A_407 firmware library
- 2. ArteryTek.AT32F435_437_DFP.2.0.3 Updated AT32F435_437 firmware library
- ArteryTek.AT32F421_DFP.2.0.1Added the newest edition of AT32F421 pack
- 4. ArteryTek.AT32F413_DFP.2.0.0
 Added the newest edition of AT32F413 pack

5. ArteryTek.AT32F415_DFP.2.0.0
Added the newest edition of AT32F415 pack

V2.0.5-2021/11/15

- ArteryTek.AT32F403A_407_DFP.2.0.3
 Updated AT32F403A_407 firmware library and svd file
- 2. ArteryTek.AT32F435_437_DFP.2.0.2
 Updated AT32F435_437 firmware library and svd file
- ArteryTek.AT32F421_DFP.2.0.0Added the newest edition of AT32F421 pack

V2.0.4-2021/10/27

 ArteryTek.AT32F403A_407_DFP.2.0.2 Updated AT32F403A_407 firmware library

V2.0.3-2021/10/26

ArteryTek.AT32F435_437_DFP.2.0.1
 Updated AT32F435_437 svd file
 Updated AT32F435_437 firmware library

V2.0.2-2021/10/21

ArteryTek.AT32F403A_407_DFP.2.0.1
 Updated AT32F403A_407 svd file
 Updated AT32F403A_407 firmware library

V2.0.1-2021/09/30

1. ArteryTek.AT32F435_437_DFP.2.0.0
Added the newest edition of AT32F435_437 pack

V2.0.0-2021/07/01

ArteryTek.AT32F403A_407_DFP.2.0.0
 Added the newest edition of AT32F403A_407 pack