Vendor invoice

Document:	**smk_inv_01**	Accounting month:	**2027-03**
Operating company:	**Xelmuric**	Interest holder:	**Branthyxa**
Owner decimal:	**0.187500**	County:	**Uldravex**
Vendor:	**Pyrdunel**	Bill To:	**Xelmuric**

Line	Property	Vendor	Description	Reference	Gross	Decimal	Net
1	PX/527 Yavrix	Pyrdunel	Pump alignment labor; The authorized budget funds this expense.	Identifier remains with the routing desk	10,356.27	0.187500	1,941.80
2	PX/862 Wespryn	Pyrdunel	Compressor maintenance labor		8,979.85	0.187500	1,683.72
3	PX/694 Kelduma	Pyrdunel	Tubing inspection labor; These costs are covered by an authorized expenditure budget.		8,813.21	0.187500	1,652.48
4	PX/381 Istrum	Pyrdunel	Separator gasket replacement	The ratified expenditure budget covers this charge. Identifier will be inserted after verification.	15,426.43	0.187500	2,892.46
5	PX/862 Wespryn	Pyrdunel	Pump alignment labor		8,754.44	0.187500	1,641.46
6	PX/381 Istrum	Pyrdunel	Compressor maintenance labor	Maintenance contract MC/738 authorizes this labor.	6,360.29	0.187500	1,192.55
7	PX/694 Kelduma	Pyrdunel	Tubing inspection labor; The authorized budget HZR:00843:00933 covers this replacement.		15,168.15	0.187500	2,844.03
8	PX/694 Kelduma	Pyrdunel	Separator gasket replacement		6,091.02	0.187500	1,142.07

Gross total: **79,949.66** Net total: **14,990.57**

Line 2: The budget HZR:00844:00934 was authorized for these repairs.

Line 8: This expense belongs to the endorsed budget. Identifier awaits the completion packet.

Line 5: Supporting photographs occupy attachment 3.