Joint Interest Billing

Document:	**smk_jib_01**	Accounting month:	**2027-03**
Operating company:	**Xelmuric**	Interest holder:	**Branthyxa**
Owner decimal:	**0.187500**	County:	**Uldravex**

Line	Property	Vendor	Description	Reference	Gross	Decimal	Net
1	PX/381 Istrum	Pyrdunel	Tubing inspection labor	This charge falls within the authorized budget. Identifier will arrive after reconciliation.	2,425.04	0.187500	454.70
2	PX/694 Kelduma	Jomvexa	Separator gasket replacement		10,324.71	0.187500	1,935.88
3	PX/381 Istrum	Pyrdunel	Pump alignment labor; These repairs are covered by the authorized budget.	HZR:00841:00931	1,535.02	0.187500	287.82
4	PX/862 Wespryn	Jomvexa	Compressor maintenance labor; The sanctioned budget covers this charge.	Identifier awaits clerical entry	13,324.96	0.187500	2,498.43
5	PX/527 Yavrix	Pyrdunel	Tubing inspection labor		2,078.32	0.187500	389.68
6	PX/527 Yavrix	Jomvexa	Separator gasket replacement		4,766.67	0.187500	893.75
7	PX/694 Kelduma	Pyrdunel	Pump alignment labor; The authorized budget covers these repairs.	TBD	13,022.96	0.187500	2,441.80
8	PX/381 Istrum	Jomvexa	Compressor maintenance labor	The ratified budget includes this expense. Identifier remains queued for transcription.	1,402.01	0.187500	262.88

Gross total: **48,879.69** Net total: **9,164.94**

Line 5: Emergency response authorization permits this repair.

Line 6: This expense draws against the endorsed budget. Identifier will accompany the next attachment.

Line 2: Supporting photographs occupy attachment 1.