Joint Interest Billing

Document:	**sco_jib_09**
Billing period:	**2026-09**
Operator:	**Redwillow Mesa Operating LLC**
Owner:	**Alderfen Mineral Interests LLC**

Line	Property	Description	Reference	Vendor	Gross	Decimal	Net
1	PR6812	Sump liquid removal; Posting this expense against AFE RWM/58260/OC follows its signed spending release.		Brindleford Production Services LLC	4,068.40	0.187500	762.83
2	PR4937	Heater ignition servicing	AFE approved allocation: RWM/0058261/OC	Stoneharbor Pump Works LLC	5,477.77	0.187500	1,027.08
3	PR2689	Electrical panel servicing	Approved-product register photocopies	Brindleford Production Services LLC	3,037.81	0.187500	569.59
4	PR4937	Choke trim replacement	AFE approved allocation: RWM/58261/OC	Stoneharbor Pump Works LLC	1,261.66	0.187500	236.56
5	PR7524	Flowline insulation repair		Brindleford Production Services LLC	583.52	0.187500	109.41

Page totals Gross: 14,429.16 Net: 2,705.47

> Line 1: The mechanic photographed the removed component.

Joint Interest Billing

Document:	**sco_jib_09**
Billing period:	**2026-09**
Operator:	**Redwillow Mesa Operating LLC**
Owner:	**Alderfen Mineral Interests LLC**

Line	Property	Description	Reference	Vendor	Gross	Decimal	Net
6	PR7524	Compressor belt renewal	AFE consent recorded: RWM/58762/OC	Stoneharbor Pump Works LLC	5,875.11	0.187500	1,101.58
7	PR4937	Valve actuator adjustment	AFE spending release: R-W-M/58261/OC	Brindleford Production Services LLC	3,431.90	0.187500	643.48
8	PR6812	Casing vent inspection		Stoneharbor Pump Works LLC	5,951.45	0.187500	1,115.90
9	PR6812	Compressor belt renewal	AFE consent recorded: RWM/58262/OC	Brindleford Production Services LLC	4,467.63	0.187500	837.68

Page totals Gross: 19,726.09 Net: 3,698.64

Document totals Gross: 34,155.25 Net: 6,404.11