Joint Interest Billing

Document: **m1_jib_02**

Billing period: **2027-01**

Operator: **Cinderelm Operating LLC**

Owner: **Thistlewater Mineral Holdings LLC**

Row sequence	Lease designation	Ledger classification	Work narrative	AFE authorization docket	Supplier identity	Supplier billing serial	Work performed on	Measured units	Charge per unit	Full-interest charge	Participation fraction	Owner allocation
1	Sablebrook Ridge 2H	7318	Wellsite equipment inspection	CE08427~K	Mossquarry Well Services LLC	CP27119X	2027-01-08			250	0.18	45.0
2	Larkstone Hollow 5H	7425	Separator fitting repair		Rillhaven Equipment Repair LLC	CP27120X	2027-01-26			450	0.1	45.0
3	WQ814	7318	Access surface maintenance		Cairnford Mechanical Services LLC	CP27121X	2024-12-15			350	0.125	43.75
4	Foxmarsh Bnd. 8-H	7425	Valve packing replacement	CE08425~K	Mossquarry Well Services LLC	CP27122X	2027-01-11			600	0.16	96.0
5	Hawthorn Bench 9H	7318	Wellsite equipment inspection	AFE: identifier will arrive with the signed budget sheet.	Rillhaven Equipment Repair LLC	CP27123X	2027-01-12			240	0.2	48.0
6	WQ365	7425	Separator fitting repair	CE08421~K	Cairnford Mechanical Services LLC	CP27124X	2027-01-13			330	0.075	24.75
7	Sablebrook Ridge 2H	7318	Pump inspection labor		Cairnford Mechanical Services LLC	CP27125X	2027-01-14	3	125	375	0.18	67.5
8	Flintmere Draw 4H	7425	This work has approved budget authorization.		Rillhaven Equipment Repair LLC	CP27126X	2027-01-15			280	0.125	35.0

> Line 7: Three inspection hours recorded on the crew sheet.

Document total (gross): 2875 Document total (net): 405.00