Joint Interest Billing

Document: **m1_jib_03**

Billing period: **2027-01**

Operator: **Cinderelm Operating LLC**

Owner: **Thistlewater Mineral Holdings LLC**

Row sequence	Lease designation	Ledger classification	Work narrative	AFE authorization docket	Supplier identity	Supplier billing serial	Work performed on	Measured units	Charge per unit	Full-interest charge	Participation fraction	Owner allocation
1	Coppercedar Run 6H	7318	Separator fitting repair		Rillhaven Equipment Repair LLC	CP27102X	2027-01-10			400	0.075	30.0
2	WQ482	7425	Access surface maintenance		Cairnford Mechanical Services LLC	CP27139X	2027-01-09			500	0.22	110.0
3	Flintmere Draw 4H	7318	Valve packing replacement	CE 008421 ~ K	Mossquarry Well Services LLC	CP27140X	2027-01-10			410	0.125	51.25
4	Hawthorn Bench 9H	7425	Pump inspection labor		Mossquarry Well Services LLC	CP27141X	2027-01-11	5	100	500	0.2	100.0

Joint Interest Billing

Document: **m1_jib_03**

Billing period: **2027-01**

Operator: **Cinderelm Operating LLC**

Owner: **Thistlewater Mineral Holdings LLC**

Row sequence	Lease designation	Ledger classification	Work narrative	AFE authorization docket	Supplier identity	Supplier billing serial	Work performed on	Measured units	Charge per unit	Full-interest charge	Participation fraction	Owner allocation
5	WQ739	7318	Separator fitting repair	AFE CE08426~K approved for this maintenance work.	Cairnford Mechanical Services LLC	CP27142X	2027-01-12			320	0.1	32.0
6	COPPERCEDAR RUN 06H	7425	Access surface maintenance		Mossquarry Well Services LLC	CP27143X	2027-01-13			220	0.075	16.5
7	Sablebrook Ridge 2H	7318	Approved-vendor list fee		Rillhaven Equipment Repair LLC	CP27144X	2027-01-14			170	0.18	30.6
8	WQ927	7425	Wellsite equipment inspection	TBD	Cairnford Mechanical Services LLC	CP27145X	2027-01-15			190	0.2	38.0

> Line 6: Emergency authority invoked to isolate the leaking valve.

Document total (gross): 2710 Document total (net): 408.35