Joint Interest Billing

Document: **m4_jib_01**

Billing period: **2027-04**

Operator: **Cinderelm Operating LLC**

Owner: **Thistlewater Mineral Holdings LLC**

Producing location	Entry index	Performance day	Contractor identity	Payable document serial	Charge explanation	Expense category	Billed measure	Price per measure	Unallocated cost	Interest multiplier	Allocated cost	Budget clearance locator
Foxmarsh Bend 8H	1	2027-04-08	Mossquarry Well Services LLC	CP27176X	Valve packing replacement	7318			250	0.16	40.0	K::08425::CE
Flintmere Draw 4H	2	2027-04-09	Cairnford Mechanical Services LLC	CP27177X	Pump inspection labor	7425	2	140	280	0.14	39.2	
Coppercedar Run 6H	3	2027-01-10	Rillhaven Equipment Repair LLC	CP27102X	Separator fitting repair	7318			400	0.075	30.0	
Hawthorn Bench 9H	4	2027-04-11	Mossquarry Well Services LLC	CP27179X	Access surface maintenance	7425			340	0.2	68.0	

> Line 4: AFE K::08422::CE authorizes this inspection.

Joint Interest Billing

Document: **m4_jib_01**

Billing period: **2027-04**

Operator: **Cinderelm Operating LLC**

Owner: **Thistlewater Mineral Holdings LLC**

Producing location	Entry index	Performance day	Contractor identity	Payable document serial	Charge explanation	Expense category	Billed measure	Price per measure	Unallocated cost	Interest multiplier	Allocated cost	Budget clearance locator
Sablebrook Rdg #2-H	5	2027-04-12	Cairnford Mechanical Services LLC	CP27180X	Pump inspection labor	7318	3	150	450	0.18	81.0	
WQ739	6	2027-04-13	Cairnford Mechanical Services LLC	CP27181X	Wellsite equipment inspection	7425			390	0.1	39.0	
Flintmere Draw 4H	7	2027-04-14	Mossquarry Well Services LLC	CP27182X	Separator fitting repair	7318			180	0.14	25.2	AFE: allocation clerk will append the approval identifier.
Hawthorn Bench 9H	8	2027-04-15	Rillhaven Equipment Repair LLC	CP27183X	Access surface maintenance	7425			270	0.2	54.0	

Document total (gross): 2560 Document total (net): 376.4