



Garage One Subaru Workshop

2885 Winchester Blvd STE A
Campbell, CA 95008
BAR License #: 277681
EPA ID: CAL000412993
(408) 429-8688
campbell@garage1auto.com

Work Order #4540

Page 1 of 7
04-27-22
Frank Chen
2003 Subaru Impreza

Frank Chen

frankchen07@gmail.com
+1 925-989-6325

2003 Subaru Impreza

JF1GD29603G510470
Engine: 2.0L H4 (EJ205)
Turbocharged GAS FI
Plate: 6HIE656
Odometer In: 88353
Odometer Out: 88355

Advisor: Agnes Kerchner

Technician: Adrian
Dominguez

GRAND TOTAL: \$175.00

✓ PAID

SERVICES

1

Courtesy Inspection

SUBTOTAL: \$0.00

LABOR

Perform courtesy inspection
Adjust tire pressure to factory specifications

Labor: \$0.00
Parts: \$0.00
Fees: \$0.00
Sublet: \$0.00

2

Garage One License Plate Cover

SUBTOTAL: \$0.00

LABOR

Install Rear Garage One License Plate Cover

Labor: \$0.00
Parts: \$0.00
Fees: \$0.00
Sublet: \$0.00

PARTS

License Plate Cover

QTY

EACH

TOTAL

1.0

\$0.00

\$0.00

3

Suspension Inspection

SUBTOTAL: \$175.00

LABOR

Complete inspection of suspension system
Test drive vehicle
Advise on any customer concerns

Labor: \$175.00
Parts: \$0.00
Fees: \$0.00
Sublet: \$0.00

Terms of Service:

1. "YES, DO THIS WORK"

I hereby authorize the corresponding service, including sublet work, to be done along with the necessary materials.

2. "ADDITIONAL FASTENERS MAY BE FURNISHED AS NEEDED"

I authorize Garage One to replace any missing or damaged clips and bolts during this visit, up to an amount of \$20.

3. "I MAY REQUEST RETURN OF REPLACED PARTS"

I have the right to: (A) the return of my replaced parts unless they are required for core return. (B) know the prices, terms, and conditions of all warranties, if any. My old parts will be saved for inspection or return upon receipt of the vehicle only if requested at the time of estimate.

4. "YOU MAY DRIVE MY CAR ON PUBLIC ROADS"

Garage One Subaru Workshop staff may operate my vehicle for the purpose of testing, inspection, and delivery.

5. "NO PAYMENT, NO KEYS"

An express mechanic's lien is hereby acknowledged on my vehicle to secure the amount of

GRAND TOTAL: \$175.00

Total Labor: \$175.00
Total Parts: \$0.00
Total Fees: \$0.00
Total Sublets: \$0.00
Sales Tax: \$0.00

✓ PAID

04-27-2022 6:35 PM

Paid by Credit Card via Terminal: **\$175.00**

CHEN/FRANK 40xx-xxxx-xxxx-xx18

Transaction ID: "d4hZHBq27rLQh6zbA34"



Garage One Subaru Workshop

2885 Winchester Blvd STE A
Campbell, CA 95008
BAR License #: 277681
EPA ID: CAL000412993
(408) 429-8688
campbell@garage1auto.com

Work Order #4540

Page 2 of 7
04-27-22
Frank Chen
2003 Subaru Impreza

services thereto. The final invoice is to be paid in full before this vehicle is released. In the event it is necessary to retain an attorney to collect for the services and goods shown on this estimate, Garage One will be entitled to a reasonable attorney fee in addition to its court cost. Payments will be made using Visa, MasterCard, American Express, Discover, or Cash. No checks or money orders of any kind will be an accepted form of payment.

6. "ONLINE COMMUNICATION OK"

I welcome email from Garage One Subaru Workshop as a means of receiving copies of my estimate, work order, and invoice.

7. "I WILL NOT HOLD GARAGE ONE LIABLE FOR LOSSES"

Garage One will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident, or any other cause beyond our control.

8. "I WILL PROMPTLY PICK UP MY VEHICLE"

Vehicles not picked up within five (5) calendar days of completion will be charged \$50/day storage.

9. "PARTS MAY CAUSE DELAYS"

I will not hold Garage One liable for delays in shipments or unavailability of parts necessary to complete work on my vehicle.

10. "GARAGE ONE SUBARU WORKSHOP WARRANTY INFORMATION"

All parts and services listed on this repair order are guaranteed to be free of defects in materials and workmanship for 36 months or 36,000 miles, whichever occurs first from the date of this repair order, unless otherwise noted or void due to (but not limited to) one of the five (5) conditions listed as "WARRANTY LIMITATIONS" in terms 11 through 15 below. Any defects in materials or workmanship will be repaired, replaced, or resupplied at the discretion of Garage One. No returns or reimbursements will be given.

11. "WARRANTY LIMITATIONS - CUSTOMER SUPPLIED PARTS"

Garage One will not warranty parts or labor for any job with parts supplied by me. Garage one will not be held liable for any failures, damage, or poor performance due to the installation of customer supplied parts, regardless of the cause of failure, damage, or poor performance. If incorrect parts supplied by me cause my vehicle to remain immobile in Garage One's workspace, there will be a \$100/day storage fee for each day my vehicle renders this workspace unusable for the service of other vehicles. Alternatively, an additional hourly labor charge may be applied to assemble and later disassemble my vehicle in order to safely remove my vehicle from Garage One's workspace.

12. "WARRANTY LIMITATIONS - NEGLIGENCE"

Garage One will void all warranties for damages due to customer neglect. Neglect includes, but is not limited to, failure to properly and timely service vehicle to prevent premature wear or damage to components installed by Garage One, overheating engine or transmission, not using proper or required chemicals and fluids, etc.

13. "WARRANTY LIMITATIONS - MODIFICATIONS"

Any modification to any system or part, or the installation of aftermarket performance parts on my vehicle, performed either by Garage One or myself, before or after service work is performed by Garage One, will void Garage One's standard warranty. Modified systems and parts, or the use of high performance parts, that change the behavior or design of the vehicle from the vehicle's original factory specifications place added stresses to the vehicle and its systems, cause added noise and vibration, and cannot be considered as reliable or comfortable as original equipment.

14. "WARRANTY LIMITATIONS - MOTORSPORTS"

Use of my vehicle for high-performance motorsports including, but not limited to, track days, autocross, rally, and drag racing will void Garage One's warranty. Motorsports involve running vehicles at or beyond their extremities, severely shorten the life of the vehicles components, and require more than average maintenance and repair to keep the vehicle in a safe and reliable operating condition. Any upgraded components installed on a vehicle are cause to assume the use of vehicle for motorsports.



Garage One Subaru Workshop

2885 Winchester Blvd STE A
Campbell, CA 95008
BAR License #: 277681
EPA ID: CAL000412993
(408) 429-8688
campbell@garage1auto.com

Work Order #4540

Page 3 of 7
04-27-22
Frank Chen
2003 Subaru Impreza

15. "WARRANTY LIMITATIONS - SERVICES NOT PROVIDED BY GARAGE ONE"

Any failures or damages caused or found by another party while servicing my vehicle will void Garage One's warranty. Garage One will not be held responsible, and will not provide any reimbursements, for any diagnostics, repairs, towing, storage, rental fees, or any other services not arranged for or provided by Garage One.

16. "I WILL RETURN FOR ANY WARRANTY WORK"

In the event a warranty issue occurs, I will return to Garage One for repairs. Garage One will not reimburse repairs performed by another technician or repair facility. I will not hold Garage One liable for any additional costs outside of the original repairs.

17. "HERE'S MY SIGNATURE"

I endorse the attached digital image of my signature as equivalent to my written signature and as proof of my agreement to these seventeen (17) terms.

Authorization:

11:22am 04/19/22



Garage One Subaru Workshop

2885 Winchester Blvd STE A
Campbell, CA 95008
BAR License #: 277681
EPA ID: CAL000412993
(408) 429-8688
campbell@garage1auto.com

Work Order #4540

Page 4 of 7
04-27-22
Frank Chen
2003 Subaru Impreza

INSPECTION REPORT

Courtesy Inspection

- | | |
|-------------------------------------|---|
| ☒ | FLUID LEVEL AND CONDITION - Engine oil - Coolant - Brake fluid - Clutch fluid - Power steering fluid - Front differential fluid (if equipped with a dipstick) - Transmission fluid (if equipped with a dipstick) |
| ☒ | UNDER HOOD - Drive belt condition - Drive belt tension - Upper radiator hose |
| ☒ | EXTERIOR LIGHTING - FRONT - Low beams - High beams - Fog lights - Clearance lights - Side markers - Turn signals |
| ☒ | EXTERIOR LIGHTING - REAR - Tail lights - Brake lights - Reverse lights - Side markers - Turn signals - License plate lights |
| ☒ | TIRES - Tire tread condition - Record tire tread depth |
| ☒ | TOP OFF FLUIDS - Engine oil - Coolant - Brake fluid - Clutch fluid - Power steering fluid - Washer fluid |



Garage One Subaru Workshop

2885 Winchester Blvd STE A
Campbell, CA 95008
BAR License #: 277681
EPA ID: CAL000412993
(408) 429-8688
campbell@garage1auto.com

Work Order #4540

Page 5 of 7
04-27-22
Frank Chen
2003 Subaru Impreza

NOTES

PLEASE CHECK AND ADVISE:

- Customer bought the WRX with 50k miles 3 years ago, and I'm about to hit 90k. 15k ago, I did an alignment check and the camber for the right rear wheel was positive, while the other three were negative. I didn't get into an accident, so I'm afraid something down there might be bent. It hasn't affected drivability though. The only work on the suspension so far were new tires and new struts around the time that ownership was transferred to me, along with 2-3 tire alignments and rotations.

As the car approaches the 100k mark, I'd also like to get ahead of what suspension components might need replacing to improve longevity.

Written by Agnes Kerchner | Garage One Subaru Workshop at 04/19/2022 03:46 PM

COURTESY INSPECTION:

- Front left clearance light is out.
- Both fog lights are inoperative.
- Aged radiator.
- Radiator hoses are deteriorating.
- Power steering fluid is getting dark.
- Tire pressure adjusted to 33 psi front, 32 psi rear
- Tire tread depth is 5/32" in front, 4/32" in rear

Written by Adrian Dominguez | Garage One Subaru Workshop at 04/28/2022 12:59 AM

SUSPENSION DIAGNOSTIC:

- Front strut top hats are installed incorrectly. They are installed in the wrong direction.
- Front sway bar end link boots are torn.
- Rear sway bar end links are cracking.
- Did not see anything bent with the visual inspection.
- Recommend to fix top hats and have alignment done again to see where issue can be.

Written by Adrian Dominguez | Garage One Subaru Workshop at 04/28/2022 01:13 AM

- Axle boots are leaking. Left inner and right inner.

Written by Adrian Dominguez | Garage One Subaru Workshop at 04/28/2022 01:13 AM



762B3262-5791-473A-
8B67-31BBE852431E.jpeg



BBC7628A-B5A7-4CDD-
83C7-D15F5190908B.jpeg



E6DE57D2-B42C-4403-
B7F3-9541F99952B7.jpeg



6791E332-69BC-4DD3-
8906-9898FE3BF03C.jpeg



Garage One Subaru Workshop

2885 Winchester Blvd STE A
Campbell, CA 95008
BAR License #: 277681
EPA ID: CAL000412993
(408) 429-8688
campbell@garage1auto.com

Work Order #4540

Page 6 of 7
04-27-22
Frank Chen
2003 Subaru Impreza

Written by Adrian Dominguez | Garage One Subaru Workshop at 04/28/2022 01:21 AM

Attached Images:





Garage One Subaru Workshop

2885 Winchester Blvd STE A
Campbell, CA 95008
BAR License #: 277681
EPA ID: CAL000412993
(408) 429-8688
campbell@garage1auto.com

Work Order #4540

Page 7 of 7
04-27-22
Frank Chen
2003 Subaru Impreza

