

DENABABA ENGINEERING CONSULTANT, LLC


Majority of the items mentioned above has commenced but not completed. It is my understanding that Mr. Matiella has stopped the remediation activities-as detailed by Mr. Guner. I have no recurring interactions, so I can only go by the information given to me.

The monitoring device was installed in September 2020 and I checked the markings on the wall on the day of the meeting held May 7th 2021. I have no indication of any displacement of the walls at 770 Princeton Place, NW based on the verification conducted.

The monitoring can be conducted for two more months to ensure that there is no displacement of Mr. Matiella's building. The other items not completed shall be completed upon receiving authorization to do so from Mr. Matiella.

If you should have any questions regarding the content of this report, please feel free to contact me.

Sincerely,



Dennis A Anibaba Jr
Dennis Anibaba Jr
5/14/2021
Denababa Engineering Consultant, LLC

CC:

Mr. Fatih Guner
Murdock Street, LLC
3619 Georgia Avenue, NW
Washington, DC 20018