

- ZZ1 These assemblies are ESD sensitive, ESD precautions shall be observed.
- ZZ2 These assemblies must be clean and free from flux and all contaminants. Use of no clean flux is not acceptable.
- ZZ3 ■These assemblies must comply with workmanship standards IPC-A-610 Class 2, unless otherwise specified.



## COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED. ASSEMBLY VARIANT: 001

PCB VIEWED FROM TOP SIDE	BOARD #: BMS029	REV: B	SUN REV:	Not In VersionControl	
	TID #: N/A				
PLOT NAME = Top Assembly Drawing	GENERATED : 6/30/2	2020 3: 07: 24	PM	TEXAS INSTRUMENTS	



## COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED. ASSEMBLY VARIANT: 001

PCB VIEWED FROM BOTTOM SIDE	BOARD #: BMS029	REV: B	SUN REU	: Not In VersionControl	
	TID #: N/A				
PLOT NAME = Bottom Assembly Drawing	GENERATED : 6/30/2	2020 3: 07: 24	PM	TEXAS INSTRUMENTS	