States

```
Pulse OFF = 0                          -> først
                                          timer = min_off
    (1 and counter) = 0 then
        PDM_out = 1 then
            counter += 1
    (Ikke mea_req)
    timer = 0 then
        counter >= min_on then
            pulse = 1
Pulse ON = 1                           -> først
  (mea_req = 0)                           timer = max_on
    counter > 0 then
        PDM_out = 0 then
            counter -= 1
    timer = 0 then
        pulse = 0
    counter = 0 then
        pulse = 0
MEASURE
  (mea_req = 1)
    wait until current pulse finish its duration then (timer = 0)
        assert mea_ack = 1 until mea_req = 0
    mea_req = 0 then
        mea_ack = 0
        go back to pulse OFF
```

Default:

timer <= timer-1

- når pilen går utenfor stiplet linje så teller timer -1 pga. default
- Antar at den ikke kan gå inn i measurment med mindre pulse er low