





Circular Pattern
Duplicates selected sketch geometry and arranges it in an arc or circular pattern.
Select the geometry to pattern and select a point or vertex to serve as the axis. Specify the number of copies and the angle in which they fit.
Press F1 for more help








Trim (d)
Trims a curve to the nearest intersecting curves or selected boundary geometry.
Route the cursor over the curve to preview the trim. Click to accept. Creates a coincident constraint between the endpoint of the trimmed curve and the boundary curves.
Press F1 for more help



Work Plane (p)
Creates a construction plane that is attached parametrically to other objects.
Create a work plane to sketch on when no planar face exists. Use work planes to apply planar assembly constraints on or sort when no planar face exists such as the middle of a part.
Press F1 for more help



Fillet
Places an arc of a specified radius at a corner or intersection of two lines.
Select the first line and then the second. Or, pause the cursor over the intersection and click when you see the fillet previewed. All fillets you create as you execute the command share the radius dimension parameter.
Press F1 for more help












Circular Pattern (Ctrl+Shift+P)
Creates duplicate features, solids, or bodies and arranges them in an arc or circular pattern.
You can specify the number and interval of the features or solids to be patterns. You can suppress individual occurrences, except for the original.
Press F1 for more help









Offset from Plane
Creates a work plane parallel to a selected face on planes at a specified offset distance.
Press F1 for more help



Circular Pattern (Ctrl+Shift+P)
Creates duplicate features, solids, or bodies and arranges them in an arc or circular pattern.
You can specify the number and interval of the features or solids to be patterns. You can suppress individual occurrences, except for the original.
Press F1 for more help
















Revolution
Sketch9
Input Geometry
Profiles
2 Profiles
Axis
1 Axis
Behavior
Direction
Angle A
360.00 deg
Output
Boolean
Solids
20 Solids
Advanced Properties
OK
Cancel

